



Aviation Investigation Final Report

Location: GILLETTE, Wyoming Accident Number: SEA92LA138

Date & Time: June 27, 1992, 07:48 Local Registration: N2550T

Aircraft: NAVION H Aircraft Damage: Substantial

Defining Event: 1 Minor, 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

IMMEDIATELY AFTER TAKEOFF, AT ABOUT 100 FT AGL, THERE WAS AN ABRUPT LOSS OF POWER. THE PILOT LOWERED THE LANDING GEAR & EXECUTED A FORCED LANDING STRAIGHT AHEAD. THE GEAR DID NOT FULLY EXTEND, AND RETRACTED AT TOUCHDOWN. POST CRASH EXAMINATION REVEALED THAT THE INDUCTION AIR 'SCAT' TUBE INNER WALL HAD COLLAPSED AT A 90 DEG BEND, RESTRICTING INTAKE AIR TO THE ENGINE. THE TUBING WAS INSTALLED AS PER A ONE TIME FIELD APPROVED STC. THE ALTERNATE AIR BYPASS WAS DOWNSTREAM OF THE 'SCAT' TUBING. THE TUBING WAS OF A DOUBLE WALL DESIGN WHICH CHARACTERISTICALLY CAN DELAMINATE WHEN EXPOSED TO HIGH HEAT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: AN ENGINE POWER LOSS DUE TO THE COLLAPSE OF THE INDUCTION AIR DUCTING, INADEQUATE MAINTENANCE, AND IMPROPER APPROVAL OF THE MODIFICATION.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - MECH FAILURE/MALF

Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (C) INDUCTION AIR DUCTING - COLLAPSED

2. (C) MAINTENANCE, MODIFICATION - IMPROPER - OTHER MAINTENANCE PERSONNEL

3. (C) ACFT/EQUIP, INADEQUATE COMPLIANCE DETERMINATION - FAA(PRINCIPAL MAINTENANCE INSPECTOR)

Occurrence #2: FORCED LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Occurrence #3: GEAR NOT EXTENDED

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Page 2 of 5 SEA92LA138

Factual Information

Pilot Information

| Certificate: | Commercial | Age: | 67,Male |
|---------------------------|---|-----------------------------------|----------------|
| Airplane Rating(s): | Single-engine land; Multi-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | | Restraint Used: | |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 2 Valid Medicalw/ waivers/lim | Last FAA Medical Exam: | April 11, 1991 |
| Occupational Pilot: | UNK | Last Flight Review or Equivalent: | |
| Flight Time: | 4246 hours (Total, all aircraft), 3808 hours (Total, this make and model) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | NAVION | Registration: | N2550T |
|-------------------------------|--|-----------------------------------|-----------------|
| Model/Series: | нн | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Utility | Serial Number: | NAV-4-2550 |
| Landing Gear Type: | Retractable - Tricycle | Seats: | 4 |
| Date/Type of Last Inspection: | April 21, 1992 Annual | Certified Max Gross Wt.: | 3315 lbs |
| Time Since Last Inspection: | 26 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 1649 Hrs | Engine Manufacturer: | CONTINENTAL |
| ELT: | Installed, activated, did not aid in locating accident | Engine Model/Series: | TSIO-520-13A |
| Registered Owner: | ECKERT, EDWIN J. | Rated Power: | 285 Horsepower |
| Operator: | ECKERT, EDWIN J. | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |
| | | | |

Page 3 of 5 SEA92LA138

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|--------------------------------------|------------------|
| Observation Facility, Elevation: | GCC ,4363 ft msl | Distance from Accident Site: | 1 Nautical Miles |
| Observation Time: | 06:48 Local | Direction from Accident Site: | 160° |
| Lowest Cloud Condition: | Clear | Visibility | 20 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 1 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 80° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 29 inches Hg | Temperature/Dew Point: | 13°C / 10°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | | Type of Flight Plan Filed: | None |
| Destination: | HELENA , MT (HLN) | Type of Clearance: | Traffic advisory |
| Departure Time: | 07:48 Local | Type of Airspace: | Class D |

Airport Information

| Airport: | CAMPBELL COUNTY GCC | Runway Surface Type: | |
|----------------------|---------------------|----------------------------------|----------------|
| Airport Elevation: | | Runway Surface Condition: | |
| Runway Used: | 0 | IFR Approach: | None |
| Runway Length/Width: | | VFR Approach/Landing: | Forced landing |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|------------------------|-----------------|-------------------------|---------------------------|
| Passenger Injuries: | 1 Minor, 1 None | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 Minor, 2 None | Latitude, Longitude: | 44.46075,-105.700172(est) |

Page 4 of 5 SEA92LA138

Administrative Information

Investigator In Charge (IIC): Mccreary, Steven

Additional Participating Persons: ROBERT SPEICHER; HELENA , MT

Original Publish Date: October 15, 1993

Last Revision Date: Investigation Class: Class

Note: https://data.ntsb.gov/Docket?ProjectID=42843

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 SEA92LA138