



# **Aviation Investigation Final Report**

Location: MOAB, Utah Accident Number: SEA92LA217

Date & Time: September 25, 1992, 15:40 Local Registration: N2553N

Aircraft: CESSNA 140 Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

THE PILOT TOOK OFF ON A VFR X-COUNTRY FLT WITH ONE USEABLE FUEL TANK AND CALCULATED HE HAD ENOUGH FUEL TO REACH THE DESTINATION WITH RESERVE FUEL. HE MADE AN APPROACH TO LAND AT THE DESTINATION, DECIDED TO GO-AROUND, AND THE ENGINE LOST POWER DURING THE TURN TO CROSSWIND. THE PILOT INITIATED A FORCED LANDING IN A FIELD. THE ACFT IMPACTED A DITCH DURING LANDING ROLL AND NOSED OVER. EXAMINATION OF THE ACFT AFTER THE ACCIDENT REVEALED THERE WAS NO USABLE FUEL IN THE TANKS.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE LOSS OF ENGINE POWER DUE TO FUEL EXHAUSTION RESULTING FROM INACCURATE FUEL CONSUMPTION CALCULATIONS BY THE PILOT. A FACTOR RELATING TO THE ACCIDENT WAS THE TERRAIN CONDITION (DITCH) IN THE LANDING AREA.

#### **Findings**

Occurrence #1: LOSS OF ENGINE POWER

Phase of Operation: APPROACH - VFR PATTERN - DOWNWIND

**Findings** 

1. (C) FLUID, FUEL - EXHAUSTION

2. (C) FUEL CONSUMPTION CALCULATIONS - INACCURATE - PILOT IN COMMAND

-----

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

-----

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

#### Findings

3. (F) TERRAIN CONDITION - DITCH

Page 2 of 6 SEA92LA217

### **Factual Information**

#### **Pilot Information**

Certificate:	Private	Age:	32,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	November 16, 1990
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	219 hours (Total, all aircraft), 137 hours (Total, this make and model), 196 hours (Pilot In Command, all aircraft), 10 hours (Last 90 days, all aircraft), 9 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Page 3 of 6 SEA92LA217

### **Aircraft and Owner/Operator Information**

Aircraft Make:	CESSNA	Registration:	N2553N
Model/Series:	140 140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	12809
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	November 6, 1991 Annual	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	69 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3052 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	C-85-12F
Registered Owner:	HERING, KARL H.	Rated Power:	85 Horsepower
Operator:	HERING, KARL H.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	GJT ,4858 ft msl	Distance from Accident Site:	60 Nautical Miles
Observation Time:	15:50 Local	Direction from Accident Site:	55°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	90 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	310°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	21°C / -9°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ition	
Departure Point:	ESCALANTE , UT (1L7)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	13:58 Local	Type of Airspace:	Class G

Page 4 of 6 SEA92LA217

## **Airport Information**

Airport:	CANYONLANDS CNY	Runway Surface Type:	
Airport Elevation:	4553 ft msl	<b>Runway Surface Condition:</b>	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	Forced landing;Go around;Traffic pattern

### Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	38.530006,-109.550155(est)

Page 5 of 6 SEA92LA217

#### **Administrative Information**

Investigator In Charge (IIC):	Mangum, Prentiss	
Additional Participating Persons:	DICK KLARMAN; SALT LAKE CITY, UT	
Original Publish Date:	August 31, 1993	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=42912	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 SEA92LA217