



Aviation Investigation Final Report

Location: OCEAN ISLE BCH, North Carolina Accident Number: ATL98LA104

Date & Time: August 6, 1998, 11:00 Local Registration: N4103F

Aircraft: Cessna 172 Aircraft Damage: Substantial

Defining Event: 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot returned to the departure airport for a full stop landing. As she turned final for the landing, she realized that another airplane was behind her in the traffic pattern. At this point she elected to maintain a higher than normal airspeed and altitude on final. The pilot reported that the airplane touched down about 2000 feet down the 4000 foot long runway. The airplane rolled off the departure end of the runway, crossed a two lane road, and collided with a ditch. The pilot also recalled that there was a slight cross wind during the landing, and as she applied brakes to stop the airplane, the brakes appeared to have been ineffective in slowing the airplane. No mechanical problems with the airplane were reported by the pilot.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate inflight planning that resulted in excessive airspeed and altitude for a full stop landing.

Findings

Occurrence #1: OVERRUN
Phase of Operation: LANDING

Findings

1. (C) IN-FLIGHT PLANNING/DECISION - INADEQUATE - PILOT IN COMMAND

2. (C) AIRSPEED - EXCESSIVE - PILOT IN COMMAND

3. (C) ALTITUDE - EXCESSIVE - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Findings
4. TERRAIN CONDITION - DITCH

Page 2 of 6 ATL98LA104

Factual Information

On August 6, 1998, at 1100 eastern daylight time, a Cessna 172, N4103F, collided with a ditch, according to the pilot, on the departure end of runway 06 at the Ocean Isle Beach airport in Ocean Isle Beach, North Carolina. The personal flight operated under the provisions of Title 14 CFR Part 91 with no flight plan filed. A review of weather data from the nearest reporting facility disclosed that visual weather conditions prevailed at the time of the accident. An examination of the airplane at the accident site disclosed that the airframe received substantial damage. The private pilot received minor injuries. The airplane departed Ocean Isle The pilot reported that she had completed a routine Beach, North Carolina, at 1030. pleasure flight and had returned to Ocean Isle Beach for a full stop landing. As she turned final for the landing, she realized that another airplane was behind her in the traffic pattern. At this point she elected to maintain a higher than normal airspeed and altitude on final. The pilot reported that the airplane touched down about 2000 feet down the 4000 foot long runway. The airplane rolled off the departure end of the runway, crossed a two lane road, and collided with a ditch. The pilot also recalled that there was a slight cross wind during the landing, and as she applied brakes to stop the airplane, the brakes appeared to have been ineffective in slowing the airplane.

No mechanical problems with the airplane were reported by the pilot.

Pilot Information

Certificate:	Private	Age:	77,Female
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	May 31, 1997
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	750 hours (Total, all aircraft), 750 hours (Total, this make and model), 3 hours (Last 90 days, all aircraft)		

Page 3 of 6 ATL98LA104

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N4103F
Model/Series:	172 172	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	46003
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	January 15, 1998 Annual	Certified Max Gross Wt.:	2200 lbs
Time Since Last Inspection:	50 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3900 Hrs	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	O-300-A
Registered Owner:	JEANNE T. STACKHOUSE	Rated Power:	145 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

- Increase of the second secon	on and ingite ian		
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	ILM ,32 ft msl	Distance from Accident Site:	50 Nautical Miles
Observation Time:	10:53 Local	Direction from Accident Site:	360°
Lowest Cloud Condition:	Unknown	Visibility	10 miles
Lowest Ceiling:	Overcast / 1200 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	7 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	26°C / 21°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	(6J0)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	10:30 Local	Type of Airspace:	Class G

Page 4 of 6 ATL98LA104

Airport Information

Airport:	OCEAN ISLE AIRPORT 6S5	Runway Surface Type:	Asphalt
Airport Elevation:	32 ft msl	Runway Surface Condition:	Dry
Runway Used:	6	IFR Approach:	None
Runway Length/Width:	4000 ft / 75 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	33.930122,-78.469596(est)

Page 5 of 6 ATL98LA104

Administrative Information

Investigator In Charge (IIC):	Powell, Phillip	
Additional Participating Persons:	JOE SAPP; WINSTON SALEM , NC	
Original Publish Date:	February 15, 2001	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=43626	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ATL98LA104