



Aviation Investigation Final Report

Location: PLAINVIEW, Minnesota Accident Number: CHI98LA291

Date & Time: July 30, 1998, 16:30 Local Registration: N90529

Aircraft: Bell 47G-2 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 137: Agricultural

Analysis

The pilot reported he was in a 'hard right hand ag turn' when the engine lost power. The helicopter impacted the terrain hard during the resulting landing. Inspection of the helicopter revealed it was low on fuel at the time of the accident.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's not achieving the proper descent rate prior to touchdown. A factor related to the accident was fuel starvation due to a low fuel level.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: MANEUVERING - AERIAL APPLICATION

Findings

1. (F) FLUID, FUEL - LOW LEVEL
2. (F) FLUID, FUEL - STARVATION

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY LANDING

Occurrence #3: HARD LANDING

Phase of Operation: EMERGENCY LANDING

Findings
3. PROPER DESCENT RATE - NOT OBTAINED - PILOT IN COMMAND

Page 2 of 6 CHI98LA291

Factual Information

On July 30, 1998, at 1630 central daylight time, a Bell 47G-2, N90529, sustained substantial damage when it impacted the terrain following a loss of engine power while maneuvering near Plainview, Minnesota. Visual meteorological conditions prevailed at the time of the accident. The pilot reported no injures. The 14 CFR Part 137 aerial application flight was not operating on a flight plan. The local flight departed from a field near Plainview, Minnesota.

The pilot reported he was in a "hard right hand ag turn" when the engine lost power. The helicopter impacted the terrain hard during the resulting landing.

Post accident inspection of the helicopter by inspectors from the Federal Aviation Administration Minneapolis, Minnesota, Flight Standards District Office revealed the helicopter was low on fuel.

Pilot Information

Certificate:	Commercial	Age:	29,Male
Airplane Rating(s):	None	Seat Occupied:	Center
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Helicopter	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	March 1, 1998
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1215 hours (Total, all aircraft), 250 hours (Total, this make and model), 1100 hours (Pilot In Command, all aircraft)		

Page 3 of 6 CHI98LA291

Aircraft and Owner/Operator Information

Aircraft Make:	Bell	Registration:	N90529
Model/Series:	47G-2 47G-2	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	NT1958-1
Landing Gear Type:	Skid	Seats:	1
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	2850 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	VO-435
Registered Owner:	NORTHLAND HELICOPTERS, INC.	Rated Power:	
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:	SCOTT'S HELICOPTER SERVICES	Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	RST ,1317 ft msl	Distance from Accident Site:	22 Nautical Miles
Observation Time:	16:54 Local	Direction from Accident Site:	225°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	6 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	20°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	22°C / 11°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Page 4 of 6 CHI98LA291

Airport Information

Airport:		Runway Surface Type:
Airport Elevation:		Runway Surface Condition:
Runway Used:	0	IFR Approach:
Runway Length/Width:		VFR Approach/Landing:

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	44.160324,-92.159088(est)

Page 5 of 6 CHI98LA291

Administrative Information

Investigator In Charge (IIC):	Carlson, Todd	
Additional Participating Persons:	ROLLAND SCHNEIDER; MINNEAPOLIS , MN	
Original Publish Date:	January 28, 2000	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=43630	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CHI98LA291