



Aviation Investigation Final Report

Location: PARIS, Tennessee Accident Number: ATL98LA114

Date & Time: August 15, 1998, 10:25 Local Registration: N9721D

Aircraft: Piper PA-22-150 Aircraft Damage: Substantial

Defining Event: 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot established an approach for runway 27. According to the pilot, 'it seemed that I was too high, so I dropped the flaps. My descent was uncontrolled and I hit the strip very hard'. The nose gear and the left main landing gear collapsed after the airplane touched down about 400 feet from the approach end of the sod runway. There were no known mechanical problems with the airplane

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's improper landing flare that resulted in an overload failure of the left main landing gear.

Findings

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) FLARE - IMPROPER - PILOT IN COMMAND

Occurrence #2: GEAR COLLAPSED

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings
2. LANDING GEAR, MAIN GEAR - OVERLOAD

Page 2 of 6 ATL98LA114

Factual Information

On August 15,1998, at 1025 central daylight time, a Piper PA-22-150, N9721D, collided with the ground and collapsed the landing gear, at a private airstrip near Paris, Tennessee. The personal flight operated under the provisions of Title 14 CFR Part 91 with no flight plan filed. Weather data from the nearest reporting facility revealed that visual weather conditions prevailed at the time of the accident. The private pilot received minor injuries. Examination of the airplane at the accident site disclosed that the airframe had sustained substantial damage. According to the pilot, the flight departed Camden, Tennessee, at 1000.

The pilot stated that he had conducted a visual over flight of the airport to determine the direction of the landing runway and general airstrip condition. The pilot established an approach for runway 27. According to the pilot, "it seemed that I was too high, so I dropped the flaps. My descent was uncontrolled and I hit the strip very hard". The nose gear and the left main landing gear collapsed after the airplane touched down about 400 feet from the approach end of the sod runway.

The pilot stated that there were no known mechanical problems with the airplane.

Pilot Information

Certificate:	Private	Age:	72,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	April 5, 1998
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	246 hours (Total, all aircraft), 237 hours (Total, this make and model), 236 hours (Pilot In Command, all aircraft)		

Page 3 of 6 ATL98LA114

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N9721D
Model/Series:	PA-22-150 PA-22-150	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	226638
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	March 12, 1998 Annual	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:	6 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2586 Hrs	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	O-320-A2B
Registered Owner:	LAWRENCE G. ATKINS	Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dawn
Observation Facility, Elevation:	MLK ,434 ft msl	Distance from Accident Site:	50 Nautical Miles
Observation Time:	10:55 Local	Direction from Accident Site:	35°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	20°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	29°C / 20°C
Precipitation and Obscuration:	No Obscuration; No Precipi	tation	
Departure Point:	CAMDEN , TN (0M4)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	10:00 Local	Type of Airspace:	Class G

Page 4 of 6 ATL98LA114

Airport Information

Airport:	PRIVATE AIRSTRIP	Runway Surface Type:	Grass/turf
Airport Elevation:	500 ft msl	Runway Surface Condition:	Dry
Runway Used:	9	IFR Approach:	None
Runway Length/Width:	3000 ft / 500 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	36.300273,-88.299331(est)

Page 5 of 6 ATL98LA114

Administrative Information

Investigator In Charge (IIC):	Powell, Phillip	
Additional Participating Persons:	PATRICIA K MATHES; MEMPHIS , TN	
Original Publish Date:	February 15, 2001	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=43649	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ATL98LA114