



# Aviation Investigation Final Report

<b>Location:</b>	DIXON, California	<b>Accident Number:</b>	LAX98LA280
<b>Date &amp; Time:</b>	September 2, 1998, 06:30 Local	<b>Registration:</b>	N202AW
<b>Aircraft:</b>	Cessna 188B	<b>Aircraft Damage:</b>	Destroyed
<b>Defining Event:</b>		<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 137: Agricultural		

## Analysis

The agricultural airplane had flown the day before the accident flight with no discrepancies noted. This was the first flight of the day and the airplane was carrying a full load of sulfur for an application flight. After takeoff, the pilot made a turn to the left and experienced a partial loss of engine power. The pilot made a bank to the right to land in an open field. The airplane landed hard and bounced into the air. After the first bounce, the airplane was simultaneously on fire and rotating 180 degrees. The airplane struck the ground again and the pilot exited the airplane. The chemical manufacturer stated that the powdered sulfur dust compound used in aerial application operations was considered a moderate fire hazard. The airplane was destroyed by a post impact fire.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A partial loss of engine power for an undetermined reason, and the ignition of a highly combustible compound in the application hopper.

## Findings

Occurrence #1: LOSS OF ENGINE POWER  
Phase of Operation: TAKEOFF - INITIAL CLIMB

### Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED

-----

Occurrence #2: FORCED LANDING  
Phase of Operation: EMERGENCY LANDING AFTER TAKEOFF

-----

Occurrence #3: FIRE  
Phase of Operation: LANDING - ROLL

Findings  
2. (C) AERIAL APPLICATION MATERIALS - OTHER

## Factual Information

On September 2, 1998, at 0630 hours Pacific daylight time, a Cessna 188B, N202AW, experienced a loss of engine power after takeoff and made an emergency landing in an alfalfa field near Dixon, California. The aircraft, operated under 14 CFR Part 137 as an agricultural crop dusting operation by the William D. Joslin Corporation, was destroyed in a postimpact fire. The commercial instrument rated pilot, the sole occupant, was not injured. Visual meteorological conditions existed for the flight and no flight plan was filed.

The pilot stated that this was the first flight of the day and he was going to spray sulfur dust on a tomato field. After departure, he reduced power at approximately 100 feet agl. He experienced a partial loss of power, and made a forced landing in an adjacent alfalfa field. The pilot stated that after landing the aircraft caught fire and was destroyed in the ensuing fire.

A Federal Aviation Administration (FAA) inspector responded to the scene and interviewed the owner. Aircraft and engine testing were not conducted due to the postimpact fire. The owner reported that the aircraft had flown the day before the accident flight with no discrepancies noted. This was the first flight of the day and the aircraft was carrying a full load of sulfur. After takeoff the pilot made a turn to the left and the engine quit. The owner stated that the pilot attempted to return to the runway, and when he saw he was not going to make it made a slight banking turn to the right and aimed for an open field. The owner reported that the aircraft was in a nose high attitude with a high sink rate due to the full load of chemicals. The aircraft landed hard and bounced into the air. After the first bounce, the aircraft was simultaneously on fire and was rotating 180 degrees. The aircraft struck the ground again and the pilot exited the aircraft.

The chemical manufacturer was contacted and the representative stated that the powdered sulfur dust compound used in aerial application operations is considered a moderate fire hazard according to the National Fire Protection Association criteria. While the compound has a flash point of 374 degrees Fahrenheit, published studies (page 48, INVESTIGATION OF FIRE AND EXPLOSION HAZARDS IN CHEMICAL, MINING AND FUEL RELATED INDUSTRIES Bureau of Mines, U.S. Department of Interior) demonstrate that atomized layers of clouds of dust may ignite at ignition temperatures of 190 degrees in air to substance density limits of less than 0.1 ounces per cubic foot. The test was conducted in a Hartman apparatus with a high voltage 24-watt spark source for ignition.

The manufacturer's representative noted that sulfur is processed in an inert atmosphere during manufacture into the powdered form to prevent potential explosions or fires.

## Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	31, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Front
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 1 Valid Medical--no waivers/lim.	<b>Last FAA Medical Exam:</b>	December 5, 1997
<b>Occupational Pilot:</b>	UNK	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	2100 hours (Total, all aircraft), 240 hours (Total, this make and model), 1850 hours (Pilot In Command, all aircraft), 87 hours (Last 90 days, all aircraft), 38 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Cessna	<b>Registration:</b>	N202AW
<b>Model/Series:</b>	188B 188B	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	18800835
<b>Landing Gear Type:</b>	Tailwheel	<b>Seats:</b>	1
<b>Date/Type of Last Inspection:</b>	January 24, 1998 100 hour	<b>Certified Max Gross Wt.:</b>	4000 lbs
<b>Time Since Last Inspection:</b>	40 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	5853 Hrs	<b>Engine Manufacturer:</b>	Continental
<b>ELT:</b>		<b>Engine Model/Series:</b>	IO-520D
<b>Registered Owner:</b>	WILLIAM D. JOSLIN	<b>Rated Power:</b>	300 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	
<b>Operator Does Business As:</b>		<b>Operator Designator Code:</b>	

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Dawn
<b>Observation Facility, Elevation:</b>	SAC ,24 ft msl	<b>Distance from Accident Site:</b>	15 Nautical Miles
<b>Observation Time:</b>	06:53 Local	<b>Direction from Accident Site:</b>	46°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	3 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	270°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29 inches Hg	<b>Temperature/Dew Point:</b>	17°C / 14°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	, CA	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>		<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	06:30 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>		<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>		<b>Runway Surface Condition:</b>	
<b>Runway Used:</b>	0	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Destroyed
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	On-ground
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	38.389244,-121.809791(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Cornejo, Tealeye
<b>Additional Participating Persons:</b>	EARL BENEDICT; SACRAMENTO , CA
<b>Original Publish Date:</b>	June 21, 2000
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=43853">https://data.nts.gov/Docket?ProjectID=43853</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).