

Aviation Investigation Final Report

Location:	UNALAKLEET, Alask	а	Accident Number:	ANC85LA043
Date & Time:	January 31, 1985, 13	3:12 Local	Registration:	N410WR
Aircraft:	CESSNA	U206G	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 135: Air taxi & commuter - Non-scheduled			

Analysis

ACFT VEERED TO THE LEFT AND CONTACTED A SNOWBANK DURING THE TAKEOFF GROUND ROLL. INSPECTION REVEALED PLT FAILED TO REMOVE THE RUDDER GUST LOCK BEFORE TAKEOFF WAS ATTEMPTED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. (C) AIRCRAFT PREFLIGHT - INADEQUATE - PILOT IN COMMAND 2. (C) REMOVAL OF CONTROL/GUST LOCK(S) - NOT PERFORMED - PILOT IN COMMAND 3. DIRECTIONAL CONTROL - NOT POSSIBLE - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: TAKEOFF - ROLL/RUN

Findings 4. AIRPORT FACILITIES, RUNWAY/LANDING AREA CONDITION - SNOWBANK

Factual Information

Pilot Information

Certificate:	Commercial	Age:	42,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	June 10, 1984
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	4200 hours (Total, all aircraft), 600 hours (Total, this make and model), 4200 hours (Pilot In Command, all aircraft), 90 hours (Last 90 days, all aircraft), 45 hours (Last 30 days, all aircraft), 15 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N410WR
Model/Series:	U206G U206G	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Utility	Serial Number:	04472
Landing Gear Type:	Tricycle	Seats:	6
Date/Type of Last Inspection:	December 1, 1984 100 hour	Certified Max Gross Wt.:	3500 lbs
Time Since Last Inspection:	21 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	5021 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	10-520
Registered Owner:	RYAN AIR SERVICE, INC.	Rated Power:	285 Horsepower
Operator:		Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 1500 ft AGL	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	27 inches Hg	Temperature/Dew Point:	2°C / -1°C
Precipitation and Obscuration:	No Obscuration; No Precipita	tion	
Departure Point:	UNALAKLEET , AK (UNK)	Type of Flight Plan Filed:	VFR
Destination:	SHAKTOOLIK , AK (SKI)	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Airport Information

Airport:	UNALAKLEET UNK	Runway Surface Type:	Snow
Airport Elevation:	21 ft msl	Runway Surface Condition:	Dry
Runway Used:	32	IFR Approach:	None
Runway Length/Width:	6000 ft / 170 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	64.090499,-160.360885(est)

Administrative Information

Investigator In Charge (IIC):	Michelangelo, James
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=4463

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.