

Aviation Investigation Final Report

Location:	DILLINGHAM, Alas	ka	Accident Number:	ANC85LA103
Date & Time:	June 21, 1985, 13:3	30 Local	Registration:	N45PC
Aircraft:	PIPER	PA-20	Aircraft Damage:	Substantial
Defining Event:			Injuries:	2 None
Flight Conducted Under:	Part 91: General av	viation - Personal		

Analysis

THE AIRCRAFT SWERVD ON THE RUNWAY AND GROUND LOOPED, THE PILOT STATED HE LOST CONTROL OF THE ACFT DUE TO THE WIND CONDITION.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - ROLL

Findings

(F) WEATHER CONDITION - HIGH WIND
(F) PROCEDURES/DIRECTIVES - NOT FOLLOWED - PILOT IN COMMAND
(F) WEATHER CONDITION - UNFAVORABLE WIND
(C) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND
(C) GO-AROUND - NOT PERFORMED - PILOT IN COMMAND
(C) LOAD JETTISON - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: LANDING - ROLL

Factual Information

Pilot Information

T not information			
Certificate:	Private	Age:	60,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	February 24, 1985
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	115 hours (Total, all aircraft), 115 hours (Total, this make and model), 65 hours (Pilot In Command, all aircraft), 25 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N45PC
Model/Series:	PA-20 PA-20	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	223145
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	March 10, 1985 Annual	Certified Max Gross Wt.:	1950 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-290-D
Registered Owner:	JIM D. REARDEN	Rated Power:	125 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:			Distance from Accident Site:	
Observation Time:	13:35 Local		Direction from Accident Site:	
Lowest Cloud Condition:	Clear		Visibility	50 miles
Lowest Ceiling:	None		Visibility (RVR):	
Wind Speed/Gusts:	10 knots / 20	0 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	190°		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Ho	g	Temperature/Dew Point:	8°C / -7°C
Precipitation and Obscuration:	No Obscuration; No Precipitation			
Departure Point:	HOMER	, AK (HOM)	Type of Flight Plan Filed:	VFR
Destination:			Type of Clearance:	None
Departure Time:	10:30 Local		Type of Airspace:	Class E

Airport Information

Airport:	DILLINGHAM DLG	Runway Surface Type:	Asphalt
Airport Elevation:	85 ft msl	Runway Surface Condition:	Dry
Runway Used:	19	IFR Approach:	None
Runway Length/Width:	6404 ft / 150 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	58.819866,-157.860321(est)

Administrative Information

Investigator In Charge (IIC):	Michealangelo, James
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=4505

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.