



# Aviation Investigation Final Report

<b>Location:</b>	HICKORY, North Carolina	<b>Accident Number:</b>	MIA99LA017
<b>Date &amp; Time:</b>	October 26, 1998, 15:15 Local	<b>Registration:</b>	N500GQ
<b>Aircraft:</b>	Reinhold MINI 500	REVOLUTION	<b>Aircraft Damage:</b> Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

The pilot stated the engine lost power without warning while in cruise flight between 500-700 feet. An autorotation was made to a clear area with high vegetation. During touchdown on the previously unnoticed uneven terrain, the main rotor hit the mechanical stop and contacted the tailboom. The helicopter then spun around 180 degrees and came to rest. Postcrash examination of the engine showed the rear cylinder had seized in the barrel. The pilot stated this was the second time this had happened. The engine had accumulated 46 hours since being rebuilt after the previous failure.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The seizure of the rear piston in the cylinder barrel resulting in total loss of engine power and an autorotation which resulted in main rotor contact with the tail boom while touching down on unsuitable terrain.

### Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - MECH FAILURE/MALF  
Phase of Operation: CRUISE - NORMAL

#### Findings

1. (C) ENGINE ASSEMBLY, PISTON - SEIZED

-----

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY DESCENT/LANDING

Findings

2. AUTOROTATION - PERFORMED - PILOT IN COMMAND

-----

Occurrence #3: MISCELLANEOUS/OTHER

Phase of Operation: EMERGENCY DESCENT/LANDING

Findings

3. TERRAIN CONDITION - NONE SUITABLE

4. TERRAIN CONDITION - HIGH VEGETATION

5. MISC ROTORCRAFT,MAIN ROTOR/TAIL BOOM CONTACT

## Factual Information

On October 26, 1998, about 1515 eastern standard time, a Reinhold Revolution Mini 500, N500GQ, registered to an individual, crashed while making a forced landing following loss of engine power near Hickory, North Carolina, while on a Title 14 CFR Part 91 personal flight. Visual meteorological conditions prevailed at the time and no flight plan was filed. The helicopter received substantial damage and the airline transport-rated pilot was not injured. The flight originated from Hickory, North Carolina, the same day, about 1600.

The pilot stated that while in cruise flight at between 500-700 feet, the engine quit with no prior warning. He initiated an autorotation and made a left turn toward a clearing. Upon touchdown on uneven terrain, the main rotor hit the mechanical stop and then contacted the tailboom. The helicopter spun around to the left 180 degrees and came to rest on the back skids and engine muffler. The clear area he selected for the landing was overgrown with about 6 feet of vegetation.

Postcrash examination of the engine by the pilot showed the rear piston had seized in the barrel. The pilot stated to NTSB that this was the second time this has happened in this helicopter. The engine had accumulated about 46 flight hours since it was rebuilt after the previous piston seizure.

### Pilot Information

<b>Certificate:</b>	Airline transport; Flight engineer; Flight instructor	<b>Age:</b>	39, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Center
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	Airplane multi-engine; Airplane single-engine; Instrument airplane	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 1 Valid Medical--no waivers/lim.	<b>Last FAA Medical Exam:</b>	May 19, 1998
<b>Occupational Pilot:</b>	UNK	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	11600 hours (Total, all aircraft), 69 hours (Total, this make and model), 4000 hours (Pilot In Command, all aircraft), 210 hours (Last 90 days, all aircraft), 70 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Reinhold	<b>Registration:</b>	N500GQ
<b>Model/Series:</b>	REVOLUTION MINI 500 REVOLUTION	<b>Aircraft Category:</b>	Helicopter
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	Yes
<b>Airworthiness Certificate:</b>	Experimental (Special)	<b>Serial Number:</b>	404
<b>Landing Gear Type:</b>	Skid	<b>Seats:</b>	1
<b>Date/Type of Last Inspection:</b>	March 15, 1998 Annual	<b>Certified Max Gross Wt.:</b>	840 lbs
<b>Time Since Last Inspection:</b>	38 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	69 Hrs	<b>Engine Manufacturer:</b>	Rotax
<b>ELT:</b>	Installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	582
<b>Registered Owner:</b>	GRAUER REINHOLD	<b>Rated Power:</b>	67 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	None
<b>Operator Does Business As:</b>		<b>Operator Designator Code:</b>	

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	HKY ,1189 ft msl	<b>Distance from Accident Site:</b>	1 Nautical Miles
<b>Observation Time:</b>	15:53 Local	<b>Direction from Accident Site:</b>	270°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	/	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	0°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30 inches Hg	<b>Temperature/Dew Point:</b>	24°C / 4°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	WEDDINGTON , NC	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>		<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	13:45 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>		<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>		<b>Runway Surface Condition:</b>	
<b>Runway Used:</b>	0	<b>IFR Approach:</b>	
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	35.770591,-81.329452(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Kennedy, Jeffrey
<b>Additional Participating Persons:</b>	RALPH S CARR; CHARLOTTE , NC
<b>Original Publish Date:</b>	August 27, 1999
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=45171">https://data.ntsb.gov/Docket?ProjectID=45171</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).