



# **Aviation Investigation Final Report**

Location: ANCHORAGE, Alaska Accident Number: ANC85LA149

Date & Time: August 6, 1985, 16:35 Local Registration: N7070K

Aircraft: PIPER PA-20-135 Aircraft Damage: Substantial

**Defining Event:** 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

LOW TIME STUDENT PLT LOST CONTROL DURING ATTEMPTED GO-AROUND & CRASHED INTO TWO PARKED ACFT. 8 TO 12 KT CROSSWIND WAS REPORTED.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: GO-AROUND (VFR)

#### **Findings**

- 1. TERRAIN CONDITION UPHILL
- 2. (C) COMPENSATION FOR WIND CONDITIONS INADEQUATE PILOT IN COMMAND
- 3. (C) OVERCONFIDENCE IN PERSONAL ABILITY PILOT IN COMMAND
- 4. (F) INSUFFICIENT STANDARDS/REQUIREMENTS, AIRMAN FAA(ORGANIZATION)
- 5. TERRAIN CONDITION HIGH VEGETATION
- 6. (F) ANXIETY/APPREHENSION PILOT IN COMMAND
- 7. (F) INADEQUATE CERTIFICATION/APPROVAL, AIRMAN FAA(ORGANIZATION)
- 8. (F) WEATHER CONDITION CROSSWIND
- 9. (C) INADEQUATE TRANSITION/UPGRADE TRAINING PILOT IN COMMAND
- 10. (F) LACK OF TOTAL EXPERIENCE IN KIND OF AIRCRAFT PILOT IN COMMAND
- 11. (F) TOTAL PILOT IN COMMAND

12. (F) OVERCONFIDENCE IN PERSONAL ABILITY - PILOT IN COMMAND

13. (F) LACK OF TOTAL EXPERIENCE - PILOT IN COMMAND

-----

Occurrence #2: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: GO-AROUND (VFR)

Findings

14. (F) TOTAL - PILOT IN COMMAND

Page 2 of 5 ANC85LA149

## **Factual Information**

#### **Pilot Information**

Certificate:	Student	Age:	36,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	July 9, 1985
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	62 hours (Total, all aircraft), 5 hours (Total, this make and model), 13 hours (Last 90 days, all aircraft)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	PIPER	Registration:	N7070K
Model/Series:	PA-20-135 PA-20-135	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	20-179
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	July 3, 1985 Annual	Certified Max Gross Wt.:	1950 lbs
Time Since Last Inspection:	10 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2210 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-290-D2
Registered Owner:	CLIFFORD K. ANDREWS	Rated Power:	135 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 ANC85LA149

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Scattered / 3000 ft AGL	Visibility	60 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots / 12 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	18°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	tion	
Departure Point:	TALKEETNA , AK (TKA )	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	15:30 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	SKY HARBOR AIRSTRIP	Runway Surface Type:	Gravel
Airport Elevation:	340 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	34	IFR Approach:	None
Runway Length/Width:	1800 ft / 70 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	

Page 4 of 5 ANC85LA149

#### **Administrative Information**

Investigator In Charge (IIC): Daw, Roy

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=4541

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC85LA149