

# **Aviation Investigation Final Report**

Location:	DILLINGHAM, Alaska		Accident Number:	ANC85LA161
Date & Time:	August 25, 1985, 13:0	0 Local	Registration:	N86090
Aircraft:	AERONCA	11AC	Aircraft Damage:	Substantial
Defining Event:			Injuries:	2 None
Flight Conducted Under:	Part 91: General aviati	ion - Personal		

### **Analysis**

THE PILOT STATED THAT APPROXIMATELY 200 FT INTO THE ROLLOUT THE RIGHT WING LIFTED INTO THE AIR, VEERING THE PLANE TO THE RIGHT LOSING DIRECTIONAL CONTROL OF THE AIRCRAFT CAUSING THE AIRCRAFT TO EXIT THE RUNWAY INTO A GRAVEL PIT.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: TAKEOFF - ROLL/RUN

Findings

- 1. (C) WIND INFORMATION MISJUDGED PILOT IN COMMAND
- 2. (F) IMPROPER USE OF PROCEDURE PILOT IN COMMAND
- 3. (C) PROCEDURES/DIRECTIVES NOT FOLLOWED PILOT IN COMMAND
- 4. (F) PRESSURE PILOT IN COMMAND
- 5. (C) DIRECTIONAL CONTROL NOT FOLLOWED PILOT IN COMMAND
- 6. (F) SELF-INDUCED PRESSURE PILOT IN COMMAND
- 7. (C) GROUND LOOP/SWERVE MISJUDGED PILOT IN COMMAND

# **Factual Information**

#### **Pilot Information**

Certificate:	Private	Age:	31,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	August 6, 1985
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	398 hours (Total, all aircraft), 340 hours (Pilot In Command, all aircraft)		

#### Aircraft and Owner/Operator Information

Aircraft Make:	AERONCA	Registration:	N86090
Model/Series:	11AC 11AC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	11AC513
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	March 13, 1985 Annual	Certified Max Gross Wt.:	1250 lbs
Time Since Last Inspection:	19 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1538 Hrs	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	A-78-8
Registered Owner:	AGNES ILUTSIK	Rated Power:	75 Horsepower
Operator:	JAMES L. GRAITY	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

#### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	DLG ,85 ft msl	Distance from Accident Site:	
Observation Time:	12:30 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 6000 ft AGL	Visibility	40 miles
Lowest Ceiling:	Broken / 1000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	10°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	14°C / 4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	

## **Airport Information**

Airport:	DILLINGHAM DLG	Runway Surface Type:	Asphalt
Airport Elevation:	85 ft msl	Runway Surface Condition:	Dry
Runway Used:	1	IFR Approach:	None
Runway Length/Width:	6404 ft / 150 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	58.820354,-157.859634(est)

#### **Administrative Information**

Investigator In Charge (IIC):	Michelangelo, James
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=4551
	https://data.ntsb.gov/Docket?ProjectID=4551

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.