



Aviation Investigation Final Report

Location: FEATHER RIVER, Alaska Accident Number: ANC85LA182

Date & Time: September 22, 1985, 20:00 Local Registration: N7440K

Aircraft: PIPER PA-20 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

WHILE LANDING IN GUSTY SURFACE WIND CONDITIONS THE PILOT LOST CONTROL OF HE AIRPLANE AND TURNED OVER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

- 1. (F) WEATHER CONDITION CROSSWIND
- 2. (F) WEATHER CONDITION GUSTS
- 3. (C) WIND INFORMATION INADEQUATE PILOT IN COMMAND
- 4. (C) COMPENSATION FOR WIND CONDITIONS IMPROPER PILOT IN COMMAND
- 5. (C) DIRECTIONAL CONTROL NOT MAINTAINED PILOT IN COMMAND

Occurrence #2: NOSE OVER

Phase of Operation: LANDING - ROLL

Findings

- 6. (F) IMPROPER USE OF PROCEDURE PILOT IN COMMAND 7. (F) LACK OF TOTAL EXPERIENCE PILOT IN COMMAND

Page 2 of 5 ANC85LA182

Factual Information

Pilot Information

Certificate:	Private	Age:	32,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Expired	Last FAA Medical Exam:	May 10, 1978
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	178 hours (Total, all aircraft), 81 hours (Total, this make and model), 119 hours (Pilot In Command, all aircraft), 64 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N7440K
Model/Series:	PA-20 PA-20	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	20-351
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	August 2, 1985 Annual	Certified Max Gross Wt.:	1950 lbs
Time Since Last Inspection:	13 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2327 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-290-2
Registered Owner:	CRAIG WOLTER	Rated Power:	125 Horsepower
Operator:	DAVID BRIAN LEMASTER	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 ANC85LA182

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:	20:00 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	30 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	15 knots / 35 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	335°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	10°C / 2°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	NOME , AK (OME)	Type of Flight Plan Filed:	VFR
Destination:	FEATHER RIVER , AK (3Z1)	Type of Clearance:	None
Departure Time:	18:48 Local	Type of Airspace:	Class G

Airport Information

Airport:	FEATHER RIVER 3Z1	Runway Surface Type:	Gravel
Airport Elevation:	325 ft msl	Runway Surface Condition:	Dry
Runway Used:	13	IFR Approach:	None
Runway Length/Width:	1650 ft / 40 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Page 4 of 5 ANC85LA182

Administrative Information

Investigator In Charge (IIC):	Stella, Marc
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=4570

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC85LA182