

Aviation Investigation Final Report

Location:	RIALTO, California		Accident Number:	LAX99TA115
Date & Time:	March 9, 1999, 17:55 Local		Registration:	N626SB
Aircraft:	McDonnell Douglas	600N	Aircraft Damage:	Substantial
Defining Event:			Injuries:	3 Minor
Flight Conducted Under:	Part 91: General aviation - Public aircraft			

Analysis

During a routine law enforcement patrol flight, the pilot responded to the 4,700-foot mean sea level mountainside to investigate circumstances related to an apparent abandoned vehicle. Upon arriving at the site, the pilot performed a toe-in landing to discharge his crewmember. The crewmember proceeded to evaluate the vehicle while the pilot orbited the area. While orbiting, the pilot observed that low elevation clouds were approaching. However, the visibility initially was about 10 miles, and the cloud height appeared between 500 and 600 feet above the ground. After a few minutes, the crewmember returned to the helicopter, and they departed. Seconds after taking off the pilot lost visual reference with the ground. The pilot further indicated that he continued flying by reference to his flight instruments and the helicopter began spinning. Between 1 and 1.5 minutes later the spinning stopped, and the helicopter lost altitude until impacting the mountainside.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's improper in-flight decision to maneuver in the area while observed inclement weather approached, which led to a loss of control. Contributing factors were the low ceilings, mountainous terrain and spatial disorientation.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: MANEUVERING Findings

- 1. (F) WEATHER CONDITION LOW CEILING
- 2. TERRAIN CONDITION MOUNTAINOUS/HILLY
- 3. (C) IN-FLIGHT PLANNING/DECISION IMPROPER PILOT IN COMMAND
- 4. (C) FLIGHT INTO KNOWN ADVERSE WEATHER INADVERTENT PILOT IN COMMAND
- 5. (C) AIRCRAFT CONTROL NOT MAINTAINED PILOT IN COMMAND
- 6. (F) SPATIAL DISORIENTATION PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: DESCENT - UNCONTROLLED

Findings

7. (F) TERRAIN CONDITION - MOUNTAINOUS/HILLY

Factual Information

On March 9, 1999, about 1755 hours Pacific standard time, a McDonnell Douglas 600N, N626SB, entered instrument meteorological conditions (IMC) and collided with 4,700-foot mean sea level mountainous terrain about 7 miles north of Rialto, California. A company visual flight rules (VFR) flight plan was filed. The helicopter was substantially damaged. The commercial pilot, the flight officer (crewmember), and the passenger sustained minor injuries. The aircraft was operated by the San Bernardino County Sheriff's Department, San Bernardino, California, as a public-use aircraft under the provisions of 14 CFR Part 91. The local area flight originated from San Bernardino about 1708.

In the pilot's completed report, and during an interview, he indicated that the accident occurred while on a routine law enforcement patrol flight. In summary, the pilot reported that he was on a mission to investigate circumstances related to an apparent abandoned vehicle. Upon arriving at the mountainside, he performed a toe-in landing to discharge the crewmember. While the crewmember evaluated the vehicle, the pilot orbited the area, and noted that low elevation clouds were approaching. However, the visibility was about 10 miles, and the clouds appeared to have been between 500 and 600 feet above the ground. After a few minutes, the crewmember returned to the helicopter, and they departed. Seconds after taking off the pilot lost visual reference with the ground. The pilot further indicated that he continued flying by reference to his flight instruments and the helicopter began spinning. Between 1 and 1.5 minutes later the spinning stopped, and the helicopter lost altitude until impacting the mountainside.

Certificate:	Commercial; Military	Age:	34,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Helicopter	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	August 9, 1998
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	1654 hours (Total, all aircraft), 35 hours (Total, this make and model), 1612 hours (Pilot In Command, all aircraft), 104 hours (Last 90 days, all aircraft), 72 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Pilot Information

Aircraft and Owner/Operator Information

Aircraft Make:	McDonnell Douglas	Registration:	N626SB
Model/Series:	600N 600N	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	RN024
Landing Gear Type:	Skid	Seats:	8
Date/Type of Last Inspection:	February 18, 1999 AAIP	Certified Max Gross Wt.:	3850 lbs
Time Since Last Inspection:	66 Hrs	Engines:	1 Turbo shaft
Airframe Total Time:	266 Hrs	Engine Manufacturer:	Allison
ELT:	Installed, activated, aided in locating accident	Engine Model/Series:	250-C47M
Registered Owner:	SAN BERNARDINO CTY SHERIFF DPT	Rated Power:	808 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Instrument (IMC)	Condition of Light:	Day
Observation Facility, Elevation:	ONT ,943 ft msl	Distance from Accident Site:	17 Nautical Miles
Observation Time:	17:53 Local	Direction from Accident Site:	208°
Lowest Cloud Condition:	Scattered / 5000 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	11 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	240°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	11°C / 6°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	RIALTO, CA (L67)	Type of Flight Plan Filed:	Company VFR
Destination:		Type of Clearance:	VFR on top
Departure Time:	17:08 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	2 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 Minor	Latitude, Longitude:	34.100776,-117.380821(est)

Administrative Information

Investigator In Charge (IIC):	Pollack, Wayne		
Additional Participating Persons:	ERIC JACKSON; RIVERSIDE , CA		
Original Publish Date:	January 18, 2001		
Last Revision Date:			
Investigation Class:	<u>Class</u>		
Note:			
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=45899		

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.