



Aviation Investigation Final Report

Location: BROOKSVILLE, Florida Accident Number: ATL99LA091

Date & Time: May 15, 1999, 12:00 Local Registration: N8055Y

Aircraft: Piper PA-30 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The flight instructor and private pilot arrived at their destination after an uneventful flight. Upon touchdown on the runway, the airplane porpoised, ballooned, and yawed to the left with the left wing low and the nose in a nose high attitude. The instructor took control of the aircraft and during the second landing attempt the right main gear collapsed. The right wing and propeller struck the runway. The airplane subsequently departed the left edge of the runway at an angle of approximately 45 degrees. No mechanical problems were reported by the pilot.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The certified flight instructor's failure to recover from a porpoise during landing and his failure to maintain directional control.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING

Findings

1. (F) PORPOISE/PILOT-INDUCED OSCILLATION - NOT CORRECTED - PILOT IN COMMAND(CFI)

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND(CFI)

Occurrence #2: GEAR COLLAPSED Phase of Operation: LANDING

Findings
3. LANDING GEAR, NOSE GEAR - OVERLOAD

Page 2 of 6 ATL99LA091

Factual Information

On May 15, 1999, at 1200 eastern daylight time, a Piper PA-30, N8055Y, collided with the runway when the right main gear collapsed on landing at the Hernando County Airport, in Brooksville, Florida. The dual instructional flight was operated by the certified flight instructor (CFI) under the provisions of Title 14 CFR Part 91, and visual flight rules. Visual meteorological conditions prevailed and no flight plan was filed. The CFI and the private pilot were not injured and the airplane sustained substantial damage. The flight originated from Orlando Executive Airport, Orlando, Florida, at 1130.

According to the CFI, a normal preflight and run-up was conducted prior to the flight to Brooksville, Florida. The enroute portion of the flight was uneventful with no mechanical problems reported by the CFI. The instructor reported that the Automated Surface Observation System (ASOS) at the destination airport indicated that the winds were variable from the northeast at 10 to 12 knots. The CFI elected to use runway 09. A before landing checklist was completed, and the CFI reported that a visual check of the landing showed all three wheels down and locked. Upon touchdown, the airplane "suddenly and inexplicably porpoise on to the nose gear." The airplane then "ballooned" yawing left with the left wing low and, at a nose-high attitude. The CFI took control of the airplane and took the following corrective action: added full power, applied right rudder, applied right aileron and applied forward pressure on the yoke. Attempts by the CFI to correct the attitude of the airplane failed. The right main landing gear subsequently collapsed, and the airplane departed the left edge of runway 09 at a 45 degree angle.

Damage to the airplane consisted of the right wing spar, right tip tank, right horizontal stabilizer, right main gear, right propeller, and the right flap lower attach points.

Page 3 of 6 ATL99LA091

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	33,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medical-no waivers/lim.	Last FAA Medical Exam:	December 18, 1998
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1276 hours (Total, all aircraft), 212 hours (Total, this make and model), 1209 hours (Pilot In Command, all aircraft), 41 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N8055Y
Model/Series:	PA-30 PA-30	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	30-1168
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	July 23, 1998 Annual	Certified Max Gross Wt.:	3780 lbs
Time Since Last Inspection:	19 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	8114 Hrs	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	10-360-CIC
Registered Owner:	JOSEPH A. LEVANDOWSKI	Rated Power:	200 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 4 of 6 ATL99LA091

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	BKV ,77 ft msl	Distance from Accident Site:	
Observation Time:	11:53 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	30°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	29°C / 18°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	ORLANDO , FL (ORL)	Type of Flight Plan Filed:	None
Destination:	(BKV)	Type of Clearance:	None
Departure Time:	11:30 Local	Type of Airspace:	Class G

Airport Information

Airport:	HERNANDO COUNTY BKV	Runway Surface Type:	Asphalt
Airport Elevation:	77 ft msl	Runway Surface Condition:	Dry
Runway Used:	9	IFR Approach:	None
Runway Length/Width:	7001 ft / 50 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	28.480476,-82.509025(est)

Page 5 of 6 ATL99LA091

Administrative Information

Investigator In Charge (IIC): Wilson, Butch

Additional Participating Persons:

Original Publish Date: May 12, 2000

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=46362

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ATL99LA091