



Aviation Investigation Final Report

| | | | |
|--------------------------------|--------------------------------------|-------------------------|-------------|
| Location: | GRAFTON, Ohio | Accident Number: | NYC99LA113 |
| Date & Time: | May 15, 1999, 20:45 Local | Registration: | N812WC |
| Aircraft: | Hiller UH-12C | Aircraft Damage: | Substantial |
| Defining Event: | | Injuries: | 2 None |
| Flight Conducted Under: | Part 91: General aviation - Personal | | |

Analysis

About 500 feet above ground level, and 10 minutes before landing, the pilot noticed a change in main rotor noise. The engine rpm increased, and rotor rpm decreased. The pilot reduced collective and increased throttle, but engine rpm continued to increase, and rotor rpm continued to decrease. The pilot entered an autorotation, the helicopter impacted a wire, and then came to rest upright. Inspection of the mercury clutch revealed a 'minor' leak from the transmission sun gear seal, but no oil was discovered on the clutch shoes. In addition, the intermediate drive shaft teeth were 'severely' worn, and three of the teeth had broken corners. The clutch shoes were worn beyond limits, and were glazed consistent with overheating. One clutch return spring was broken. The driver slots in the clutch side plates were 'severely' worn, and the driver lugs were also 'severely' worn. All the clutch attaching hardware were 'improperly' safetied, using .031 inch safety wire, and 'numerous' fasteners were safetied backwards. The clutch was a conditional item. Since the last 100 hour inspection on March 12, 1999, the helicopter flew 100 hours.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: Inadequate maintenance which resulted in the failure of the mercury clutch assembly.

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION
Phase of Operation: CRUISE

Findings

1. AUTOROTATION - PERFORMED - PILOT IN COMMAND
2. ROTOR DRIVE SYSTEM, CLUTCH ASSEMBLY - WORN
3. (C) MAINTENANCE - INADEQUATE - OTHER MAINTENANCE PERSONNEL

Occurrence #2: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: DESCENT - EMERGENCY

Findings

4. OBJECT - WIRE, TRANSMISSION

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Findings

5. TERRAIN CONDITION - GRASS

Factual Information

On May 15, 1999, about 2045, eastern daylight time, a Hiller UH-12C helicopter, N812WC, was substantially damaged after contacting a wire while executing an autorotation to an open area near Grafton, Ohio. The certificated commercial pilot and passenger were not injured. Visual meteorological conditions prevailed. No flight plan was filed for the personal cross-country flight conducted under 14 CFR Part 91, that departed Findlay, Ohio, destined for the Columbia Airport, Columbia, Ohio.

The day before the accident, the pilot and passenger flew to Findlay, Ohio, and landed at the local fair grounds. After coordinating with fair organizers, and conducting a flight to the Findlay Airport to coordinate fuel, the pilot started giving helicopter rides. After several rides, he stopped because of weather. In addition, the pilot felt the weather was too severe to return to Columbia, so he and the passenger checked into a hotel.

The next day, the pilot and passenger arrived at the fair grounds, about 1000. The pilot started giving rides about 1300, and continued until about 1745. He then flew back to the Findlay Airport, paid his fuel bill, and returned to the fair grounds.

About 1930, the pilot performed a second preflight for the return flight to Columbia. The pilot and passenger boarded, and the pilot started the helicopter's engine. Once the engine oil temperature went above 40 degrees Celsius, and the main rotor rpm and engine rpm matched, the pilot increased engine rpm to 2,700. He checked both the left and right magnetos, and noted no change in engine rpm. He then stabilized the engine rpm at 3,100, "cut" the throttle, and checked the sprag clutch. No anomalies were noted. After reestablishing 3,100 engine rpm, the pilot increased collective, and executed a crosswind takeoff to the northeast. He stopped the climb at 500 feet agl, and established the helicopter on course for Columbia.

Ten minutes before landing at Columbia, the pilot noticed a change in main rotor noise. He also noticed the engine rpm increasing and rotor rpm decreasing. He reduced collective and increased throttle, but engine rpm continued to increase, and rotor rpm continued to decrease. At this point, the helicopter started to shake, and the pilot felt he was losing control. He estimated that main rotor rpm decreased to 250.

The pilot entered an autorotation, and started a right turn to regain main rotor rpm. The main rotor rpm increased, and the helicopter stop shaking. While in the turn the pilot located an open area, and maneuvered to land. On final for the open area, and about 75 feet agl, the pilot identified a wire below his descent path running parallel to a road. Prior to passing over the wire the pilot identified a second wire above the first. The helicopter contacted the second wire, and the pilot heard a loud noise, and saw several intense flashes of light. The helicopter then rotated to the left several times while traveling backwards. The helicopter impacted the

ground in a level attitude. The tail rotor made contact with rising terrain destroying the tailrotor blades, and shearing the tailrotor drive shaft. With the main rotor blades still rotating, the pilot secured the ignition system, electrical master, and fuel, before he and the passenger exited the helicopter without injury.

The pilot added that the helicopter consumed 1 quart of oil for every 2 to 2 1/2 hours of flight time. In addition, the pilot had 5,400 hours of total flight experience, 5,100 hours in helicopters, and 80 hours in helicopters in the last 90 days.

On May 26, 1999, the mercury clutch was examined at a maintenance facility under the supervision of a Federal Aviation Administration Inspector. During the examination, the Inspector discovered a "minor" leak from the transmission sun gear seal, but no oil was discovered on the clutch shoes. In addition, the intermediate drive shaft teeth were "severely" worn, and three of the teeth had broken corners. The clutch shoes were worn to the bottom of the wear grooves, and were glazed consistent with overheating. One clutch return spring was broken. The driver slots in the clutch side plates were "severely" worn, and the driver lugs were also "severely" worn. All the clutch attaching hardware were "improperly" safetied, using .031 inch safety wire, and "numerous" fasteners were safetied backwards. The Inspector added that the clutch shoes were worn beyond limits.

According to the FAA Inspector, the clutch was a conditional item, and the last 100 hour inspection was completed on March 12, 1999. Since the inspection, the helicopter flew 100 hours.

Pilot Information

| | | | |
|----------------------------------|--|--|----------------|
| Certificate: | Commercial | Age: | 49, Male |
| Airplane Rating(s): | Single-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | Helicopter | Restraint Used: | |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 2 Valid Medical--w/ waivers/lim | Last FAA Medical Exam: | March 26, 1999 |
| Occupational Pilot: | UNK | Last Flight Review or Equivalent: | |
| Flight Time: | 5410 hours (Total, all aircraft), 5347 hours (Pilot In Command, all aircraft), 80 hours (Last 90 days, all aircraft), 30 hours (Last 30 days, all aircraft), 7 hours (Last 24 hours, all aircraft) | | |

Aircraft and Owner/Operator Information

| | | | |
|--------------------------------------|---------------------------|---------------------------------------|-----------------|
| Aircraft Make: | Hiller | Registration: | N812WC |
| Model/Series: | UH-12C UH-12C | Aircraft Category: | Helicopter |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 1038 |
| Landing Gear Type: | Skid | Seats: | 3 |
| Date/Type of Last Inspection: | November 9, 1998 100 hour | Certified Max Gross Wt.: | 2500 lbs |
| Time Since Last Inspection: | 100 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 7860 Hrs | Engine Manufacturer: | Franklin |
| ELT: | Not installed | Engine Model/Series: | 6V-335-B |
| Registered Owner: | WILLIAM ASAD | Rated Power: | 210 Horsepower |
| Operator: | | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |

Meteorological Information and Flight Plan

| | | | |
|---|----------------------------------|---|-------------------|
| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Night/dark |
| Observation Facility, Elevation: | CLE ,790 ft msl | Distance from Accident Site: | 24 Nautical Miles |
| Observation Time: | 16:54 Local | Direction from Accident Site: | 50° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 12 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 130° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30 inches Hg | Temperature/Dew Point: | 24°C / 8°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | FINDLAY , OH (NONE) | Type of Flight Plan Filed: | None |
| Destination: | COLUMBIA , OH (4G8) | Type of Clearance: | None |
| Departure Time: | 00:00 Local | Type of Airspace: | Class G |

Airport Information

| | | | |
|-----------------------------|---|----------------------------------|----------------|
| Airport: | | Runway Surface Type: | |
| Airport Elevation: | | Runway Surface Condition: | Vegetation |
| Runway Used: | 0 | IFR Approach: | None |
| Runway Length/Width: | | VFR Approach/Landing: | Forced landing |

Wreckage and Impact Information

| | | | |
|----------------------------|--------|-----------------------------|---------------------------|
| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
| Passenger Injuries: | 1 None | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 2 None | Latitude, Longitude: | 41.280063,-82.029197(est) |

Administrative Information

| | |
|--|---|
| Investigator In Charge (IIC): | Muzio, David |
| Additional Participating Persons: | RON BARONE; CLEVELAND , OH |
| Original Publish Date: | October 13, 2000 |
| Last Revision Date: | |
| Investigation Class: | Class |
| Note: | |
| Investigation Docket: | https://data.nts.gov/Docket?ProjectID=46375 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).