



# Aviation Investigation Final Report

<b>Location:</b>	COEUR D'ALENE, Idaho	<b>Accident Number:</b>	SEA99LA063
<b>Date &amp; Time:</b>	May 15, 1999, 12:30 Local	<b>Registration:</b>	N152WB
<b>Aircraft:</b>	Lake LA-4	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Instructional		

## Analysis

While landing in variable, shifting winds, both the dual student and the instructor had trouble maintaining directional control of the aircraft. After touchdown, the aircraft started turning toward the right side of the runway, and the instructor could not get it to straighten out using maximum left brake and full left rudder. He therefore added power to get airflow over the rudder to increase its efficiency, but the aircraft continued to turn sharper, eventually departing the right side of the runway and impacting the segmented circle at the base of the wind sock. It was later discovered that an improper repair weld on one of the engine pylon mounting straps had failed from fatigue, allowing the engine pylon to twist out of alignment with the longitudinal axis of the aircraft.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The fatigue failure of a repair weld on one of the engine pylon mount straps and the resultant reduction in directional control. Factors include an inadequate repair of the strap, variable wind speeds and sudden wind shifts.

## Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION  
Phase of Operation: UNKNOWN

Findings

1. (C) FUSELAGE - FATIGUE
2. (C) FUSELAGE - FAILURE,PARTIAL
3. (F) MAINTENANCE,MAJOR REPAIR - IMPROPER - UNKNOWN

-----

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER  
Phase of Operation: LANDING - FLARE/TOUCHDOWN

#### Findings

4. (C) DIRECTIONAL CONTROL - DIMINISHED
5. (F) WEATHER CONDITION - VARIABLE WIND
6. (F) WEATHER CONDITION - SUDDEN WINDSHIFT

## Factual Information

On May 15, 1999, approximately 1230 Pacific daylight time, a Lake LA-4, N152WB, impacted the metal segmented circle at the base of the wind sock during a landing attempt on runway 19 at Coeur D'Alene, Idaho. The certified flight instructor (CFI) and his student, who holds a private pilot license, were not injured, but the aircraft, which was owned by the CFI, sustained substantial damage. The 14 CFR Part 91 instructional flight, which originated at Coeur D'Alene about three hours earlier, was being operated in visual meteorological conditions. No flight plan had been filed, and there was no report of an ELT activation.

According to the instructor pilot, the student allowed the aircraft to get high on approach while attempting to land in variable, quickly shifting winds. The instructor told the student to steepen the approach and to center the nose of the aircraft on the runway centerline, which he monetarily did. Just prior to the flare, the instructor noticed that the wind sock was "blowing from side to side," and he again "...instructed rudder correction." Then according to the instructor, during the flare, the nose of the aircraft "...veered sharply to the right and the nose pitched up." The student was unable to bring the aircraft back into correct alignment with the runway during the touchdown, and he allowed the aircraft to land hard while "...sideways on the runway." The instructor then took over just after the aircraft touched down, but it "...jerked sharply to the right and off the runway." The instructor was unable to get the aircraft realigned with the runway using full left rudder and left brake, so he added a burst of power because he thought the increased airflow over the rudder would cause it to be more effective. The addition of power did not help in the instructor's attempt to turn the aircraft back to the left, and instead, the rate of turn to the right increased as the aircraft departed the runway and impacted the segmented circle.

While the aircraft was being disassembled after the accident, the left side engine pylon mount upper strap was found to have failed through a weld that appeared to be part of a previous repair. A portion of the strap, to include the weld line, was sent to the NTSB materials laboratory for analysis. During that analysis, it was determined that there were crack arrest position marks along portions of the weld that were consistent with propagation of a fatigue crack. It was further determined that when the repair weld was made, it had inadequate penetration, minimal fusion, and numerous voids. Also, the strap, which was made of low-alloy steel, was welded using a stainless steel electrode.

A review of the log books did not reveal when the repair had been made, nor whether Service Letter #43, which calls for inspecting the straps for cracks every 100 hours, had been complied with. It was also noted that with the strap fractured, the engine mounting pylon would twist when a cylinder was grasped by hand and forward pressure was applied.

## Pilot Information

<b>Certificate:</b>	Commercial; Flight instructor	<b>Age:</b>	49, Male
<b>Airplane Rating(s):</b>	Single-engine land; Single-engine sea	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	Airplane single-engine; Instrument airplane	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Valid Medical-w/ waivers/lim	<b>Last FAA Medical Exam:</b>	October 16, 1998
<b>Occupational Pilot:</b>	UNK	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	4286 hours (Total, all aircraft), 52 hours (Total, this make and model), 75 hours (Last 90 days, all aircraft), 23 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Lake	<b>Registration:</b>	N152WB
<b>Model/Series:</b>	LA-4 LA-4	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	268
<b>Landing Gear Type:</b>	Amphibian	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	August 11, 1998 Annual	<b>Certified Max Gross Wt.:</b>	2400 lbs
<b>Time Since Last Inspection:</b>	48 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	1367 Hrs	<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	O-360-A1A
<b>Registered Owner:</b>	CHECKLIST TRAINING SYSTEMS	<b>Rated Power:</b>	180 Horsepower
<b>Operator:</b>	MIKE D. KINCAID	<b>Operating Certificate(s) Held:</b>	None
<b>Operator Does Business As:</b>		<b>Operator Designator Code:</b>	

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>		<b>Distance from Accident Site:</b>	
<b>Observation Time:</b>		<b>Direction from Accident Site:</b>	
<b>Lowest Cloud Condition:</b>	Unknown	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	Broken / 3500 ft AGL	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	10 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	0°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30 inches Hg	<b>Temperature/Dew Point:</b>	13°C / 1°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	(COE )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>		<b>Type of Clearance:</b>	VFR
<b>Departure Time:</b>	09:30 Local	<b>Type of Airspace:</b>	Class E

## Airport Information

<b>Airport:</b>	COEUR D'ALENE COE	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	2318 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	19	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	5400 ft / 75 ft	<b>VFR Approach/Landing:</b>	Full stop

## Wreckage and Impact Information

<b>Crew Injuries:</b>	2 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 None	<b>Latitude, Longitude:</b>	47.779365,-116.710456(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Anderson, Orrin
<b>Additional Participating Persons:</b>	JOHN BIANCO; SPOKANE , WA
<b>Original Publish Date:</b>	November 30, 2000
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=46443">https://data.nts.gov/Docket?ProjectID=46443</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).