



# Aviation Investigation Final Report

---

<b>Location:</b>	TALKEETNA, Alaska	<b>Accident Number:</b>	ANC99LA083
<b>Date &amp; Time:</b>	June 29, 1999, 16:30 Local	<b>Registration:</b>	N126KT
<b>Aircraft:</b>	Cessna TU206	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	5 None
<b>Flight Conducted Under:</b>	Part 135: Air taxi & commuter - Non-scheduled - Sightseeing		

---

## Analysis

In cruise flight, about 2,000 feet above ground level, the pilot noticed fuel flow fluctuations, followed by a total loss of engine power. He switched fuel tanks, and placed the mixture control to the FULL RICH position. The pilot kept the electric fuel pump activated, alternately placing the fuel boost pump switch in the HIGH position, and then the LOW position. The pilot described the engine as alternately running for a few seconds, then losing power. He determined the airplane would not reach the airport, so he performed a forced landing on an off airport gravel bar. Postaccident inspection revealed the right fuel tank was empty, and the left fuel tank contained about 25 gallons of fuel. The engine was started and operated normally. The Cessna U206 pilot operating manual states: 'To ensure a prompt engine restart in-flight after running a fuel tank dry, immediately switch to the tank containing fuel at the first indication of fuel pressure fluctuation and/or power loss. Then place the right half of the auxiliary fuel pump switch in the ON position momentarily (3 to 5 seconds) with the throttle at least 1/2 open. Excessive use of the ON position at high altitude and full rich mixture can cause flooding of the engine as indicated by a short (1 to 2 seconds) period of power followed by a loss of power. This can be detected by a fuel flow indication accompanied by a lack of power. If flooding does occur, turn off the auxiliary fuel pump switch, and normal propeller windmilling should start the engine in 1 to 2 seconds.'

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot not following emergency procedures, and improper use of the electric fuel boost pump, while attempting to restart the engine in flight. A factor associated with this accident was the inadequate fuel consumption calculations by the pilot.

## Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: CRUISE

### Findings

1. (F) FUEL CONSUMPTION CALCULATIONS - INADEQUATE - PILOT IN COMMAND
2. (C) FUEL BOOST PUMP SELECTOR POSITION - IMPROPER USE OF - PILOT IN COMMAND
3. (C) PROCEDURES/DIRECTIVES - NOT FOLLOWED - PILOT IN COMMAND

-----

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY DESCENT/LANDING

### Findings

4. TERRAIN CONDITION - SAND BAR

-----

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: EMERGENCY DESCENT/LANDING

### Findings

5. TERRAIN CONDITION - DIRT BANK/RISING EMBANKMENT

## Factual Information

On June 29, 1999, about 1630 Alaska daylight time, a Cessna TU206 airplane, N126KT, sustained substantial damage during a forced landing about four miles northwest of the Talkeetna Airport, Talkeetna, Alaska. The commercial pilot and the four passengers aboard were not injured. The airplane was being operated by K2 Adventures, Inc., of Talkeetna, under 14 CFR Part 135, as a local air tour flight. The flight departed Talkeetna at 1505. Visual meteorological conditions prevailed at the time of the accident, and a company VFR flight plan was filed.

The pilot told the NTSB investigator-in-charge (IIC) during a telephone interview on June 29, that the flight was about 14 miles northwest of the airport, in cruise flight at 2,000 feet above ground level. The pilot said he noticed fuel flow fluctuations, followed by a total loss of engine power. He stated that he switched the fuel selector valve handle to the left fuel tank position, and turned on the electric fuel boost pump. He said that he kept the electric fuel pump activated, alternately placing the fuel boost pump in the HIGH position, then the LOW position. The pilot indicated that he kept the mixture control in the FULL RICH position, and did not turn the electric boost pump switch to the OFF position. He described the engine as alternately running for a few seconds, and then losing power. The pilot determined he would not reach the airport, and selected an off airport gravel bar for a forced landing. The airplane touched down on the gravel, and came to rest on the river bank, damaging the underside of the fuselage.

The airplane was airlifted to the Talkeetna Airport on June 30, where it was inspected by a company mechanic and an FAA airworthiness inspector. The fuel selector valve handle was found selected to the left fuel tank position. The right fuel tank was empty, and the left fuel tank contained about 25 gallons of fuel. The engine was started and operated normally. The fuel boost pump operated in both the HIGH and LOW position. The fuel system was pressurized by the electric fuel boost pump with the engine not operating, and no fuel leaks were observed.

The Cessna U206G Pilot Operating Handbook, section 7, page 7-26, contains the following statement: "To ensure a prompt engine restart in-flight after running a fuel tank dry, immediately switch to the tank containing fuel at the first indication of fuel pressure fluctuation and/or power loss. Then place the right half of the auxiliary fuel pump switch in the ON position momentarily (3 to 5 seconds) with the throttle at least 1/2 open. Excessive use of the ON position at high altitude and full rich mixture can cause flooding of the engine as indicated by a short (1 to 2 seconds) period of power followed by a loss of power. This can be detected by a fuel flow indication accompanied by a lack of power. If flooding does occur, turn off the auxiliary fuel pump switch, and normal propeller windmilling should start the engine in 1 to 2 seconds."

## Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	52, Male
<b>Airplane Rating(s):</b>	Single-engine land; Single-engine sea	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Valid Medical-w/ waivers/lim	<b>Last FAA Medical Exam:</b>	June 28, 1999
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	2763 hours (Total, all aircraft), 139 hours (Total, this make and model), 2708 hours (Pilot In Command, all aircraft), 179 hours (Last 90 days, all aircraft), 104 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Cessna	<b>Registration:</b>	N126KT
<b>Model/Series:</b>	TU206 TU206	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	U20604967
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	6
<b>Date/Type of Last Inspection:</b>	May 7, 1999 100 hour	<b>Certified Max Gross Wt.:</b>	3600 lbs
<b>Time Since Last Inspection:</b>	73 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	4460 Hrs	<b>Engine Manufacturer:</b>	Continental
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	TSIO-520-M7
<b>Registered Owner:</b>	RUST AIR, INC.	<b>Rated Power:</b>	310 Horsepower
<b>Operator:</b>	K2 ADVENTURES, INC.	<b>Operating Certificate(s) Held:</b>	On-demand air taxi (135)
<b>Operator Does Business As:</b>		<b>Operator Designator Code:</b>	K2IC

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	TKA ,358 ft msl	<b>Distance from Accident Site:</b>	4 Nautical Miles
<b>Observation Time:</b>	15:53 Local	<b>Direction from Accident Site:</b>	140°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	/	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	0°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29 inches Hg	<b>Temperature/Dew Point:</b>	18°C / 9°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	, AK (TKA )	<b>Type of Flight Plan Filed:</b>	Company VFR
<b>Destination:</b>	(TKA )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	15:00 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>		<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>		<b>Runway Surface Condition:</b>	
<b>Runway Used:</b>	0	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	4 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	5 None	<b>Latitude, Longitude:</b>	62.449684,-149.790542(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Thomas, Matthew
<b>Additional Participating Persons:</b>	GRANT W CHAPMAN(FAA FSDO); ANCHORAGE , AK
<b>Original Publish Date:</b>	June 23, 2000
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=46712">https://data.nts.gov/Docket?ProjectID=46712</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).