

# **Aviation Investigation Final Report**

Location: MAMMOTH LAKES, California Accident Number: LAX99LA254

Date & Time: July 17, 1999, 13:17 Local Registration: N1692H

Aircraft: Piper PA32R-300 Aircraft Damage: Substantial

**Defining Event:** 2 None

Flight Conducted Under: Part 91: General aviation

### **Analysis**

The pilot added full fuel prior to departure. The AWOS (Automated Weather Observing System) reported the density altitude was 9,400 feet. He reviewed the procedures for a high altitude takeoff, completed an engine run up, and leaned for departure. After taxiing into position for takeoff, he applied the brakes then power. The runway was slightly uphill and the pilot did not feel the airplane was developing full power, but he did not abort the takeoff. The airplane climbed approximately 200 feet, but would not climb higher. After deciding an attempt to turn could induce a stall, the pilot lowered the landing gear and airspeed as much as possible. He maintained a controlled descent into the terrain and estimated his speed at touchdown was 50 to 60 knots. The pilot felt the density altitude prevented the airplane from climbing. The airport had an elevation of 7,128 feet msl (mean sea level). An aviation routine weather report (METAR) issued reported the temperature was 73 degrees Fahrenheit and the altimeter setting was 30.22 inHg.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to attain and maintain an adequate airspeed for the prevailing density altitude. The pilot's failure to abort the takeoff is also causal.

#### **Findings**

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: TAKEOFF - INITIAL CLIMB

#### **Findings**

- 1. AIRPORT FACILITIES, RUNWAY/LANDING AREA CONDITION UPHILL
- 2. PLANNING/DECISION INADEQUATE PILOT IN COMMAND
- 3. (F) WEATHER CONDITION HIGH DENSITY ALTITUDE
- 4. (C) AIRSPEED INADEQUATE PILOT IN COMMAND
- 5. (C) ABORTED TAKEOFF NOT PERFORMED PILOT IN COMMAND
- 6. STALL/MUSH ENCOUNTERED PILOT IN COMMAND

-----

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Page 2 of 6 LAX99LA254

#### **Factual Information**

On July 17, 1999, at 1317 hours Pacific daylight time, a Piper PA32R-300, N1692H, sustained substantial damage when it collided with terrain during the takeoff initial climb from the Mammoth Lakes, California, airport. The commercial pilot and his passenger were not injured. The airplane was owned and operated by the pilot under the provisions of 14 CFR Part 91 for a cross-country personal flight. The pilot departed Mammoth Lakes 3 to 4 minutes prior to the accident en route to Oxnard, California. Visual meteorological conditions prevailed and a VFR flight plan was filed, but not yet activated.

The pilot stated he flew into Mammoth Lakes the day before the accident. He was planning to fly to Oxnard and then on to Monterrey, California, where the airplane was based. He added full fuel prior to departure. The pilot listened to the AWOS (Automated Weather Observing System), which reported a density altitude of 9,400 feet. He reviewed the procedures for a high altitude takeoff, completed an engine run up, and leaned for departure. After taxiing into position for takeoff, he applied the brakes, then power. The pilot stated the runway was slightly uphill and he did not feel the airplane was developing full power, but did not abort the takeoff. The airplane climbed approximately 200 feet, but would not climb higher. After deciding an attempt to turn could induce a stall, the pilot lowered the landing gear and airspeed as much as possible. He maintained a controlled descent into the terrain and estimated his speed at touchdown was 50 to 60 knots.

The pilot said he felt the density altitude prevented the airplane from climbing. The airport facilities/directory indicated Mammoth Lakes had an elevation of 7,128 feet msl (mean sea level). An aviation routine weather report (METAR) issued for Mammoth Lakes at 1251 reported the temperature was 73 degrees Fahrenheit and the altimeter setting was 30.22 in Hg.

Page 3 of 6 LAX99LA254

#### **Pilot Information**

Certificate:	Commercial; Flight instructor	Age:	51,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	January 14, 1999
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1280 hours (Total, all aircraft), 12 hours (Total, this make and model), 972 hours (Pilot In Command, all aircraft), 12 hours (Last 90 days, all aircraft), 12 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Piper	Registration:	N1692H
Model/Series:	PA32R-300 PA32R-300	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	32R-7780177
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	February 19, 1999 Annual	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:	22 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3089 Hrs	Engine Manufacturer:	Lycoming
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	IO-540-KIG5D
Registered Owner:	MICHAEL L. PHILLIPS	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 4 of 6 LAX99LA254

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MMH ,7128 ft msl	Distance from Accident Site:	
Observation Time:	12:51 Local	Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	11 knots / 14 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	200°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	23°C / -1°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	(MMH)	Type of Flight Plan Filed:	VFR
Destination:	OXNARD , CA (OXR)	Type of Clearance:	VFR
Departure Time:	13:13 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	MAMMOTH LAKES MMH	Runway Surface Type:	Asphalt
Airport Elevation:	7128 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	7000 ft / 100 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	37.580505,-118.840583(est)

Page 5 of 6 LAX99LA254

#### **Administrative Information**

Investigator In Charge (IIC): Plagens, Howard

Additional Participating Persons:

Original Publish Date: August 14, 2001

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=46810

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 LAX99LA254