



# Aviation Investigation Final Report

---

<b>Location:</b>	JETMORE, Kansas	<b>Accident Number:</b>	CHI99LA257
<b>Date &amp; Time:</b>	July 27, 1999, 17:30 Local	<b>Registration:</b>	N88007
<b>Aircraft:</b>	Schweizer 269C	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

---

## Analysis

The pilot said he was going to practice an auto rotation. He said he '...rolled the throttle back to idle position and dropped the collective...[and]noted a red light on the dash and could hear the engine had quit running.' He said the subsequent auto rotation '...terminated in a hard landing.' The on-scene investigation revealed flight and powerplant control operational continuity and fuel in the accident helicopter's fuel tanks. The engine was test run and its low idle was 1,300 rpm. According to a representative from a company that maintains and rebuilds helicopters like that of the accident helicopter, '...it is possible for an engine to die when a rapid roll-off of [the] throttle is accomplished and too low an idle RPM setting exists.' The FAA Approved Flight Manual said that the pilot should 'Split the needles by lowering the collective while maintaining throttle setting. The throttle correlation will establish a high idle RPM (approximately 2500 RPM) and will prevent the engine from loading up or stalling on recovery.'

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's use of improper procedures by not following the helicopter manufacturer's recommended engine RPM reduction procedures during autorotations. A factor was the pilot not attaining the proper rotor RPM during the autorotation practice.

## Findings

---

Occurrence #1: LOSS OF ENGINE POWER

Phase of Operation: DESCENT

### Findings

1. AUTOROTATION - INTENTIONAL - PILOT IN COMMAND
2. (C) PROCEDURES/DIRECTIVES - IMPROPER - PILOT IN COMMAND
3. (F) ROTOR RPM - NOT ATTAINED - PILOT IN COMMAND
4. REMEDIAL ACTION - ATTEMPTED - PILOT IN COMMAND

-----

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING

### Findings

5. TERRAIN CONDITION - GROUND

## Factual Information

On July 27, 1999, at 1730 central daylight time (cdt), a Schweizer 269C, N88007, piloted by a private pilot, was substantially damaged when it collided with the ground during a pilot described practice auto rotation. Visual meteorological conditions prevailed at the time of the accident. The 14 CFR Part 91 personal flight was not operating on a flight plan. The pilot reported no injuries. The flight departed Hayes, Kansas, at 1645 cdt.

The pilot said he "...climbed [the helicopter] to between 3500 and 3600 feet, turned the helicopter straight west into the wind and rolled the throttle back to idle position and dropped the collective. Immediately upon doing so, I noted a red light on the dash and could hear the engine had quit running. When I looked at the engine RPMs, I could see it was at zero." The pilot said the auto rotation "...terminated in a hard landing."

According to the Federal Aviation Administration Principal Maintenance Inspector (PMI) who spoke with the pilot, N88007's pilot told him that he performs auto rotations with engine operating at 2,000 rpm. The PMI said the pilot stated the engine stopped running at the 2,000 rpm indication. The PMI reported continuity and operation to the factory limits was established for the flight and powerplant controls. The engine was started and its lowest idle rpm was 1,300. The magnetos check revealed the rpm drop was within the manufacturer's specifications.

The PMI said a blue colored liquid, similar to 100LL AVGAS was found in N88007's fuel tanks. The pilot said he departed Hayes, Kansas, with full fuel, 49 gallons, and had flown about 30 minutes before the engine stopped running. The pilot said he had filled N88007's fuel tanks at Hayes, Kansas.

A representative from a company who maintains and rebuilds helicopters and has experience with the accident helicopter's type said, "...it is possible for an engine to die when a rapid roll off of [the] throttle is accomplished and too low an idle RPM setting exists." According to the FAA Approved Flight Manual (AFM), the section entitled, "Practice Autorotations," the pilot is to "Split the needles by lowering the collective while maintaining throttle setting. The throttle correlation will establish a high idle RPM (approximately 2500 RPM) and will prevent the engine from loading up or stalling on recovery." An excerpt from the AFM addressing this procedure is appended to this report.

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	44, Male
<b>Airplane Rating(s):</b>	None	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 Valid Medical--no waivers/lim.	<b>Last FAA Medical Exam:</b>	November 16, 1998
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	850 hours (Total, all aircraft), 645 hours (Total, this make and model), 445 hours (Pilot In Command, all aircraft), 65 hours (Last 90 days, all aircraft), 23 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Schweizer	<b>Registration:</b>	N88007
<b>Model/Series:</b>	269C 269C	<b>Aircraft Category:</b>	Helicopter
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	S1546
<b>Landing Gear Type:</b>	Skid	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	July 7, 1999 AAIP	<b>Certified Max Gross Wt.:</b>	2150 lbs
<b>Time Since Last Inspection:</b>	8 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	907 Hrs	<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	Not installed	<b>Engine Model/Series:</b>	H10-360-D1A
<b>Registered Owner:</b>	SILVER HAWK SECURITY, INC.	<b>Rated Power:</b>	190 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	None
<b>Operator Does Business As:</b>		<b>Operator Designator Code:</b>	

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	DCC ,2594 ft msl	<b>Distance from Accident Site:</b>	25 Nautical Miles
<b>Observation Time:</b>	17:56 Local	<b>Direction from Accident Site:</b>	190°
<b>Lowest Cloud Condition:</b>	Scattered / 8000 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	10 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	200°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29 inches Hg	<b>Temperature/Dew Point:</b>	36°C / 17°C
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	HAYES , KS (HYS)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>		<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	16:45 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>		<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>		<b>Runway Surface Condition:</b>	
<b>Runway Used:</b>	0	<b>IFR Approach:</b>	
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	38.080951,-99.889755(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Gattolin, Frank
<b>Additional Participating Persons:</b>	JAMES D BADHORSE; WICHITA , KS
<b>Original Publish Date:</b>	January 18, 2001
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=46900">https://data.nts.gov/Docket?ProjectID=46900</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).