



Aviation Investigation Final Report

| | | | |
|--------------------------------|------------------------------|-------------------------|-------------|
| Location: | LONG BEACH, California | Accident Number: | LAX99LA284 |
| Date & Time: | August 26, 1999, 13:33 Local | Registration: | N5224R |
| Aircraft: | Aerospatiale AS350B3 | Aircraft Damage: | Substantial |
| Defining Event: | | Injuries: | 2 None |
| Flight Conducted Under: | Part 91: General aviation | | |

Analysis

The pilot reported that a linesman directed him toward the center one of three transient parking helipads next to a small perimeter fence. All three helipads were empty. As he approached the pad, the pilot became concerned about obstructions and about exposing his tail rotor to a taxiway beyond his view. He performed a left pedal turn over the pad to bring the nose around to face the taxiway. He reported that the linesman made a 'hands-down motion' and walked away. The pilot assumed he was clear to touchdown. As he touched down, the tail rotor contacted the helipad's perimeter fence. The nose of the helicopter yawed left and the pilot performed a hovering autorotation. The tail rotor blades were destroyed and the tail boom was buckled. The distance from the center of the helipad parking space to the fence was measured at 23 feet. The distance from the main rotor mast to the end of the tail stinger on the AS350B3 is just over 23 feet. According to the parking space requirements outlined by FAA A/C 150/5390-2A, the fence was supposed to be no closer than 10 feet to any part of the helicopter. The fence was found to be within the tail rotor clearance area specified in the Advisory Circular. There was insufficient room for the helicopter to make a 180-degree turn, assuming it stayed on the center point of the parking space.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The failure of the pilot to maintain clearance with the fence while landing. A factor was the failure of the helipad to meet the obstacle clearance design criteria specified in FAA Advisory Circular guidance.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: TAXI - AERIAL

Findings

1. OBJECT - FENCE
2. (C) CLEARANCE - NOT MAINTAINED - PILOT IN COMMAND
3. (F) AIRPORT FACILITIES, HELIPAD - INADEQUATE
4. (F) PROCEDURES/DIRECTIVES - NOT COMPLIED WITH - AIRPORT PERSONNEL

Factual Information

On August 26, 1999, at 1333 hours Pacific daylight time, an Aerospatiale AS350B3, N5224R, collided with a fence while landing at the Long Beach, California, airport. The helicopter, operated by American Eurocopter, Grand Prairie, Texas, was substantially damaged. The commercial pilot and commercial rated passenger were not injured. The local area business flight was conducted under the provisions of 14 CFR Part 91 and originated from the Van Nuys, California, Airport, about 1235, and made a planned stop at a private heliport in Los Angeles before continuing to Long Beach. Visual meteorological conditions prevailed and no flight plan was filed.

In a written statement, the pilot reported that he had planned to park the helicopter on a pad in front of a fixed-base operator (FBO). He reported that the air traffic controller directed him to land on runway 7 and air taxi to the FBO. Upon reaching the FBO's ramp, a linesman directed the pilot toward the center of three helipads next to a small fence that bordered the western perimeter of the ramp. All three pads were empty. The pilot reported that as he approached the pad he became concerned that his tail rotor was exposed to a taxiway which was out of his view. Additionally, there were two large semi-tractor trailers parked south of the helipad which the pilot felt would obstruct the view of any aircraft taxiing out of the south end hangar. Because of these obstructions, the pilot initiated a left pedal turn over the pad to bring the nose of the helicopter around to face the taxiway. The pilot reported that he looked to the linesman for further landing guidance. The linesman made a "hands-down motion" and started to walk away. The pilot stated that he interpreted the linesman's signal to mean that he was clear to touchdown. As he landed, he felt a slight impact followed by a series of vibrations. The nose of the helicopter began to yaw left. The pilot reported that he immediately lowered the collective and reduced the power; he had no tail rotor control at that time.

The pilot instructed his passenger to remain in the helicopter until he could ensure that the area was clear. He performed a normal engine shutdown. As he exited the helicopter, he discovered that the tail rotor had struck the short chain link fence behind the aircraft. The tail rotor blades were destroyed and about 3 inches of the blade tips were broken off. One piece impacted the exhaust stack and went into the engine. The tailboom was buckled.

A representative from American Eurocopter submitted a drawing of the helipad displaying the measurements of the perimeter and the pad's location in relation to the fence. The pad, as defined by the painted border stripes, was 36 feet by 35 feet, which would generate a radius comparable to approximately 17 1/2 feet. The distance from the center of the "H" to the fence line was shown as 23 feet, and the distance from the nearest pad border of the helipad to the fence was 5 1/2 feet. According to American Eurocopter, the main rotor diameter of the AS350B3 helicopter is 35 feet and the distance from the center of the main rotor mast to the end of the tail stinger is just over 23 feet.

The parking space dimensions were reviewed for compliance with Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5390-2A, issued in 1994. The application of the measurements to the FAA criteria revealed that the fence, at 23 feet from the center point of the helicopter parking space, was within the tail rotor clearance area. Pertinent portions of the Advisory Circular and the helicopter dimensions are appended to this file.

Pilot Information

| | | | |
|----------------------------------|---|--|---------------|
| Certificate: | Commercial; Flight instructor; Private | Age: | 44, Male |
| Airplane Rating(s): | Single-engine land; Multi-engine land | Seat Occupied: | Right |
| Other Aircraft Rating(s): | Helicopter | Restraint Used: | |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | Helicopter | Toxicology Performed: | No |
| Medical Certification: | Class 2 Valid Medical-w/ waivers/lim | Last FAA Medical Exam: | July 29, 1999 |
| Occupational Pilot: | Yes | Last Flight Review or Equivalent: | |
| Flight Time: | 2882 hours (Total, all aircraft), 177 hours (Total, this make and model), 2574 hours (Pilot In Command, all aircraft), 3 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft) | | |

Aircraft and Owner/Operator Information

| | | | |
|--------------------------------------|--------------------------|---------------------------------------|----------------|
| Aircraft Make: | Aerospatiale | Registration: | N5224R |
| Model/Series: | AS350B3 AS350B3 | Aircraft Category: | Helicopter |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 2968 |
| Landing Gear Type: | Skid | Seats: | 6 |
| Date/Type of Last Inspection: | August 1, 1999 100 hour | Certified Max Gross Wt.: | 4961 lbs |
| Time Since Last Inspection: | 13 Hrs | Engines: | 1 Turbo shaft |
| Airframe Total Time: | 812 Hrs | Engine Manufacturer: | Turbomeca |
| ELT: | Installed, not activated | Engine Model/Series: | ARRIEL 2B |
| Registered Owner: | ROBERT'S AIRCRAFT | Rated Power: | 847 Horsepower |
| Operator: | AMERICAN EUROCOPTER | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |

Meteorological Information and Flight Plan

| | | | |
|---|----------------------------------|---|-------------|
| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
| Observation Facility, Elevation: | LGB ,57 ft msl | Distance from Accident Site: | |
| Observation Time: | 21:56 Local | Direction from Accident Site: | |
| Lowest Cloud Condition: | Scattered / 8000 ft AGL | Visibility | 10 miles |
| Lowest Ceiling: | Broken / 25000 ft AGL | Visibility (RVR): | |
| Wind Speed/Gusts: | 5 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 100° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 29 inches Hg | Temperature/Dew Point: | 32°C / 17°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | VAN NUYS , CA (VNY) | Type of Flight Plan Filed: | None |
| Destination: | (LGB) | Type of Clearance: | VFR |
| Departure Time: | 12:35 Local | Type of Airspace: | Class D |

Airport Information

| | | | |
|-----------------------------|------------------|----------------------------------|-----------|
| Airport: | LONG BEACH LGB | Runway Surface Type: | Asphalt |
| Airport Elevation: | 57 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 7R | IFR Approach: | None |
| Runway Length/Width: | 5420 ft / 150 ft | VFR Approach/Landing: | Full stop |

Wreckage and Impact Information

| | | | |
|----------------------------|--------|-----------------------------|---------------------------|
| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
| Passenger Injuries: | 1 None | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 2 None | Latitude, Longitude: | 33.78973,-118.120185(est) |

Administrative Information

| | |
|--|---|
| Investigator In Charge (IIC): | Mars, Noelani |
| Additional Participating Persons: | RICK STOCKTON; LONG BEACH , CA |
| Original Publish Date: | August 14, 2001 |
| Last Revision Date: | |
| Investigation Class: | Class |
| Note: | |
| Investigation Docket: | https://data.nts.gov/Docket?ProjectID=47232 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).