



Aviation Investigation Final Report

Location: GLENNALLEN, Alaska Accident Number: ANC00LA012

Date & Time: November 7, 1999, 15:00 Local Registration: N8145D

Aircraft: Piper PA-22-160 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The certificated private pilot had just departed from a portion of the Glenn Highway when he remembered that he had forgotten the keys to his car that was parked at his destination airport. He elected to return, and while taxiing to the parking area, he applied the brakes, and both main wheels slid on the snow-covered highway. He said that when the left main wheel contacted a patch of dry pavement, the airplane veered to the left, collided with a drainage ditch, and nosed over. The airplane sustained substantial damage to the wings, left lift-strut, and empennage. The pilot noted that there were no preaccident mechanical anomalies with the airplane.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control during landing. A factor associated with the accident was snow-covered terrain.

Findings

Occurrence #1: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) TERRAIN CONDITION - SNOW COVERED

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #3: NOSE OVER

Phase of Operation: LANDING - ROLL

Page 2 of 6 ANC00LA012

Factual Information

On November 7, 1999, about 1500 Alaska standard time, a wheel equipped Piper PA-22-160 airplane, N8145D, sustained substantial damage after landing on the Glenn Highway, about 20 miles west of Glennallen, Alaska, at latitude 62 degrees, 03 minutes north, and longitude 146 degrees, 27 minutes west. The airplane was being operated as a visual flight rules (VFR) personal flight under Title 14, CFR Part 91, when the accident occurred. The private pilot/airplane owner was not injured. Visual meteorological conditions prevailed, and no flight plan was filed.

During a telephone conversation with the National Transportation Safety Board (NTSB) investigator-in-charge on November 9, the pilot reported that he had just departed from a portion of the Glenn Highway when he remembered that he had forgotten the keys to his car that was parked at the Glennallen Airport, his intended destination. He stated that he elected to return, and while taxiing to his parking area, he applied the brakes, and both main wheels slid on the snow-covered highway. He said that when the left main wheel contacted a patch of dry pavement, the airplane veered to the left, collided with a drainage ditch, and nosed over.

The airplane sustained substantial damage to the wings, left lift-strut, and empennage.

The pilot noted that there were no preaccident mechanical anomalies with the airplane.

Pilot Information

Certificate:	Private	Age:	40,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	August 22, 1997
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	119 hours (Total, all aircraft), 76 hours (Total, this make and model), 82 hours (Pilot In Command, all aircraft), 10 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 6 ANC00LA012

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N8145D
Model/Series:	PA-22-160 PA-22-160	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	22-5636
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	October 30, 1998 Annual	Certified Max Gross Wt.:	2000 lbs
Time Since Last Inspection:	25 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3289 Hrs	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	O-320-B2A
Registered Owner:	RUSSELL L. JINDRA	Rated Power:	160 Lbs thrust
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PAG ,1579 ft msl	Distance from Accident Site:	22 Nautical Miles
Observation Time:	14:53 Local	Direction from Accident Site:	70°
Lowest Cloud Condition:	Scattered / 3000 ft AGL	Visibility	50 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	-13°C / -14°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:	(3Z5)	Type of Clearance:	None
Departure Time:	14:30 Local	Type of Airspace:	Class G

Page 4 of 6 ANC00LA012

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	62.099533,-145.530715(est)

Page 5 of 6 ANC00LA012

Administrative Information

Investigator In Charge (IIC):	Johnson, Clinton	
Additional Participating Persons:	PAUL R RAKER (FAA); ANCHORAGE , AK	
Original Publish Date:	May 17, 2001	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=47768	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC00LA012