



Aviation Investigation Final Report

Location: RUBY, Alaska Accident Number: ANC87LA022

Date & Time: December 22, 1986, 12:15 Local Registration: N734WE

Aircraft: CESSNA 206 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT STATED THAT DURING THE LANDING ROLL ON THE FROZEN RIVER, HE LOST CONTROL OF THE AIRCRAFT CAUSING THE AIRCRAFT TO GROUND LOOP.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) TERRAIN CONDITION - ICY

- 2. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA NOT IDENTIFIED PILOT IN COMMAND
- 3. (C) DIRECTIONAL CONTROL NOT MAINTAINED PILOT IN COMMAND
- 4. (C) GROUND LOOP/SWERVE INADVERTENT PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Airline transport	Age:	37,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	February 27, 1986
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	8500 hours (Total, all aircraft), 2600 hours (Total, this make and model), 8200 hours (Pilot In Command, all aircraft), 75 hours (Last 90 days, all aircraft), 23 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Page 2 of 5 ANC87LA022

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N734WE
Model/Series:	206 206	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Utility	Serial Number:	U20604883
Landing Gear Type:	Tricycle	Seats:	6
Date/Type of Last Inspection:	June 13, 1986 Annual	Certified Max Gross Wt.:	3500 lbs
Time Since Last Inspection:	200 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1950 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	10-520
Registered Owner:	JOSEPH MATTIE	Rated Power:	285 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	100 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	300°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	-23°C / -7°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	11:30 Local	Type of Airspace:	Class G

Page 3 of 5 ANC87LA022

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	65.030113,-154.910736(est)

Page 4 of 5 ANC87LA022

Administrative Information

Investigator In Charge (IIC):	Michelangelo, James
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=4814

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC87LA022