



# **Aviation Investigation Final Report**

Location: KING SALMON, Alaska Accident Number: ANC87LA078

Date & Time: June 11, 1987, 10:30 Local Registration: N98EL

Aircraft: de Havilland DHC-2 Aircraft Damage: Substantial

**Defining Event:** Injuries: 6 None

Flight Conducted Under: Part 91: General aviation

### **Analysis**

THE PILOT STATED THAT HE STARTED HIS TAKEOFF RUN IN THE MIDDLE OF THE LAKE. THE AIRCRAFT OVERRAN THE LAKE AND ENDED UP ON THE TUNDRA APPROXIMATELY 75 YARDS FROM THE LAKE SHORE.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

### **Findings**

Occurrence #1: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: TAKEOFF - ROLL/RUN

#### **Findings**

1. (F) TERRAIN CONDITION - WATER, GLASSY

- 2. (C) PERFORMANCE DATA NOT UNDERSTOOD PILOT IN COMMAND
- 3. (C) ALL AVAILABLE RUNWAY NOT USED PILOT IN COMMAND
- 4. (C) AIRSPEED NOT OBTAINED PILOT IN COMMAND
- 5. (C) LIFT-OFF NOT OBTAINED PILOT IN COMMAND

## **Factual Information**

#### **Pilot Information**

Certificate:	Commercial	Age:	50,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	May 26, 1987
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	6312 hours (Total, all aircraft), 2600 hours (Total, this make and model), 6200 hours (Pilot In Command, all aircraft), 112 hours (Last 90 days, all aircraft), 40 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Page 2 of 5 ANC87LA078

### **Aircraft and Owner/Operator Information**

Aircraft Make:	de Havilland	Registration:	N98EL
Model/Series:	DHC-2 DHC-2	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	826
Landing Gear Type:	Float	Seats:	6
Date/Type of Last Inspection:	May 20, 1987 Annual	Certified Max Gross Wt.:	5100 lbs
Time Since Last Inspection:	26 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	14680 Hrs	Engine Manufacturer:	P&W
ELT:	Installed, activated, aided in locating accident	Engine Model/Series:	R-985
Registered Owner:	ALASKA ENCHANTED LAKE LODGE	Rated Power:	450 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	30 miles
Lowest Ceiling:	Overcast / 8000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	11°C / 4°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Page 3 of 5 ANC87LA078

### **Airport Information**

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

### Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	5 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	6 None	Latitude, Longitude:	58.749633,-156.539962(est)

Page 4 of 5 ANC87LA078

#### **Administrative Information**

Investigator In Charge (IIC): Michelangelo, James

Additional Participating
Persons:

Original Publish Date: May 2, 1988

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=4856

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC87LA078