



Aviation Investigation Final Report

Location: DILLINGHAM, Alaska Accident Number: ANC87LA093

Date & Time: July 11, 1987, 12:00 Local Registration: N1304H

Aircraft: AERONCA 15AC Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE STUDENT PILOT STATED THAT THE AIRCRAFT LOST PARTIAL POWER DURING THE TAKE OFF RUN DUE TO WATER BEING INGESTED INTO THE ENGINE AIR FILTER AS HE MADE HIS WATER TAKEOFF. HE ELECTED TO CONTINUE WITH THE TAKEOFF ATTEMPT AND STRUCK THE SHORELINE PRIOR TO BECOMING AIRBORNE. THE AIRCRAFT WAS SUBSTANTIALLY DAMAGED, BUT NEITHER THE PILOT NOR HIS PASSENGER WERE INJURED. HE SAID THAT HE LAST TOOK FORMALIZED FLIGHT INSTRUCTION IN 1965.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(PARTIAL) - NONMECHANICAL

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. (F) INDUCTION AIR CONTROL, AIR FILTER/SCREEN - WATER

2. (C) PREFLIGHT PLANNING/PREPARATION - POOR - PILOT IN COMMAND

3. (F) MAINTENANCE, SERVICE OF AIRCRAFT/EQUIPMENT - IMPROPER - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: TAKEOFF - ROLL/RUN

Page 2 of 5 ANC87LA093

Factual Information

Pilot Information

Certificate:	Student	Age:	58,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Expired	Last FAA Medical Exam:	May 2, 1985
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1341 hours (Total, all aircraft), 1071 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	AERONCA	Registration:	N1304H
Model/Series:	15AC 15AC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	15AC330
Landing Gear Type:	Float	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2050 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O-360-AIA
Registered Owner:	HENRY E SHADE	Rated Power:	180 Horsepower
Operator:	HENRY SHADE	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 ANC87LA093

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	DLG ,85 ft msl	Distance from Accident Site:	3 Nautical Miles
Observation Time:	13:50 Local	Direction from Accident Site:	280°
Lowest Cloud Condition:	Scattered / 3500 ft AGL	Visibility	30 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	150°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	17°C / 8°C
Precipitation and Obscuration:	No Obscuration; No Precipita	tion	
Departure Point:	DILLINGHAM , AK (023)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	12:00 Local	Type of Airspace:	

Airport Information

Airport:	SHANNON'S POND 023	Runway Surface Type:	Water
Airport Elevation:	80 ft msl	Runway Surface Condition:	Water-calm
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	1400 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	58.819351,-157.860183(est)

Page 4 of 5 ANC87LA093

Administrative Information

Investigator In Charge (IIC): La belle, James

Additional Participating
Persons:

Original Publish Date: May 9, 1988

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=4869

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC87LA093