



Aviation Investigation Final Report

Location: CHARLEY RIVER, Alaska Accident Number: ANC87LA104

Date & Time: July 22, 1987, 13:45 Local Registration: N1023H

Aircraft: AERONCA 15AC Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT STATED THAT DURING THE TAKEOFF ROLL HE STRUCK A HIDDEN TREE STUMP; HE LOST DIRECTIONAL CONTROL OF THE AIRCRAFT CAUSING THE PLANE TO NOSE OVER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. (F) TERRAIN CONDITION - HIGH OBSTRUCTION(S)

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

3. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA - SELECTED - PILOT IN COMMAND

.

Occurrence #2: NOSE OVER

Phase of Operation: TAKEOFF - ROLL/RUN

Factual Information

Pilot Information

Certificate:	Private	Age:	39,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	February 18, 1987
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	133 hours (Total, all aircraft), 48 hours (Total, this make and model), 45 hours (Pilot In Command, all aircraft), 47 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft), 7 hours (Last 24 hours, all aircraft)		

Page 2 of 5 ANC87LA104

Aircraft and Owner/Operator Information

Aircraft Make:	AERONCA	Registration:	N1023H
Model/Series:	15AC 15AC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	15AC23
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	April 1, 1987 Unknown	Certified Max Gross Wt.:	2050 lbs
Time Since Last Inspection:	45 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2479 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated, aided in locating accident	Engine Model/Series:	C-145
Registered Owner:	ARTHUR D. HIRSCHEL	Rated Power:	145 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Weteorological illionilati	on and ingite i lan		
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	50 miles
Lowest Ceiling:	Overcast / 6000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	10°C / -1°C
Precipitation and Obscuration:	No Obscuration; No Precipi	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Page 3 of 5 ANC87LA104

Airport Information

Airport:		Runway Surface Type:	Dirt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Soft
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Page 4 of 5 ANC87LA104

Administrative Information

Investigator In Charge (IIC): Michelangelo, James

Additional Participating
Persons:

Original Publish Date: May 9, 1988

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=4877

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC87LA104