

Aviation Investigation Final Report

Location:	HUNTER, Oklahoma		Accident Number:	FTW00LA132
Date & Time:	April 26, 2000, 13:50	Local	Registration:	N76176
Aircraft:	Cessna	140	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General avia	tion - Personal		

Analysis

While en route, following a decrease of oil pressure, the pilot shut down the engine. During the forced landing flare/touchdown in the field, the main landing gear struck a fence and the airplane nosed over. At the site, oil was found covering the lower surface of the airplane from the engine cowling to the empennage, and the oil cap was not found. The engine and aircraft manufacturers did not have any record where a secured oil cap came off in flight. The aircraft representative stated that if the 'tabs inside the filler cap became corroded completely through, they would not retain the cap properly.' A mechanic, who recovered the airplane from the field, stated that the oil cap was not found, and he noticed no discrepancies or rust on the oil filler neck. The manufacturer's preflight checklist states in part: 'Check oil level.' The operating details states in part: 'In replacing the cap, make sure that it is on firmly and turned all the way to the stop at the right to prevent loss of oil through the filler neck.'

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate preflight resulting in the loss of the oil cap and subsequent loss of engine oil. A factor was the lack of suitable terrain for the landing.

Findings

Occurrence #1: MISCELLANEOUS/OTHER Phase of Operation: CRUISE Findings

1. (C) LUBRICATING SYSTEM,OIL FILLER CAP - MISSING 2. (C) AIRCRAFT PREFLIGHT - INADEQUATE - PILOT IN COMMAND 3. FLUID,OIL - LOSS,PARTIAL

Occurrence #2: FORCED LANDING Phase of Operation: EMERGENCY DESCENT/LANDING

Occurrence #3: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings 4. (F) TERRAIN CONDITION - NONE SUITABLE 5. TERRAIN CONDITION - CROP 6. OBJECT - FENCE

Occurrence #4: NOSE OVER Phase of Operation: LANDING - ROLL

Factual Information

On April 26, 2000, at 1350 central daylight time, a Cessna 140, single-engine airplane, N76176, struck a fence during a forced landing following a loss of oil pressure near Hunter, Oklahoma. The airplane was owned and operated by the private pilot. The private pilot, sole occupant, was not injured, and the airplane sustained substantial damage. Visual meteorological conditions prevailed for the cross-country flight, and a flight plan was not filed. The 14 Code of Federal Regulations Part 91 personal flight departed Justin, Texas, at 1020, with a planned destination of Des Moines, Iowa.

The pilot reported on the Pilot/Operator Aircraft Accident Report (NTSB Form 6120.1/2) that the flight was en route when the oil pressure started to decrease. The pilot shut down the engine and picked a field for the landing. Prior to the touchdown, the pilot saw a fence in the center of the field. The main landing gear struck the fence, and the airplane flipped to the inverted position.

The FAA inspector responding to the accident site found the airplane (36 degrees 33 minutes north; 097 degrees 24 minutes west) approximately 50 feet north of the fence. The inspector and the pilot found oil covering the lower surface of the airplane from the engine cowling to the empennage. The FAA inspector stated that the "oil cap was not found at the site." The pilot stated that he thought the oil cap was on during the preflight and came off in-flight. Structural damage was found at the engine mount, right wing strut, and the vertical stabilizer.

On the Pilot/Operator Aircraft Accident Report (NTSB Form 6120.1/2), the pilot stated that the oil cap was lost in flight. He recommended "safety A.D. [airworthiness directive] on all oil caps."

The pilot reported to the NTSB investigator-in-charge that the oil cap did not have a retainer safety chain. He stated that he had put the oil cap on this make and model of aircraft hundreds of times in his history of flying.

The Teledyne Continental engine and Cessna Aircraft Company representatives reported that the manufacturers did not have any history where a secured oil cap came off in flight. The aircraft representative further stated that if the "tabs inside the filler cap became corroded completely through, they would not retain the cap properly."

A mechanic, who recovered the airplane from the field, stated that the oil cap was not found. He further stated that he did notice any discrepancies or rust on the oil filler neck.

The manufacturer's preflight checklist states in part: A. BEFORE ENTERING THE AIRPLANE (1) Check oil level. The operating details states in part: Oil Level: The quantity can be checked

easily by raising the hood on the right side and reading the quantity in the sump directly on the stick attached to the oil tank cap. In replacing the cap, make sure that it is on firmly and turned all the way to the stop at the right to prevent loss of oil through the filler neck.

Pilot Information

Certificate:	Private	Age:	67,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 6, 2000
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1000 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N76176
Model/Series:	140 140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	10573
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	1495 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Continental
ELT:	Installed	Engine Model/Series:	C-90-12F
Registered Owner:	GILBERT E. JOHNSON	Rated Power:	90 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipitat	tion	
Departure Point:	JUSTIN , TX (NONE)	Type of Flight Plan Filed:	None
Destination:	DES MOINES , IA (DSM)	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class E

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	Vegetation
Runway Used:	0	IFR Approach:	
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	36.559967,-97.660095(est)

Administrative Information

Investigator In Charge (IIC):	Roach, Joyce
Additional Participating Persons:	ROBERT E SHOOK; OKLAHOMA CITY, OK
Original Publish Date:	July 17, 2001
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	The NTSB traveled to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=49075

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.