



# Aviation Investigation Final Report

---

<b>Location:</b>	PATTERSON, Louisiana	<b>Accident Number:</b>	FTW00LA153
<b>Date &amp; Time:</b>	May 24, 2000, 10:25 Local	<b>Registration:</b>	N350JG
<b>Aircraft:</b>	Eurocopter AS350B2	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	2 Minor
<b>Flight Conducted Under:</b>	Part 135: Air taxi & commuter - Non-scheduled		

---

## Analysis

The helicopter was in level flight at 1,000 feet msl, when the pilot felt a thump and a yaw. He moved the anti-torque pedals; however, there was no "tail rotor response." A pilot from another helicopter confirmed that the tail rotor was still turning. The pilot reported that he reviewed the emergency procedure for tail rotor failure and flew the helicopter to a nearby airport. The pilot stated that he maintained about 70 knots indicated airspeed and pressed the "HYD" test button for 5 seconds, then returned it to the normal position, as called for in the procedure. The pilot also reported that at this time he turned off the warning horn which alerts the pilot of low main rotor rpm or loss of hydraulic pressure. He completed three shallow approaches to burn off fuel and to see how the helicopter would respond to control movements. While turning left to downwind, during the fourth go-around, the pilot was having trouble controlling the left yaw when he realized the helicopter's hydraulic system had failed. The pilot initiated an autorotation downwind and instructed the passenger to "pull the [fuel flow control] lever off." When the helicopter touched down, "it slid with a yaw left and flipped over coming to rest on its left side." Examination of the cockpit revealed that the console hydraulic test switch (located next to the horn switch) was pressed in (hydraulics off). According to the manufacturer, the hydraulic test switch cuts off hydraulic power; however, the pilot would not lose control assist until the accumulators were depleted. The horn switch was not pressed in (warning horn deactivated, for the horn to function, the switch has to be pressed in). Post accident testing of the hydraulic system revealed no anomalies. Examination of the tail rotor system revealed that the spider bearing inner race was cut through the rotating housing. Examination of the tail rotor spider revealed that the bearing seal exhibited heat damage, and the bearing would not rotate due to small pieces of cage material loose in between the inner and outer races. No evidence of lubrication was present on the race or balls.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the failure of the tail rotor spider bearing, the pilot's failure to follow the proper emergency procedures as stated in the helicopter's checklist by not performing a run-on landing, and the inadvertent deactivation of the hydraulic system.

### Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION

Phase of Operation: CRUISE

#### Findings

1. (C) ROTOR SYSTEM, TAIL ROTOR HUB PITCH CHANGE MECHANISM - FAILURE
2. (C) HYDRAULIC SYSTEM - INADVERTENT DEACTIVATION - PILOT IN COMMAND
3. (C) CHECKLIST - NOT FOLLOWED - PILOT IN COMMAND
4. RUN ON LANDING - NOT PERFORMED - PILOT IN COMMAND
5. AUTOROTATION - INITIATED - PILOT IN COMMAND

-----

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

-----

Occurrence #3: ROLL OVER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

## Factual Information

On May 24, 2000, at 1025 central daylight time, a Eurocopter AS350B2 helicopter, N350JG, was substantially damaged during an emergency landing at the Harry P Williams Memorial Airport, Patterson, Louisiana. The helicopter was registered to the First Security Bank NA Trustee, and operated by Tex Air of Houston, Texas. The commercial pilot and his only passenger sustained minor injuries. Visual meteorological conditions prevailed, and a company flight plan was filed for the 14 Code of Federal Regulations Part 135 nonscheduled air taxi flight. The flight originated from Morgan City, Louisiana, at 0925, with a destination of Eugene Island 307B platform in the Gulf of Mexico.

The pilot reported that the helicopter was in level flight at 1,000 feet msl, when he felt a thump and a yaw. He moved the anti-torque pedals; however, there was no "tail rotor response." The pilot contacted another helicopter pilot in the area and requested that he visually confirm that the tail rotor was still operating. The pilot confirmed that the tail rotor was still turning. The pilot further reported that he reviewed the emergency procedure and flew the helicopter to the Harry P Williams Memorial Airport (PTN). He added that he was in contact with representatives from American Eurocopter during the flight to PTN. He stated that he maintained about 70 knots indicated airspeed and pressed the "HYD" test button for 5 seconds, then returned it to the normal position (this procedure relieves accumulator pressure and helps center the tail rotor pedals). After the fire trucks and rescue vehicles arrived at PTN, he completed three shallow approaches to runway 24 to burn off fuel and to see how the helicopter would respond to control movements. While turning left to downwind, during the fourth go-around, the pilot was having trouble controlling the left yaw when he realized the helicopter's hydraulic system had failed. He "decided the safest thing to do was as soon as possible enter autorotation over [the] grass near [the] fire trucks." The pilot stated that he briefed the passenger on which lever was the fuel flow control. He entered autorotation downwind and instructed the passenger to "pull the [fuel flow control] lever off." When the helicopter touched down, "it slid with a yaw left and flipped over coming to rest on its left side."

The passenger reported that he was briefed regarding the operation of the exit and the emergency evacuation procedures. The pilot then proceeded to circle the airport to burn off excess fuel and discuss with several "helicopter operation personnel" various emergency actions. The pilot "asked me to pull the flight manual and read him the instructions for failed tail rotor procedure." After making several practice approaches, the pilot felt that "we had lost all hydraulic control power and briefed me up on what I need[ed] to do to assist him," which was to cut the fuel flow control lever at his command.

Prior to the accident occurring, a local representative from American Eurocopter arrived at PTN to assist in trouble shooting a maintenance discrepancy on another aircraft. The local representative upon learning of the situation with N350JG, telephoned a test pilot at the

American Eurocopter facility in Grand Prairie, Texas. The test pilot requested that the pilot conduct the emergency procedure for hydraulic failure of the tail rotor servo. Before the local representative could confirm if the pilot had initiated any hydraulic isolation, the pilot reported a total hydraulic failure and stated that he was going to enter autorotation.

Following the accident, the pilot reported to a representative from the American Eurocopter facility in Grand Prairie that during the fourth go-around the cyclic jerked and the hydraulic light came on. The pilot further reported that when he had pressed the "HYD" test button earlier in the flight, he had deactivated the warning horn. The cyclic pressure felt aft right, and the collective had to be held down. After entering autorotation, the pilot turned the hydraulic switch located on the collective to the off position.

Examination of the helicopter by the FAA and the manufacturer's representative from Grand Prairie revealed that the helicopter was lying on its left side. The tail boom was separated from the fuselage with hoses still connected at the tail rotor servo. The hydraulic reservoir was full and no anomalies were found with the hydraulic and air conditioner belts. Examination of the tail rotor system revealed that the spider bearing inner race was cut through the rotating housing.

Examination of the cockpit revealed that the collective hydraulic switch was in the off position, and the console hydraulic test switch (located next to the horn switch) was pressed in (hydraulics off). According to the manufacturer, the hydraulic test switch cuts off hydraulic power; however, the pilot would not lose control assist until the accumulators were depleted. The horn switch was not pressed in (warning horn was deactivated, for the warning horn to function, the switch has to be pressed in). According to the manufacturer, the warning horn alerts the pilot of either a low main rotor rpm condition or the loss of hydraulic pressure.

The hydraulic system was tested at the American Eurocopter facility in Grand Prairie under the supervision of the NTSB investigator-in-charge (IIC). The main and tail rotor servos, hydraulic pump, and regulation manifold were connected on another main rotor shaft. The hydraulic pump was powered by using a drill motor to turn the drive splines with sufficient speed to develop pressure and operate the servos, manifold, and electrical solenoids. Electrical switching was accomplished by connecting N350JG's wiring to an aircraft in Eurocopter's facility. No anomalies were noted with the hydraulic system.

Examination of the tail rotor spider was performed at the American Eurocopter facility under the supervision of the NTSB IIC. The bearing was removed from the housing. The bearing seal exhibited heat damage, and the bearing would not rotate due to small pieces of cage material that were loose between the inner and outer races. No evidence of lubrication was present on the race or balls. The cage had broken areas where the balls ride inside the cage and at several points where the cage is riveted together. The bearing balls exhibited surface corrosion.

Airworthiness Directive (AD) 99-24-18 and mandatory Service Bulletin 05.00.29 for the tail rotor

hub pitch change spider bearing check were in effect throughout the time this assembly had been in service. Aircraft maintenance records indicated the AD had been complied with every 50 hours as required. As of May 24, 2000, the tail rotor spider bearing had a total time of 450.1 hours.

For a tail rotor control failure the AS350 flight manual states, "set I.A.S. [indicated airspeed] 70 knots (130km/hr), in level flight. Press the hyd. [hydraulic] accumulator test push-button (this cuts off hydraulic power to the yaw servo control and depressurizes the load-compensating servo accumulator). After 5 seconds, reset the test button to the normal position. Make a shallow approach to a clear landing area with a slight side slip to the left. Perform a run-on landing; the side slip will be reduced progressively as power is applied."

For a hydraulics failure the AS350 flight manual states in part, "calmly reduce collective pitch and adjust the airspeed to between 40 and 60 knots (74 to 111 km/hr) in level flight. Cut off the hydraulic pressure, using collective lever pushbutton. Make a flat approach over a clear landing area and land with slight forward speed."

At 1015, the recorded wind at PTN was from 220 degrees at 10 knots.

### Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	40, Male
<b>Airplane Rating(s):</b>	None	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Helicopter	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Valid Medical--no waivers/lim.	<b>Last FAA Medical Exam:</b>	May 10, 2000
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	2626 hours (Total, all aircraft), 454 hours (Total, this make and model), 2456 hours (Pilot In Command, all aircraft), 177 hours (Last 90 days, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Eurocopter	<b>Registration:</b>	N350JG
<b>Model/Series:</b>	AS350B2 AS350B2	<b>Aircraft Category:</b>	Helicopter
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	3232
<b>Landing Gear Type:</b>	Skid	<b>Seats:</b>	6
<b>Date/Type of Last Inspection:</b>	May 14, 2000 100 hour	<b>Certified Max Gross Wt.:</b>	4951 lbs
<b>Time Since Last Inspection:</b>	36 Hrs	<b>Engines:</b>	1 Turbo shaft
<b>Airframe Total Time:</b>	461 Hrs	<b>Engine Manufacturer:</b>	Turbomeca
<b>ELT:</b>	Installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	ARRIEL-1D1
<b>Registered Owner:</b>	FIRST SECURITY BANK NA TRUSTEE	<b>Rated Power:</b>	732 Horsepower
<b>Operator:</b>	TEX AIR HELICOPTERS, INC.	<b>Operating Certificate(s) Held:</b>	On-demand air taxi (135)
<b>Operator Does Business As:</b>		<b>Operator Designator Code:</b>	TXEA

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	PTN ,9 ft msl	<b>Distance from Accident Site:</b>	
<b>Observation Time:</b>	10:15 Local	<b>Direction from Accident Site:</b>	
<b>Lowest Cloud Condition:</b>	Scattered / 2000 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	10 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	220°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29 inches Hg	<b>Temperature/Dew Point:</b>	84°C / 72°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	MORGAN CITY , LA (NONE)	<b>Type of Flight Plan Filed:</b>	Company VFR
<b>Destination:</b>	EI 307B , GM (0000)	<b>Type of Clearance:</b>	
<b>Departure Time:</b>	09:25 Local	<b>Type of Airspace:</b>	Class E

## Airport Information

<b>Airport:</b>	HARRY P WILLIAMS MEMORIAL PTN	<b>Runway Surface Type:</b>	Grass/turf
<b>Airport Elevation:</b>	9 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	0	<b>IFR Approach:</b>	
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Forced landing;Traffic pattern

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Minor	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 Minor	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 Minor	<b>Latitude, Longitude:</b>	29.689756,-91.299865(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Wigington, Douglas
<b>Additional Participating Persons:</b>	JAMES M BOWLING; BATON ROUGE , LA ROBERT REULAND; GRAND PRAIRIE , TX EDWARD L BEHNE; HOUSTON , TX
<b>Original Publish Date:</b>	November 14, 2001
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB traveled to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=49269">https://data.nts.gov/Docket?ProjectID=49269</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).