



# **Aviation Investigation Final Report**

Location: HAYFORK, California Accident Number: LAX00LA228

Date & Time: June 15, 2000, 11:15 Local Registration: N2688N

Aircraft: Cessna 140 Aircraft Damage: Substantial

**Defining Event:** 1 Minor, 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

### **Analysis**

During the landing roll, the airplane veered off the runway and contacted a runway light. After about 50-75 feet of additional landing roll, the left main gear wheel axle broke and the airplane nosed over inverted.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The failure of the pilot under instruction to maintain directional control during the landing roll and the inadequate supervision of the flight instructor, which resulted in a collision with a runway light, overload failure of the wheel axle, and the airplane nosing over inverted.

#### **Findings**

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

**Findings** 

1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - COPILOT/SECOND PILOT

2. (C) SUPERVISION - INADEQUATE - PILOT IN COMMAND(CFI)

\_\_\_\_\_

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - ROLL

Findings

3. OBJECT - RUNWAY LIGHT

\_\_\_\_\_

Occurrence #3: NOSE OVER

Phase of Operation: LANDING - ROLL

Findings

4. LANDING GEAR, AXLE - FAILURE

5. LANDING GEAR, AXLE - OVERLOAD

Page 2 of 6 LAX00LA228

#### **Factual Information**

On June 15, 2000, at 1115 hours Pacific daylight time, a Cessna 140, N2688N, ran off the runway and nosed over during landing at Hayfork, California. The flight instructor was not injured, and the private pilot sustained minor injuries. The airplane, operated by the pilot under instruction, sustained substantial damage. The local area instructional flight was conducted under the provisions of 14 CFR Part 91. The pilot did not file a flight plan and did not obtain a weather briefing prior to departure. Visual meteorological conditions prevailed at the time of the accident. The flight originated in Eureka, California, at an unknown time.

According to the owner of the airplane, this flight was to be an instructional flight prior to solo for insurance purposes. He said that they departed Eureka Airport and then went to Kneeland and landed. They then flew to Hayfork Airport and landed on runway 25. He stated that upon rollout he got off the left side of the runway a "few feet" and broke a runway light lens. The light lens hit the fuselage about 6 feet in front of the tail wheel. He said they continued to rollout about 40 miles per hour for 50-75 feet, when the left main gear axle broke and the airplane nosed over onto it's back.

#### **Pilot Information**

Certificate:	Airline transport; Flight instructor	Age:	36,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	May 22, 2000
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	4991 hours (Total, all aircraft), 76 hours (Total, this make and model), 4912 hours (Pilot In Command, all aircraft), 269 hours (Last 90 days, all aircraft), 46 hours (Last 30 days, all aircraft), 6 hours (Last 24 hours, all aircraft)		

Page 3 of 6 LAX00LA228

## **Aircraft and Owner/Operator Information**

Aircraft Make:	Cessna	Registration:	N2688N
Model/Series:	140 140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	12946
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	May 17, 2000 Annual	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	5 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	5229 Hrs	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	C-85
Registered Owner:	KEN KILBURN	Rated Power:	85 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Not reported
Observation Facility, Elevation:	RDD ,502 ft msl	Distance from Accident Site:	41 Nautical Miles
Observation Time:	10:56 Local	Direction from Accident Site:	65°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	19 knots / 28 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	350°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	91°C / 55°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	EUREKA , CA (033)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	10:45 Local	Type of Airspace:	Class E

Page 4 of 6 LAX00LA228

## **Airport Information**

Airport:	HAYFORK AIRPORT Q72	Runway Surface Type:	Asphalt
Airport Elevation:	2321 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	25	IFR Approach:	None
Runway Length/Width:	4115 ft / 60 ft	VFR Approach/Landing:	Full stop

## Wreckage and Impact Information

Crew Injuries:	1 Minor, 1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 1 None	Latitude, Longitude:	40.50019,-123.189048(est)

Page 5 of 6 LAX00LA228

#### **Administrative Information**

Investigator In Charge (IIC):	Childress, Deborah	
Additional Participating Persons:	MIKE BOHAMERA; SACRAMENTO , CA	
Original Publish Date:	August 21, 2001	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:	The NTSB traveled to the scene of this accident.	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=49451	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 LAX00LA228