

# **Aviation Investigation Final Report**

Location:	LAKE WALES, Florid	а	Accident Number:	MIA00LA205
Date & Time:	July 2, 2000, 14:00 l	₋ocal	Registration:	N983K
Aircraft:	Beech	65-A90	Aircraft Damage:	Substantial
Defining Event:			Injuries:	7 None
Flight Conducted Under:	Part 91: General avi	ation		

#### Analysis

After takeoff the pilot raised the landing gear and then had to take evasive action to the right to avoid a flock of birds. As he performed the evasive maneuver, he raised the flaps. The aircraft was slow, and he kept the nose down to build up speed for the climb. Just as he was to commence the climb, he caught a glimpse of a wire ahead. He pulled up rapidly, but contacted the wire with the right wing. The wire broke. He entered downwind and landed on runway 6. The pilot stated that he was fatigued, frustrated, and disappointed after he had worked straight for the previous 3 weeks, and had been unable to get a day off.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate visual lookout while maneuvering to avoid a flock of birds shortly after takeoff, resulting in the aircraft colliding with a wire. A factor in the accident was the pilot's fatigue after having worked everyday for the previous 3 weeks.

**Findings** 

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings 1. OBJECT - WIRE, STATIC

#### 2. (C) VISUAL LOOKOUT - INADEQUATE - PILOT IN COMMAND 3. (F) FATIGUE(FLIGHT SCHEDULE) - PILOT IN COMMAND

#### **Factual Information**

On July 2, 2000, about 1400 eastern daylight time, a Beech 65-A90, N983K, registered to Silver Lining Service, Inc., collided with wires during takeoff from Lake Wales Municipal Airport, Lake Wales, Florida, while on a Title 14 CFR Part 91 parachute flight. Visual meteorological conditions prevailed at the time and no flight plan was filed for the local flight. The aircraft received substantial damage and the commercial-rated pilot and six parachutists were not injured. The flight was originating at the time of the accident.

The pilot stated he took off on runway 6. After takeoff he raised the landing gear and then had to take evasive action to the right to avoid a flock of birds. As he performed the evasive maneuver, he raised the flaps. The aircraft was slow, and he kept the nose down to build up speed for the climb. Just as he was to commence the climb, he caught a glimpse of a wire ahead. He pulled up rapidly, but contacted the wire with the right wing. The wire broke. He entered downwind and landed on runway 6. The pilot stated that he was fatigued, frustrated, and disappointed after he had worked straight for the previous 3 weeks, and had been unable to get a day off.

Certificate:	Commercial	Age:	29,Male
Airplane Rating(s):	Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	September 22, 1999
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	1650 hours (Total, all aircraft), 110 hours (Total, this make and model), 1570 hours (Pilot In Command, all aircraft), 250 hours (Last 90 days, all aircraft), 80 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

#### **Pilot Information**

### Aircraft and Owner/Operator Information

			(
Aircraft Make:	Beech	Registration:	N983K
Model/Series:	65-A90 65-A90	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	LJ-169
Landing Gear Type:	Retractable - Tricycle	Seats:	1
Date/Type of Last Inspection:	October 10, 1999 AAIP	Certified Max Gross Wt.:	6300 lbs
Time Since Last Inspection:	120 Hrs	Engines:	2 Turbo prop
Airframe Total Time:	8900 Hrs	Engine Manufacturer:	P&W
ELT:	Not installed	Engine Model/Series:	PT6A-20
Registered Owner:	SILVER LINING SERVICE INC.	Rated Power:	500 Horsepower
Operator:	SKYDIVE LAKE WALES	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

# Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
<b>Observation Facility, Elevation:</b>	BOW ,125 ft msl	Distance from Accident Site:	10 Nautical Miles
Observation Time:	13:52 Local	Direction from Accident Site:	290°
Lowest Cloud Condition:	Scattered / 4000 ft AGL	Visibility	12 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	11 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	70°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	32°C / 20°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	(X07)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	14:00 Local	Type of Airspace:	Class G

### **Airport Information**

Airport:	LAKE WALES X07	Runway Surface Type:	Concrete
Airport Elevation:	126 ft msl	Runway Surface Condition:	Dry
Runway Used:	6	IFR Approach:	None
Runway Length/Width:	3800 ft / 100 ft	VFR Approach/Landing:	None

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	6 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	7 None	Latitude, Longitude:	27.899135,-81.579162(est)

#### **Administrative Information**

Investigator In Charge (IIC):	Kennedy, Jeffrey
Additional Participating Persons:	FRANK RIOS; ORLANDO , FL
Original Publish Date:	December 4, 2000
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	The NTSB traveled to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=49616

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.