



Aviation Investigation Final Report

Location:	WALLER, Texas	Accident Number:	FTW00LA219
Date & Time:	July 29, 2000, 15:00 Local	Registration:	N105LW
Aircraft:	Let BLANKIT	L-23 SUPER	Aircraft Damage: Destroyed
Defining Event:		Injuries:	1 Fatal
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot of the towplane reported that the takeoff was normal, and while climbing through 600 feet agl, he initiated a turn to the east and he felt the glider release as the airplane was turning. Witnesses reported that when the towplane turned left, the glider continued straight ahead and entered a climb. The glider then entered an uncoordinated turn to the right toward the airport. Subsequently, the glider's nose dropped, and it entered a spin and impacted the ground. When the tow plane landed it was evident that the tow rope had separated, and the glider pilot had not released in the normal manner. The 5/16-inch polypropylene rope separated at a point 25 feet forward of the glider attach point. The rope's fibers, at the point of separation, were frayed and uneven. The remainder of the rope was clean and free of abrasions, knots, and nicks. According to toxicology tests, 0.034 (ug/ml,ug/g) diphenhydramine was detected in the pilot's blood, and an unquantified amount was found in the urine. Diphenhydramine is an over-the-counter drug used as an antihistamine. Results of a study on diphenhydramine concluded that it adversely affects a person's ability to maneuver an automobile.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the pilot's failure to maintain control of the glider while maneuvering. Contributory factors were the in-flight separation of the tow rope and the pilot's physical impairment from his use of diphenhydramine.

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION

Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (F) GLIDER LAUNCH/TOW EQUIPMENT - SEPARATION

Occurrence #2: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: MANEUVERING - TURN TO LANDING AREA (EMERGENCY)

Findings

2. (C) AIRCRAFT CONTROL - NOT MAINTAINED - PILOT IN COMMAND

3. STALL/SPIN - ENCOUNTERED - PILOT IN COMMAND

4. (F) IMPAIRMENT(DRUGS) - PILOT IN COMMAND

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: EMERGENCY DESCENT/LANDING

Findings

5. TERRAIN CONDITION - GROUND

Factual Information

On July 29, 2000, at 1500 central daylight time, a Let L-23 Super Blankit non-powered glider, N105LW, was destroyed when it impacted trees following a separation of the towrope and loss of control during the initial takeoff climb from the Houston Gliderport, Waller, Texas. The glider was registered to and operated by The Soaring Club of Houston, Houston, Texas. The private pilot, who held a glider rating, sustained fatal injuries. Visual meteorological conditions prevailed and a flight plan was not filed for the 14 Code of Federal Regulations Part 91 personal flight. The local flight was originating at the time of the accident.

According to the pilot of the towplane, the takeoff from runway 17 was normal and while climbing through 600 feet agl he initiated a left turn to the east. He reported that as the airplane was turning he "felt the glider release from the tow," and he then banked hard left to give way to the glider. Subsequently, the pilot received a radio transmission that the glider had crashed, and he returned to the airport. Upon landing it was evident that the tow rope had separated, and the glider pilot had not released in the normal manner.

According to witnesses, the initial climb-out "appeared quite normal" and "as usual, at the end of the airport the tow plane commenced a left turn." However, the glider continued straight ahead and it entered a climb. The glider was 250-300 feet agl when it began a "very uncoordinated turn to the right," and as it turned through 90 degrees, the "nose of the glider dropped and it entered a spin." Subsequently, the glider completed 1-2 turns before impacting trees and the ground. One witness, who was part of the airport crew and a wing runner for the gliders, stated that "it was picture-perfect for soaring," and "all other flights that day were without incident and none of the pilots of the Blankit that day had mentioned any problems."

The separated sections of the rope were removed from the glider attach point and from the tow plane by an FAA inspector. The rope was sent to the NTSB Investigator-In-Charge for examination. The rope was separated approximately 25 feet forward of the attach point on the glider, and the rope's fibers, at the separation point, appeared frayed and uneven. The remainder of the rope appeared clean and was free of abrasions, knots, and nicks. According to Soaring Club personnel, the rope was 5/16-inch polypropylene, with a breaking strength of 1,300 pounds.

According to FAA records and the pilot's flight logbook, the pilot was issued a private pilot certificate (single-engine land) on September 19, 1970, and a glider rating on April 30, 2000. He had accumulated a total of 118.4 flight hours, of which 26.2 flight hours were in gliders. His last FAA third class medical certificate was issued on June 14, 1992, and there was no record of the pilot having been issued an FAA medical certificate since that time. Additionally, the FAA does not require a pilot to hold a medical certificate to pilot a glider.

An autopsy was performed by the Office of the Medical Examiner of Harris County, Houston, Texas. Toxicological tests were performed by the FAA's Civil Aeromedical Institute, Oklahoma City, Oklahoma. The tests were negative for carbon monoxide, cyanide and ethanol. The tests revealed the following; Bupropion present in blood and urine, bupropion metabolite detected in blood and urine, 0.034 (ug/ml, ug/g) diphenhydramine detected in blood, and diphenhydramine detected in urine. Bupropion is a prescription medication (commonly known by the trade name Wellbutrin) used in the treatment of depression, attention deficit hyperactivity disorder, and smoking cessation. Diphenhydramine is an over-the-counter antihistamine (commonly known by the trade name Benadryl) used in symptomatic management of allergic symptoms and also for its sedative, antitussive and antispasmodic effects.

The American College of Physicians-American Society of Internal Medicine conducted a study (Effects of Fexofenadine, Diphenhydramine, and Alcohol on Driving Performance) on the effects of diphenhydramine on driving performance. The results of that study indicated that "Participants had significantly better coherence after taking alcohol or fexofenadine (Allegra) than after taking diphenhydramine...After participants took diphenhydramine, driving performance was poorest, indicating that diphenhydramine had a greater impact on driving than alcohol did."

Pilot Information

Certificate:	Private	Age:	53, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 3 Expired	Last FAA Medical Exam:	August 14, 1992
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	118 hours (Total, all aircraft), 26 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	Let	Registration:	N105LW
Model/Series:	L-23 SUPER BLANKIT L-23 SUPER	Aircraft Category:	Glider
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Utility	Serial Number:	938105
Landing Gear Type:		Seats:	2
Date/Type of Last Inspection:	April 22, 2000 Annual	Certified Max Gross Wt.:	1120 lbs
Time Since Last Inspection:	70 Hrs	Engines:	Unknown
Airframe Total Time:	1399 Hrs	Engine Manufacturer:	
ELT:		Engine Model/Series:	
Registered Owner:	THE SOARING CLUB OF HOUSTON	Rated Power:	
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	HOU ,47 ft msl	Distance from Accident Site:	30 Nautical Miles
Observation Time:	16:53 Local	Direction from Accident Site:	90°
Lowest Cloud Condition:	Scattered / 6000 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 25000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	12 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	150°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	27°C / 20°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	WALLER , TX (89TA)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	
Departure Time:	15:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	HOUSTON GLIDERPORT 89TA	Runway Surface Type:	Grass/turf
Airport Elevation:	300 ft msl	Runway Surface Condition:	Dry
Runway Used:	17	IFR Approach:	
Runway Length/Width:	3500 ft / 300 ft	VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Fatal	Latitude, Longitude:	30.050788,-95.920417(est)

Administrative Information

Investigator In Charge (IIC):	Ragogna, Jason
Additional Participating Persons:	DAVID H MILLER; HOUSTON , TX
Original Publish Date:	July 10, 2001
Last Revision Date:	
Investigation Class:	Class
Note:	The NTSB traveled to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=49876

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).