

# **Aviation Investigation Final Report**

Location:	DOUGLAS, Wyomin	g	Accident Number:	DEN00LA156
Date & Time:	August 20, 2000, 19	0:00 Local	<b>Registration:</b>	N61782
Aircraft:	Cessna	180K	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal			

#### **Analysis**

During landing roll at the completion of a cross-country flight, the aircraft departed the left side of the runway and the right wing sustained substantial damage when it impacted the ground. The landing was being made on runway 5 and the wind was from 010 degrees magnetic heading at 27 knots with gusts to 34 knots. This produced a calculated direct crosswind of 17 knots with a direct crosswind of 23 knots during peak gusts. In accordance with this aircraft's certification requirements established in 14 CFR Part 23, published crosswind limitations are not required. The demonstrated crosswind capability listed in the operating handbook is 12 knots.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain control of the aircraft during landing roll. Factors were high winds and crosswinds.

#### Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - ROLL

Findings 1. (F) WEATHER CONDITION - HIGH WIND 2. (F) WEATHER CONDITION - CROSSWIND 3. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND 4. INADEQUATE CERTIFICATION/APPROVAL - FAA(ORGANIZATION)

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: LANDING - ROLL

#### **Factual Information**

On August 20, 2000, at 1900 mountain daylight time, a Cessna 180K, N61782, sustained substantial damage and the pilot was not injured when the right wing contacted the ground during a crosswind landing at Douglas, Wyoming. Visual meteorological conditions prevailed for this cross-country personal flight operating under Title 14 CFR Part 91 and no flight plan was filed. The flight originated from a private airstrip at Chugwater, Wyoming at 1820.

According to the pilot, when the flight arrived in the Douglas area he entered left traffic for a landing on runway 5. He said the wind was from the north and he maintained directional control for 300 to 400 hundred feet following touchdown and then lost directional control and the aircraft "weathervaned" to the left and departed the side of the runway. When the aircraft left the runway the right wing and propeller struck the ground.

Examination of the aircraft by an FAA inspector revealed both spar and rib damage to the outer portion of the right wing.

Recorded wind at the time of the accident was from 010 degrees magnetic heading at 27 knots with gusts to 34 knots. The direct steady state crosswind was computed to be 17 knots and the peak gusts produced a direct crosswind computed at 23 knots. According to the aircraft operating handbook, the demonstrated direct crosswind capability is 12 knots. In accordance with this aircraft's certification requirements established in 14 CFR Part 23, published crosswind limitations are not required.

Certificate:	Private	Age:	50,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	July 6, 1999
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	434 hours (Total, all aircraft), 376 hours (Total, this make and model), 434 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

#### **Pilot Information**

## Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N61782
Model/Series:	180K 180K	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18052798
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	October 11, 1999 Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:	16 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2928 Hrs	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	0-470-U
Registered Owner:	RODGER V. SCHROEDER	Rated Power:	230 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	DGW ,4929 ft msl	Distance from Accident Site:	
Observation Time:	18:53 Local	Direction from Accident Site:	1°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	27 knots / 34 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	10°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	27°C / 6°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	CHUGWATER , WY	Type of Flight Plan Filed:	None
Destination:	(DGW)	Type of Clearance:	None
Departure Time:	18:20 Local	Type of Airspace:	Class E

## **Airport Information**

Airport:	CONVERSE COUNTY DGW	Runway Surface Type:	Asphalt
Airport Elevation:	4929 ft msl	Runway Surface Condition:	Dry
Runway Used:	5	IFR Approach:	None
Runway Length/Width:	4760 ft / 75 ft	VFR Approach/Landing:	Traffic pattern

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	42.749378,-105.389717(est)

#### **Administrative Information**

Investigator In Charge (IIC):	Wiemeyer, Norman		
Additional Participating Persons:	JAMES P CLAYVILLE; CASPER , WY		
Original Publish Date:	March 2, 2001		
Last Revision Date:			
Investigation Class:	<u>Class</u>		
Note:	The NTSB traveled to the scene of this accident.		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=50039		

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.