



# Aviation Investigation Final Report

---

|                                |                                      |                         |                 |
|--------------------------------|--------------------------------------|-------------------------|-----------------|
| <b>Location:</b>               | ZEPHYRHILLS, Florida                 | <b>Accident Number:</b> | MIA00LA263      |
| <b>Date &amp; Time:</b>        | September 16, 2000, 10:00 Local      | <b>Registration:</b>    | N7196L          |
| <b>Aircraft:</b>               | Grumman AA-5                         | <b>Aircraft Damage:</b> | Substantial     |
| <b>Defining Event:</b>         |                                      | <b>Injuries:</b>        | 1 Minor, 2 None |
| <b>Flight Conducted Under:</b> | Part 91: General aviation - Personal |                         |                 |

---

## Analysis

The pilot noted the airplane was not climbing as expected and a decreased engine rpm. He checked the throttle and mixture controls then with obstructions ahead, intentionally stalled the airplane; a hard landing resulted. The mixture control arm was in the idle cutoff position and the mixture control cable was fractured aft of the mixture control arm. A bracket near the carburetor securing the mixture cable was displaced to the left 1.5 inches. The swivel assembly in the mixture control arm was installed upside down. Post accident, the engine was operated to 2,300 rpm. Both ends of the flame tube of the muffler were found separated following the engine run. One of the flame tube ends was impact damaged; portions of the fracture surfaces on both flame tube ends had a relatively shiny appearance. Wear and fatigue noted on the mixture control cable adjacent to the fracture area; bending overstress to the right on the remaining fracture surface. The mixture control cable had not been replaced since airplane manufacture in 1974. The airplane had accumulated 2,246 hours since then, 44 hours since the last annual inspection 11 months earlier, and 408 hours since an overhauled muffler was installed.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the intentional stall/mush by the pilot-in-command due to obstructions ahead resulting in a hard landing. Contributing to the accident was the partial loss of engine power due to fuel starvation caused by wear, fatigue, then overstress separation of the mixture control cable resulting in the mixture control arm moving to the idle cutoff position.

## Findings

Occurrence #1: LOSS OF ENGINE POWER(PARTIAL) - MECH FAILURE/MALF

Phase of Operation: TAKEOFF - INITIAL CLIMB

### Findings

1. (F) MIXTURE CONTROL,CABLE - WORN
2. (F) MIXTURE CONTROL,CABLE - FATIGUE
3. (F) MIXTURE CONTROL,CABLE - FAILURE,TOTAL
4. (F) MIXTURE CONTROL,CABLE - NOT CONNECTED
5. (F) FLUID,FUEL - STARVATION

-----

Occurrence #2: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: MANEUVERING - TURN TO LANDING AREA (EMERGENCY)

### Findings

6. (C) STALL/MUSH - INTENTIONAL - PILOT IN COMMAND

## Factual Information

On September 16, 2000, about 1000 eastern daylight time, a Grumman AA-5, N7196L, registered to Positive Attitudes, Inc., experienced a loss of engine power shortly after takeoff from the Zephyrhills Municipal Airport, Zephyrhills, Florida. Visual meteorological conditions prevailed at the time and no flight plan was filed for the 14 CFR Part 91 personal flight. The airplane was substantially damaged and the private-rated pilot and one passenger were not injured. One passenger sustained minor injuries. The flight originated about 1 minute earlier from the Zephyrhills Municipal Airport.

The pilot stated that the aircraft preflight and engine run-up before departure were uneventful. The flight departed and during the initial climb at approximately 350 feet above ground level (agl), he noted that the airplane did not appear to be ascending as expected. He looked at the tachometer which was indicating between 1,900 and 2,000 rpm and, "...checked throttle and mixture which were both OK." He also scanned the gauges and switches on the instrument panel which were also indicating "OK." He advised his passengers of the situation and maneuvered the airplane for a landing in a field. He noted trees that were ahead and applied aft elevator control input to intentionally stall the airplane; it dropped and impacted the ground then slid approximately 60-70 feet before coming to rest upright. Both passengers reported that the airplane impacted the ground "real hard."

The accident site was located approximately 1 mile north of the airport. The airplane was recovered and according to the FAA certificated mechanic who recovered it, the carburetor bowl was drained and found to contain 2.5 ounces of fuel; no contaminants were noted. Some automotive fuel was present. The mechanic also indicated that he smelled fuel on the ground during recovery and that there was no fuel remaining in the fuel tanks when he recovered the airplane.

Examination of the airplane following recovery by an FAA airworthiness inspector revealed the mixture control cable was broken aft of the mixture control arm at the carburetor. An approximate 3-inch section of the cable remained secured to the mixture control arm which was found in the idle cutoff position. A bracket located in the engine compartment approximately 4.5 inches aft of the carburetor that secures the mixture control cable was noted to be displaced approximately 1.5 inches to the left; the cable housing remained secured to the bracket. The swivel assembly in the mixture control arm was installed upside down contrary to the illustrations in the maintenance manual and the illustrated parts catalog. The damaged propeller was removed from the airplane and a serviceable propeller was installed for the attempted engine run that was performed with FAA oversight. The engine was started and operated to 2,300 rpm. A check of each magneto during the engine run revealed that the left magneto had a broken "P" lead; the right magneto drop was noted to be "OK." Also during the engine run, a "tinny rattling noise" was heard. The engine was secured and a rattling sound

was heard when the muffler struck by hand. The muffler was removed and cut open which revealed that both end caps of the flame tube were separated and loose inside the muffler. Copies of the FAA inspector statements are an attachment to this report. The muffler and broken mixture control cable were retained for further examination by the NTSB Materials Laboratory located in Washington, D.C.

Metallurgical examination of the mixture control cable revealed the fracture location of the wire was 0.14 inches forward of the end of the housing when the cable was straight and with the knob pushed in all of the way. The solid wire of the cable was worn adjacent to the fracture surface with the greatest wear on the wire located within approximately 0.34 inches aft and 0.09 inches forward of the fracture location. The worn surface was located at the outside radius of the bend (on the right side of the cable). Fatigue was noted emanating from multiple origins at the worn surface of the wire adjacent to the fracture surface. The area of the fatigue region was less than 10 percent of the total fracture surface area. The remaining fracture surface had dimpled fracture features consistent with overstress fracture. The fracture surfaces of the forward and aft pieces of the control cable were fit together which formed an angle of 129 degrees relative to each other with a bend radius of approximately 0.17 inches at the cable centerline. The direction of the deformation in the cable was such that the angle of the bend pointed to aircraft right. Examination of the muffler revealed the interior of the muffler had a generally corroded appearance, and the perforated inner cylinder wall thickness appeared thinner nearest the fracture locations where the end caps were located. Pieces were missing from the inner cylinder. Impact damage to the exterior of the muffler was noted and one of the separated end caps was deformed which was associated with the exterior crushing. Portions of the fracture surfaces on each end cap had a relatively shiny appearance consistent with little or no oxidation. A copy of the metallurgy report is an attachment to this report.

The airplane was manufactured in 1974, and had accumulated approximately 2,246 hours since then at the time of the accident. There was no record that the mixture control cable had been replaced since the airplane was manufactured. The muffler was replaced with an "overhauled" unit on August 11, 1993. The muffler had been in service for 408 hours at the time of the accident as determined by the tachometer. The airplane was inspected last on October 26, 1999, in accordance with an annual inspection and had accumulated approximately 44 hours since then at the time of the accident. Excerpts from the maintenance records are an attachment to this report.

The airplane minus the retained mixture control cable was released to Mr. Steven M. Homenda, insurance adjuster for Universal Loss Management, Inc., on September 20, 2000. The muffler was retained on November 15, 2000. The retained mixture control cable and muffler were released to Mr. Steven M. Homenda, on July 13, 2001.

## Pilot Information

|                                  |   |  |              |
|----------------------------------|---|--|--------------|
| <b>Certificate:</b>              | Private   | <b>Age:</b>                              | 45, Male     |
| <b>Airplane Rating(s):</b>       | Single-engine land  | <b>Seat Occupied:</b>                    | Left         |
| <b>Other Aircraft Rating(s):</b> | None  | <b>Restraint Used:</b>                   |              |
| <b>Instrument Rating(s):</b>     | None  | <b>Second Pilot Present:</b>             | No           |
| <b>Instructor Rating(s):</b>     | None  | <b>Toxicology Performed:</b>             | No           |
| <b>Medical Certification:</b>    | Class 3 Valid Medical--no waivers/lim.  | <b>Last FAA Medical Exam:</b>            | July 7, 1999 |
| <b>Occupational Pilot:</b>       | UNK   | <b>Last Flight Review or Equivalent:</b> |              |
| <b>Flight Time:</b>              | 93 hours (Total, all aircraft), 5 hours (Total, this make and model), 43 hours (Pilot In Command, all aircraft), 21 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft) |  |              |

## Aircraft and Owner/Operator Information

|                                      |                          |                                       |                 |
|--------------------------------------|--------------------------|---------------------------------------|-----------------|
| <b>Aircraft Make:</b>                | Grumman                  | <b>Registration:</b>                  | N7196L          |
| <b>Model/Series:</b>                 | AA-5 AA-5                | <b>Aircraft Category:</b>             | Airplane        |
| <b>Year of Manufacture:</b>          |                          | <b>Amateur Built:</b>                 |                 |
| <b>Airworthiness Certificate:</b>    | Normal; Utility          | <b>Serial Number:</b>                 | AA5-0496        |
| <b>Landing Gear Type:</b>            | Tricycle                 | <b>Seats:</b>                         | 4               |
| <b>Date/Type of Last Inspection:</b> | October 26, 1999 Annual  | <b>Certified Max Gross Wt.:</b>       | 2200 lbs        |
| <b>Time Since Last Inspection:</b>   | 44 Hrs                   | <b>Engines:</b>                       | 1 Reciprocating |
| <b>Airframe Total Time:</b>          | 2246 Hrs                 | <b>Engine Manufacturer:</b>           | Lycoming        |
| <b>ELT:</b>                          | Installed, not activated | <b>Engine Model/Series:</b>           | O-320-E2G       |
| <b>Registered Owner:</b>             | POSITIVE ATTITUDES, INC. | <b>Rated Power:</b>                   | 150 Horsepower  |
| <b>Operator:</b>                     | ARTHUR L. SCHAEER        | <b>Operating Certificate(s) Held:</b> | None            |
| <b>Operator Does Business As:</b>    |                          | <b>Operator Designator Code:</b>      |                 |

## Meteorological Information and Flight Plan

|   |                                  |   |                    |
|---|----------------------------------|---|--------------------|
| <b>Conditions at Accident Site:</b>     | Visual (VMC)                     | <b>Condition of Light:</b>                  | Day                |
| <b>Observation Facility, Elevation:</b> | LAL ,142 ft msl                  | <b>Distance from Accident Site:</b>         | 151 Nautical Miles |
| <b>Observation Time:</b>                | 09:50 Local                      | <b>Direction from Accident Site:</b>        | 17°                |
| <b>Lowest Cloud Condition:</b>          | Scattered / 7000 ft AGL          | <b>Visibility</b>                           | 12 miles           |
| <b>Lowest Ceiling:</b>                  | Broken / 15000 ft AGL            | <b>Visibility (RVR):</b>                    |                    |
| <b>Wind Speed/Gusts:</b>                | 4 knots /                        | <b>Turbulence Type Forecast/Actual:</b>     | /                  |
| <b>Wind Direction:</b>                  | 180°                             | <b>Turbulence Severity Forecast/Actual:</b> | /                  |
| <b>Altimeter Setting:</b>               | 29 inches Hg                     | <b>Temperature/Dew Point:</b>               | 79°C / 73°C        |
| <b>Precipitation and Obscuration:</b>   | No Obscuration; No Precipitation |   |                    |
| <b>Departure Point:</b>                 | (ZPH )                           | <b>Type of Flight Plan Filed:</b>           | None               |
| <b>Destination:</b>                     | LEESBURG , FL (LEE )             | <b>Type of Clearance:</b>                   | None               |
| <b>Departure Time:</b>                  | 09:59 Local                      | <b>Type of Airspace:</b>                    | Class G            |

## Airport Information

|                             |                           |                                  |         |
|-----------------------------|---------------------------|----------------------------------|---------|
| <b>Airport:</b>             | ZEPHYRHILLS MUNICIPAL ZPH | <b>Runway Surface Type:</b>      | Asphalt |
| <b>Airport Elevation:</b>   | 90 ft msl                 | <b>Runway Surface Condition:</b> | Dry     |
| <b>Runway Used:</b>         | 4                         | <b>IFR Approach:</b>             |         |
| <b>Runway Length/Width:</b> | 5001 ft / 100 ft          | <b>VFR Approach/Landing:</b>     |         |

## Wreckage and Impact Information

|                            |                 |                             |             |
|----------------------------|-----------------|-----------------------------|-------------|
| <b>Crew Injuries:</b>      | 1 None          | <b>Aircraft Damage:</b>     | Substantial |
| <b>Passenger Injuries:</b> | 1 Minor, 1 None | <b>Aircraft Fire:</b>       | None        |
| <b>Ground Injuries:</b>    | N/A             | <b>Aircraft Explosion:</b>  | None        |
| <b>Total Injuries:</b>     | 1 Minor, 2 None | <b>Latitude, Longitude:</b> |             |

## Administrative Information

|  |   |
|--|---|
| <b>Investigator In Charge (IIC):</b>     | Monville, Timothy   |
| <b>Additional Participating Persons:</b> | JAMES R BLAKE; TAMPA , FL<br>GARY VIDAK; ORLANDO , FL   |
| <b>Original Publish Date:</b>            | October 9, 2001   |
| <b>Last Revision Date:</b>               |   |
| <b>Investigation Class:</b>              | <a href="#">Class</a>   |
| <b>Note:</b>                             | The NTSB traveled to the scene of this accident.  |
| <b>Investigation Docket:</b>             | <a href="https://data.nts.gov/Docket?ProjectID=50288">https://data.nts.gov/Docket?ProjectID=50288</a> |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).