



Aviation Investigation Final Report

Location: KIANA, Alaska Accident Number: ANC01LA002

Date & Time: October 5, 2000, 18:50 Local Registration: N5293X

Aircraft: Cessna 206 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 135: Air taxi & commuter - Scheduled

Analysis

The airline transport certificated pilot departed on a scheduled commuter flight. About 10 minutes after departure, about 2,000 feet msl, the pilot heard and felt a thump. The windshield became covered in blood, and the pilot noticed the oil access door was open. He returned to the departure airport and discovered several areas of impact with birds that included the windshield, vertical stabilizer, the right wing root, and the right wingtip. An examination of the right wing by the director of maintenance revealed aft crushing of the leading edge, and damage to a nose rib, about six inches inboard from the tip.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: An in-flight collision with birds.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: CRUISE

Findings

1. (C) OBJECT - BIRD(S)

2. WING, WING RIB - BUCKLED

Factual Information

On October 5, 2000, about 1850 Alaska daylight time, a Cessna 206 airplane, N5293X, sustained substantial damage following an in-flight collision with several birds, about 10 miles west of Kiana, Alaska, about latitude 66 degrees, 58 minutes north, and longitude 160 degrees, 53 minutes west. The airplane was being operated by Baker Aviation, Kotzebue, Alaska, under Title 14, CFR Part 135, as Flight 426, a visual flight rules, scheduled domestic passenger flight, when the accident occurred. The airline transport certificated pilot, the sole occupant, was not injured. Visual meteorological conditions prevailed. A VFR flight plan was filed. The flight originated at the Bob Baker Memorial Airport, Kiana, about 1845.

On October 9, 2000, the director of maintenance for the operator reported the pilot departed Kiana, en route to Kotzebue, without any passengers. While in cruise flight at 2,000 feet msl, the pilot heard and felt a thump. The windshield became covered in blood, and the pilot noticed the oil access door was open. He returned to Kiana and discovered several areas of impact with birds that included the windshield, vertical stabilizer, the right wing root, and the right wingtip. An examination of the right wing by the director of maintenance revealed aft crushing of the leading edge, and damage to a nose rib, about six inches inboard from the tip.

Pilot Information

Certificate:	Airline transport	Age:	42,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	October 2, 2000
Occupational Pilot:	Yes Last Flight Review or Equivalent:		
Flight Time:	6960 hours (Total, all aircraft), 4650 hours (Total, this make and model), 6760 hours (Pilot In Command, all aircraft), 241 hours (Last 90 days, all aircraft), 108 hours (Last 30 days, all aircraft), 7 hours (Last 24 hours, all aircraft)		

Page 2 of 5 ANC01LA002

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N5293X
Model/Series:	206 206	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	2060005612
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	September 16, 2000 100 hour	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:	86 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	13279 Hrs	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	IO-520-F
Registered Owner:	BAKER AVIATION INC.	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	Commuter air carrier (135), On-demand air taxi (135)
Operator Does Business As:		Operator Designator Code:	BAJA

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	30°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	-2°C / -7°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	KIANA , AK (PAIL)	Type of Flight Plan Filed:	VFR
Destination:	KOTZEBUE , AK (PAOT)	Type of Clearance:	None
Departure Time:	18:45 Local	Type of Airspace:	Class G

Page 3 of 5 ANC01LA002

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	66.980194,-160.429962(est)

Page 4 of 5 ANC01LA002

Administrative Information

Investigator In Charge (IIC):	Erickson, Scott	
Additional Participating Persons:	ERIC JONES (FAA); FAIRBANKS , AK	
Original Publish Date:	July 10, 2001	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=50444	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC01LA002