

Aviation Investigation Final Report

Location:	LINCOLN PARK, Ne	ew Jersey	Accident Number:	NYC01LA010
Date & Time:	October 6, 2000, 16	5:30 Local	Registration:	N8895M
Aircraft:	Beech	BE-23	Aircraft Damage:	Substantial
Defining Event:			Injuries:	2 None
Flight Conducted Under:	Part 91: General av	iation - Personal		

Analysis

The pilot stated that he was teaching his girlfriend to taxi their new airplane. The pilot became distracted by a wasp in the cockpit. While his attention was diverted, the airplane veered to the right, and struck a parked airplane.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot-in-command's failure to maintain directional control while taxiing.

Findings

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT Phase of Operation: TAXI

Findings 1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Factual Information

On October 6, 2000, about 1630 Eastern Daylight Time, a Beech BE-23, N8895M, was substantially damaged while taxiing at Lincoln Park Airport (N07), Lincoln Park, New Jersey. The certificated commercial pilot and passenger were not injured. Visual meteorological conditions prevailed, and no flight plan was filed for the local personal flight conducted under 14 CFR Part 91.

The pilot stated that he had recently bought the airplane. The pilot was not a certified flight instructor, but he was teaching his girlfriend to taxi. While taxiing, the pilot was distracted by a wasp in the cockpit. While his attention was diverted, the airplane veered off to the right side of the taxiway, and struck a parked airplane. The right wing of his airplane sustained substantial damage, and the propeller and windscreen of the parked airplane was damaged. The pilot added that the parked airplane was much closer to the taxiway than all other parked airplanes at N07.

According to a Lincoln Park Police Officer, the pilot reported that he had just landed, and was taxiing toward the parking area. He was distracted by a wasp and struck the parked airplane.

Certificate:	Commercial	Age:	35,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	September 12, 2000
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	1200 hours (Total, all aircraft)		

Pilot Information

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N8895M
Model/Series:	BE-23 BE-23	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	M-647
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	February 1, 1999 Annual	Certified Max Gross Wt.:	2405 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2200 Hrs	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	IO-360
Registered Owner:	CRAIG A. SQUILLANTE	Rated Power:	165 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	CDW ,173 ft msl	Distance from Accident Site:	180 Nautical Miles
Observation Time:	16:53 Local	Direction from Accident Site:	5°
Lowest Cloud Condition:	Scattered / 3500 ft AGL	Visibility	6 miles
Lowest Ceiling:	Broken / 6500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	290°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	21°C / 17°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	(N07)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	LINCOLN PARK AIRPORT N07	Runway Surface Type:	Asphalt
Airport Elevation:	182 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	Gretz, Robert		
Additional Participating Persons:	KEN SYMONS; TETERBORO , NJ		
Original Publish Date:	May 8, 2001		
Last Revision Date:			
Investigation Class:	<u>Class</u>		
Note:	The NTSB traveled to the scene of this accident.		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=50450		

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.