



# **Aviation Investigation Final Report**

Location: MONTROSE, Colorado Accident Number: DEN01LA023

Date & Time: October 14, 2000, 08:30 Local Registration: N111KC

Aircraft: Cessna 310N Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot said he encountered wind shear on short final and made a "very hard" landing. A National Climatic Data Center representative said that the winds at 0800 were from 150 degrees at 7 knots, and at 0900, calm. The pilot stated that a higher airspeed during landing flare could have prevented the accident. Following the event, the pilot flew the airplane for approximately 8 more hours when a mechanic discovered structural damage to the right wing.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the pilot's inadequate airspeed on final approach which resulted in a hard landing. A contributing factor was wind shear.

### **Findings**

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

#### **Findings**

1. (F) WEATHER CONDITION - WINDSHEAR

2. (C) AIRSPEED - INADEQUATE - PILOT IN COMMAND

#### **Factual Information**

On October 14, 2000, at approximately 0830 mountain daylight time, a Cessna 310N, N111KC, was substantially damaged during a hard landing at Montrose Regional Airport, Montrose, Colorado. The private pilot, the sole occupant in the airplane, was not injured. The pilot was operating the airplane under Title 14 CFR Part 91. Visual meteorological conditions prevailed for the cross-country flight that originated 45 minutes before the accident from Aspen, Colorado. The pilot had not filed a flight plan.

According to the pilot, he encountered wind shear on short final and made a "very hard" landing. A National Climatic Data Center representative said that the winds in Montrose, Colorado, on October 14, 2000, at 0800 were from 150 degrees at 7 knots, and at 0900, calm. The pilot stated that "a higher speed into round-off/flare" could have prevented the accident.

Following this event, the pilot flew the airplane for approximately 8 more hours (until approximately December 1) when a mechanic discovered structural damage to the right wing.

#### **Pilot Information**

| Certificate:              | Private   | Age:                              | 42,Male           |
|---------------------------|---|-----------------------------------|-------------------|
| Airplane Rating(s):       | Multi-engine land   | Seat Occupied:                    | Left              |
| Other Aircraft Rating(s): | None  | Restraint Used:                   |                   |
| Instrument Rating(s):     | None  | Second Pilot Present:             | No                |
| Instructor Rating(s):     | None  | Toxicology Performed:             | No                |
| Medical Certification:    | Class 3 Valid Medicalno waivers/lim.  | Last FAA Medical Exam:            | February 15, 1999 |
| Occupational Pilot:       | UNK   | Last Flight Review or Equivalent: |                   |
| Flight Time:              | 626 hours (Total, all aircraft), 153 hours (Total, this make and model), 451 hours (Pilot In Command, all aircraft), 20 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft) |                                   |                   |

Page 2 of 5 DEN01LA023

## **Aircraft and Owner/Operator Information**

| Aircraft Make:                   | Cessna                 | Registration:                     | N111KC          |
|----------------------------------|------------------------|-----------------------------------|-----------------|
| Model/Series:                    | 310N 310N              | Aircraft Category:                | Airplane        |
| Year of Manufacture:             |                        | Amateur Built:                    |                 |
| Airworthiness Certificate:       | Normal                 | Serial Number:                    | 310N-0005       |
| Landing Gear Type:               | Retractable - Tricycle | Seats:                            | 6               |
| Date/Type of Last<br>Inspection: | June 15, 2000 Annual   | Certified Max Gross Wt.:          | 5200 lbs        |
| Time Since Last Inspection:      | 148 Hrs                | Engines:                          | 2 Reciprocating |
| Airframe Total Time:             | 3750 Hrs               | Engine Manufacturer:              | Lycoming        |
| ELT:                             |                        | Engine Model/Series:              | TIO-540         |
| Registered Owner:                | RUSSELL A. ANDREWS     | Rated Power:                      | 310 Horsepower  |
| Operator:                        |                        | Operating Certificate(s)<br>Held: | None            |
| Operator Does Business As:       |                        | Operator Designator Code:         |                 |

## Meteorological Information and Flight Plan

| Conditions at Accident Site:     | Visual (VMC)                | Condition of Light:                  | Day         |
|----------------------------------|-----------------------------|--------------------------------------|-------------|
| Observation Facility, Elevation: | MTJ ,5759 ft msl            | Distance from Accident Site:         |             |
| Observation Time:                | 08:53 Local                 | Direction from Accident Site:        |             |
| <b>Lowest Cloud Condition:</b>   | Clear                       | Visibility                           | 10 miles    |
| Lowest Ceiling:                  | None                        | Visibility (RVR):                    |             |
| Wind Speed/Gusts:                | /                           | Turbulence Type<br>Forecast/Actual:  | /           |
| Wind Direction:                  | 0°                          | Turbulence Severity Forecast/Actual: | /           |
| Altimeter Setting:               | 30 inches Hg                | Temperature/Dew Point:               | 47°C / 23°C |
| Precipitation and Obscuration:   | No Obscuration; No Precipit | ation                                |             |
| Departure Point:                 | ASPEN , CO (ASE )           | Type of Flight Plan Filed:           | None        |
| Destination:                     | (MTJ)                       | Type of Clearance:                   | None        |
| Departure Time:                  | 07:45 Local                 | Type of Airspace:                    | Class C     |

Page 3 of 5 DEN01LA023

## **Airport Information**

| Airport:             | MONTROSE REGIONAL AIRPORT<br>MTJ | Runway Surface Type:      | Asphalt   |
|----------------------|----------------------------------|---------------------------|-----------|
| Airport Elevation:   | 5759 ft msl                      | Runway Surface Condition: | Dry       |
| Runway Used:         | 17                               | IFR Approach:             | None      |
| Runway Length/Width: | 10000 ft / 150 ft                | VFR Approach/Landing:     | Full stop |

# Wreckage and Impact Information

| Crew Injuries:         | 1 None | Aircraft Damage:        | Substantial                |
|------------------------|--------|-------------------------|----------------------------|
| Passenger<br>Injuries: |        | Aircraft Fire:          | None                       |
| Ground Injuries:       | N/A    | Aircraft Explosion:     | None                       |
| Total Injuries:        | 1 None | Latitude,<br>Longitude: | 38.490367,-107.870452(est) |

Page 4 of 5 DEN01LA023

#### **Administrative Information**

| Investigator In Charge (IIC):        | Struhsaker, James                                |  |
|--------------------------------------|--|--|
| Additional Participating<br>Persons: | MIKE DAVEY; DENVER , CO                          |  |
| Original Publish Date:               | November 1, 2001                                 |  |
| Last Revision Date:                  |  |  |
| Investigation Class:                 | <u>Class</u>                                     |  |
| Note:                                | The NTSB traveled to the scene of this accident. |  |
| Investigation Docket:                | https://data.ntsb.gov/Docket?ProjectID=50778     |  |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 DEN01LA023