



# Aviation Investigation Final Report

<b>Location:</b>	Santiam, Oregon	<b>Accident Number:</b>	SEA01LA040
<b>Date &amp; Time:</b>	January 20, 2001, 14:30 Local	<b>Registration:</b>	N94432
<b>Aircraft:</b>	Ercoupe 415G	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

While en route at cruise power, the aircraft's engine began to lose power. Soon thereafter the engine slowed to idle rpm, and the pilot elected to make an emergency landing at a nearby snow-covered Oregon State Airport. Although the touchdown was successful, during the landing roll, the aircraft nosed over in the two-foot deep snow. A post-accident carburetor teardown revealed that the orifice to the main metering jet was partially plugged by a putty-like contaminant.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The partial blockage of the carburetor main metering jet orifice by contamination of undetermined origin. Factors include a snow-covered runway upon which the pilot executed a forced landing.

## Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL  
Phase of Operation: CRUISE

### Findings

1. (C) FUEL SYSTEM,CARBURETOR - BLOCKED(PARTIAL)
2. (C) FUEL SYSTEM,CARBURETOR - CONTAMINATION,OTHER THAN WATER

-----

Occurrence #2: FORCED LANDING  
Phase of Operation: DESCENT - EMERGENCY  
-----

Occurrence #3: NOSE OVER  
Phase of Operation: LANDING - ROLL

Findings  
3. (F) TERRAIN CONDITION - SNOW COVERED

## Factual Information

On January 20, 2001, approximately 1430 Pacific standard time, an Ercoupe 415G, N94432, nosed over in the snow during a forced landing at Santiam Junction State Airport, Santiam, Oregon. The private pilot, who was the sole occupant, was not injured, but the aircraft, which was owned and operated by the pilot, sustained substantial damage. The 14 CFR Part 91 personal pleasure flight, which was en route to Prineville, Oregon, in visual meteorological conditions, departed Independence, Oregon, about 55 minutes earlier. No flight plan had been filed. The ELT, which was activated by the accident sequence, was turned off at the scene.

According to the pilot, just after he passed Santiam Junction Airport, the aircraft's engine began to lose power. He therefore applied carburetor heat and turned back toward the airport. Soon thereafter, the engine went to idle RPM, and the pilot elected to execute a forced landing on runway 06 at the Santiam Junction Airport. Although the touchdown was successful, as the aircraft slowed, it nosed over in the snow that had accumulated on the runway surface. According to the pilot, the snow was approximately two feet deep.

During a post-accident engine examination, the carburetor was disassembled, and it was discovered that the orifice to the main metering jet was almost completely plugged by ball of putty-like contaminant. No similar material was found anywhere else in or on the carburetor, and it could not be determined when or how the contamination had entered the carburetor bowl.

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	29, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 Valid Medical--w/ waivers/lim	<b>Last FAA Medical Exam:</b>	April 15, 1999
<b>Occupational Pilot:</b>	UNK	<b>Last Flight Review or Equivalent:</b>	July 2, 1999
<b>Flight Time:</b>	180 hours (Total, all aircraft), 167 hours (Total, this make and model), 150 hours (Pilot In Command, all aircraft), 34 hours (Last 90 days, all aircraft), 13 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Ercoupe	<b>Registration:</b>	N94432
<b>Model/Series:</b>	415G	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	5078
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	September 10, 2000 Annual	<b>Certified Max Gross Wt.:</b>	1400 lbs
<b>Time Since Last Inspection:</b>	31 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	1898 Hrs at time of accident	<b>Engine Manufacturer:</b>	Continental
<b>ELT:</b>	Installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	C-85-12
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	85 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>		<b>Distance from Accident Site:</b>	
<b>Observation Time:</b>		<b>Direction from Accident Site:</b>	
<b>Lowest Cloud Condition:</b>		<b>Visibility</b>	15 miles
<b>Lowest Ceiling:</b>	Overcast / 14000 ft AGL	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	/	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>		<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>		<b>Temperature/Dew Point:</b>	4°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Independence, OR (7S5 )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Prineville, OR (S39 )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	13:35 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>	Santiam Junction State Airport 8S3	<b>Runway Surface Type:</b>	Grass/turf
<b>Airport Elevation:</b>	3780 ft msl	<b>Runway Surface Condition:</b>	Snow
<b>Runway Used:</b>	06	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	3100 ft / 150 ft	<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	44.41053,-121.920158(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Anderson, Orrin
<b>Additional Participating Persons:</b>	Gordon Reed; Portland FSDO
<b>Original Publish Date:</b>	July 30, 2001
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB traveled to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=51362">https://data.ntsb.gov/Docket?ProjectID=51362</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).