



# Aviation Investigation Final Report

---

<b>Location:</b>	Gary, Indiana	<b>Accident Number:</b>	CHI01LA114
<b>Date &amp; Time:</b>	April 8, 2001, 09:00 Local	<b>Registration:</b>	N6460D
<b>Aircraft:</b>	Piper J3C-65	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Other work use		

---

## Analysis

The airplane contacted a rock and directional control was lost during a forced landing following a loss of engine power. The pilot reported the engine quit while he was six miles out over the water from the shoreline of Lake Michigan. The pilot reported he was able to temporarily restore engine power as he positioned the airplane for a forced landing. The right main gear separated from the airplane during the landing roll after it contacted a large rock. The airplane came to rest part way down an embankment. Examination of the airplane after the accident revealed the carburetor had separated from the engine; however, there was no evidence of fuel leakage at the accident site. One and one-half ounces of fuel were drained from the fuel line between the header fuel tank and the fuel selector. The fuel gages indicated the right tank was empty and the left tank contained 1/3 tank of fuel. A visual inspection of both tanks revealed they were empty. The airplane had been modified with an extended range fuel system. The airplane had not been flown since September, 2000. The pilot reported that three days prior to the accident, he noticed fuel leaking out of the carburetor. He reported that he was told by a mechanic and the airplane owner that the float needle was stuck and that he should tap the carburetor with a wrench. He reported he did this, then flew the airplane around the traffic pattern. The airplane then sat until the day of the accident. The pilot reported he did not visually check the fuel level prior to takeoff on the accident flight.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The inadequate preflight performed by the pilot which resulted in an insufficient fuel supply and the subsequent fuel exhaustion. Factors associated with the accident were the inaccurate fuel quantity indicator, the rock which resulted in the overload failure of the right main landing gear, and the embankment which the airplane traveled down.

## Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL  
Phase of Operation: CRUISE - NORMAL

### Findings

1. (C) AIRCRAFT PREFLIGHT - INADEQUATE - PILOT IN COMMAND
2. FUEL SUPPLY - INADEQUATE
3. (C) FLUID,FUEL - EXHAUSTION
4. ENGINE INSTRUMENTS,FUEL QUANTITY GAGE - INACCURATE

-----

Occurrence #2: FORCED LANDING  
Phase of Operation: EMERGENCY DESCENT/LANDING

-----

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER  
Phase of Operation: LANDING - ROLL

### Findings

5. (F) AIRPORT FACILITIES,RUNWAY/LANDING AREA CONDITION - ROCK(S)/BOULDER(S)

-----

Occurrence #4: MAIN GEAR COLLAPSED  
Phase of Operation: LANDING - ROLL

### Findings

6. (F) LANDING GEAR,MAIN GEAR - OVERLOAD

-----

Occurrence #5: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER  
Phase of Operation: LANDING - ROLL

### Findings

7. (F) AIRPORT FACILITIES,RUNWAY/LANDING AREA CONDITION - DROP-OFF/DESCENDING EMBANKMENT

## Factual Information

On April 8, 2001, at 0900 central daylight time, a Piper J3C-65, N6460D, operated by a commercial pilot, collided with the terrain during a forced landing on a road in Gary, Indiana. The forced landing followed a loss of engine power. The pilot was not injured and the airplane was substantially damaged. The 14 CFR Part 91 flight was operating in visual meteorological conditions without a flight plan. The flight originated from Merrillville, Indiana, at 0850 central standard time, with an intended destination of Milwaukee, Wisconsin.

The pilot reported he performed an aircraft preflight and called flight service prior to departing Merrillville. He stated that he intended to fly along the Lake Michigan shoreline at 3,000 feet. The pilot reported that about 6 miles north of the Gary Airport, Gary, Indiana, while over Lake Michigan, the engine quit. He reported that he was in level flight when this occurred.

The pilot reported, "I restored engine power when I positioned the engine throttle close to idle position, then restored full power for a short time. (I cycle[d] through this situation all the way to the forced landing) I informed the tower, that I was trying to make the airport. Switched tanks valve, with no change in power pattern. In overall I just had an increased [sic] in the glide ratio caused by the low and high power setting. I informed the tower that I was going to land on the industrial complex north of the airport."

The pilot reported that he chose a road on which to land. He said that after approximately 150 feet of ground roll, the right main landing gear struck a "big" rock on the edge of the road. The landing gear separated from the airplane and the airplane slid to the right, traveling part way down an embankment. The carburetor was separated from the airplane during the impact. The right wing came to rest on the ground. The fuselage was buckled above the cockpit.

The airplane was examined by an inspector from the Federal Aviation Administration, South Bend, Indiana, Flight Standards District Office. The inspector reported that there was no evidence of fuel leakage at the accident site. The inspector drained 1 1/2 ounces of fuel from the fuel line between the header fuel tank and the fuel selector. He reported that the fuel gages indicated the right tank was empty and the left tank contained 1/3 tank of fuel. He reported, however, a visual inspection of both tanks revealed they were empty. The airplane had been modified with an extended range fuel system.

The airplane had not been flown since September, 2000. The pilot reported that three days prior to the accident, he noticed fuel leaking out of the carburetor. He reported that he was told by a mechanic and the airplane owner that the float needle was stuck and that he should tap the carburetor with a wrench. He reported he did this, then flew the airplane around the traffic pattern. The airplane then sat until the day of the accident. The pilot reported to the FAA inspector that he did not visually check the fuel level prior to takeoff on the accident flight.

## Pilot Information

<b>Certificate:</b>	Commercial; Flight instructor	<b>Age:</b>	54, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Center
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	Airplane single-engine	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Valid Medical-w/ waivers/lim	<b>Last FAA Medical Exam:</b>	March 22, 2001
<b>Occupational Pilot:</b>	UNK	<b>Last Flight Review or Equivalent:</b>	April 21, 2000
<b>Flight Time:</b>	10000 hours (Total, all aircraft), 60 hours (Total, this make and model), 9000 hours (Pilot In Command, all aircraft), 10 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Piper	<b>Registration:</b>	N6460D
<b>Model/Series:</b>	J3C-65	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Restricted (Special)	<b>Serial Number:</b>	19640
<b>Landing Gear Type:</b>	Tailwheel	<b>Seats:</b>	1
<b>Date/Type of Last Inspection:</b>	100 hour	<b>Certified Max Gross Wt.:</b>	1220 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>		<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	O-320
<b>Registered Owner:</b>	Aerial Two, Inc.	<b>Rated Power:</b>	180 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	GYG,592 ft msl	<b>Distance from Accident Site:</b>	
<b>Observation Time:</b>	09:38 Local	<b>Direction from Accident Site:</b>	
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	15 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	12 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	250°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.89 inches Hg	<b>Temperature/Dew Point:</b>	14°C / 6°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Merrillville, IN (05C )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Milwaukee, WI	<b>Type of Clearance:</b>	VFR
<b>Departure Time:</b>	08:50 Local	<b>Type of Airspace:</b>	Class E

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Sullivan, Pamela
<b>Additional Participating Persons:</b>	Dave Kepple; FAA; South Bend, IN
<b>Original Publish Date:</b>	January 2, 2002
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB traveled to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=52041">https://data.ntsb.gov/Docket?ProjectID=52041</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).