



# **Aviation Investigation Final Report**

Location: Murrieta, California Accident Number: LAX01LA159

Date & Time: April 22, 2001, 11:30 Local Registration: N46503

Aircraft: Ryan ST3KR Aircraft Damage: Substantial

**Defining Event:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot reported that, as he taxiied the low-wing, tailwheel equipped aircraft into the run-up area, the underside of the left wing struck a 4-foot-tall pole protecting a fire hydrant. The pilot was seated in the rear cockpit of the tandem-seating aircraft. He reported that the presence of another aircraft entering the run-up area at the same time made it necessary to alter his taxi route and, after he turned sharply, the low post was too close to be visible from the rear cockpit. The pilot also noted that the hydrant was one of two positioned within the operational area of run-up pad and there were no hazard markings painted on the asphalt around the hydrants.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The failure of the pilot to maintain an adequate visual lookout during taxi to avoid striking a post. A factor in the accident was the inadequate marking of the obstruction by airport personnel.

### **Findings**

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: TAXI - TO TAKEOFF

Findings

1. OBJECT - POLE

- 2. VISUAL LOOKOUT RESTRICTED
- 3. (C) VISUAL LOOKOUT INADEQUATE PILOT IN COMMAND 4. (F) OTHER AIRPORT/RUNWAY MAINTENANCE INADEQUATE AIRPORT PERSONNEL

Page 2 of 6 LAX01LA159

#### **Factual Information**

On April 22, 2001, at 1130 hours Pacific daylight time, a Ryan ST3KR, N46503, was substantially damaged when the aircraft's wing impacted a post during taxi for takeoff at the French Valley Airport, Murrieta, California. The airline transport certificated pilot and one passenger were not injured, and intended to conduct a local area flight. Visual meteorological conditions prevailed and no flight plan was filed for the personal flight, which was operated by the owner under 14 CFR Part 91.

The pilot reported that, as he taxiied the tailwheel equipped aircraft into the run-up area adjacent to runway 18, the underside of the left wing struck a 4-foot-tall pole protecting a fire hydrant. The pilot was seated in the rear cockpit of the tandem-seating aircraft. He reported that the presence of another aircraft entering the run-up area at the same time made it necessary to alter his taxi route and, after he turned sharply, the low post was too close to be visible from the rear cockpit. The pilot also noted that the hydrant was one of two positioned within the operational area of run-up pad and there were no hazard markings painted on the asphalt around the hydrant.

#### **Pilot Information**

1 not imormation			
Certificate:	Airline transport; Flight engineer	Age:	53,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Rear
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	February 5, 2001
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	September 5, 2000
Flight Time:	9605 hours (Total, all aircraft), 43 hours (Total, this make and model), 5641 hours (Pilot In Command, all aircraft), 69 hours (Last 90 days, all aircraft), 69 hours (Last 30 days, all aircraft)		

Page 3 of 6 LAX01LA159

## **Aircraft and Owner/Operator Information**

Aircraft Make:	Ryan	Registration:	N46503
Model/Series:	ST3KR	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	1290
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	February 1, 2001 Annual	Certified Max Gross Wt.:	1885 lbs
Time Since Last Inspection:	41 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2729 Hrs at time of accident	Engine Manufacturer:	Kinner
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	R-55
Registered Owner:	Thomas S. Valenzia	Rated Power:	160 Horsepower
Operator:		Operating Certificate(s) Held:	None

# Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Day
RIV,1538 ft msl	Distance from Accident Site:	20 Nautical Miles
11:56 Local	Direction from Accident Site:	150°
Clear	Visibility	40 miles
None	Visibility (RVR):	
4 knots /	Turbulence Type Forecast/Actual:	/
310°	Turbulence Severity Forecast/Actual:	/
30.21 inches Hg	Temperature/Dew Point:	17°C / 5°C
No Obscuration; No Precipitation		
Murrietta, CA (F70 )	Type of Flight Plan Filed:	None
	Type of Clearance:	None
	Type of Airspace:	Class G
	Visual (VMC) RIV,1538 ft msl 11:56 Local Clear None 4 knots / 310°  30.21 inches Hg No Obscuration; No Precipital	Visual (VMC)  RIV,1538 ft msl  Distance from Accident Site:  11:56 Local  Direction from Accident Site:  Clear  Visibility  None  Visibility (RVR):  4 knots /  Turbulence Type Forecast/Actual:  310°  Turbulence Severity Forecast/Actual:  30.21 inches Hg  Temperature/Dew Point:  No Obscuration; No Precipitation  Murrietta, CA (F70)  Type of Flight Plan Filed:  Type of Clearance:

Page 4 of 6 LAX01LA159

## **Airport Information**

Airport:	French Valley F70	Runway Surface Type:	Asphalt
Airport Elevation:	1347 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:		IFR Approach:	Unknown
Runway Length/Width:		VFR Approach/Landing:	Unknown

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Page 5 of 6 LAX01LA159

#### **Administrative Information**

Investigator In Charge (IIC):	Parker, Richard
Additional Participating Persons:	DANIEL S BAKER; FAA Flt Stnds Dist. Office; Riverside, CA
Original Publish Date:	November 28, 2001
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	The NTSB traveled to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=52175

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 LAX01LA159