



Aviation Investigation Final Report

Location:	Fort Worth, Texas	Accident Number:	FTW01LA122
Date & Time:	May 20, 2001, 14:15 Local	Registration:	N77241
Aircraft:	Cessna 140	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

the pilot reported that the tail-wheel equipped airplane ground looped after encountering a "sudden right crosswind gust" during the landing roll. The left wing contacted the runway, and the left main landing gear collapsed. The pilot reported the wind was from 220-240 degrees at 10-15 knots with gusts to 20 knots. The wind at the nearest weather observation facility (approximately 32 nautical miles northeast of the accident site) was reported from 200 degrees at 12 knots gusting to 18 knots.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the inadvertent ground loop during the landing roll. A contributing factor was the gusty crosswind.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (C) GROUND LOOP/SWERVE - INADVERTENT - PILOT IN COMMAND
2. (F) WEATHER CONDITION - CROSSWIND
3. (F) WEATHER CONDITION - GUSTS

Factual Information

On May 20, 2001, at 1415 central daylight time, a Cessna 140, single-engine tail-wheel equipped airplane, N77241, ground looped during landing on runway 17 at the Bourland Field Airport, near Fort Worth, Texas. The airplane, owned and operated by the pilot under 14 Code of Federal Regulations Part 91, sustained substantial damage. The private pilot and his passenger were not injured. Visual meteorological conditions prevailed for the personal flight, and a flight plan was not filed. The local flight departed Bourland Field approximately 1400.

The pilot reported to the FAA inspector, who responded to the accident site, that a "strong crosswind occurred from the right causing a venturi effect between two hangers adjacent to the runway." The pilot further reported that the "right wing lifted up, the airplane ground looped, and he could not correct for the ground loop."

On the Pilot/Operator Aircraft Accident Report (NTSB Form 6120.1/2), the pilot stated the wind was from 220-240 degrees at 10-15 knots with gusts to 20 knots. During the second landing, the airplane was rolling on the centerline of the runway when a "sudden right crosswind gust from the hangar area on the west side [of the runway] lifted the right wing into a ground loop." The left wing contacted the runway, the left main landing gear collapsed, and the airplane came to rest on the west edge of the runway.

The FAA inspector examined the airplane and found that the firewall and left wing sustained substantial damage. The left main landing gear was collapsed.

The wind at Fort Worth Meacham Airport (approximately 32 nautical miles northeast of the accident site) was reported from 200 degrees at 12 knots gusting to 18 knots.

Pilot Information

Certificate:	Private	Age:	55, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	May 9, 2000
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	June 8, 2000
Flight Time:	230 hours (Total, all aircraft), 45 hours (Total, this make and model), 177 hours (Pilot In Command, all aircraft), 5 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N77241
Model/Series:	140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	11703
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	January 16, 2001 Annual	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	5 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3200 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	C85-12F
Registered Owner:	Andrew C. Weatherly	Rated Power:	85 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	FTW,710 ft msl	Distance from Accident Site:	32 Nautical Miles
Observation Time:	14:53 Local	Direction from Accident Site:	220°
Lowest Cloud Condition:	Scattered / 15000 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	12 knots / 18 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	200°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.61 inches Hg	Temperature/Dew Point:	32°C / 19°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Fort Worth, TX (50F)	Type of Flight Plan Filed:	None
Destination:	Fort Worth, TX (50F)	Type of Clearance:	None
Departure Time:	14:00 Local	Type of Airspace:	Class E

Airport Information

Airport:	Bourland Field 50F	Runway Surface Type:	Asphalt
Airport Elevation:	870 ft msl	Runway Surface Condition:	Dry
Runway Used:	17	IFR Approach:	None
Runway Length/Width:	4092 ft / 60 ft	VFR Approach/Landing:	Stop and go;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	32.570835,-97.586944

Administrative Information

Investigator In Charge (IIC):	Roach, Joyce
Additional Participating Persons:	Frank Gentile; FAA Flight Standards District Office; Fort Worth, TX
Original Publish Date:	October 9, 2001
Last Revision Date:	
Investigation Class:	Class
Note:	The NTSB traveled to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=52294

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).