



# Aviation Investigation Final Report

---

<b>Location:</b>	PLATTSMOUTH, Nebraska	<b>Accident Number:</b>	CHI01LA184
<b>Date &amp; Time:</b>	June 21, 2001, 18:05 Local	<b>Registration:</b>	N5659V
<b>Aircraft:</b>	Piper PA-32R-300	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	2 Minor
<b>Flight Conducted Under:</b>	Part 91: General aviation - Instructional		

---

## Analysis

The student pilot was flying a practice NDB approach to runway 34. The instructor said they began descending during the procedure turn. They rolled out on the inbound heading of 354 degrees. The instructor pilot said, "I called Omaha approach and they approved a switch to Plattsmouth advisory." While he changed radio frequencies, the student pilot descended to the minimum descent altitude of 1,820 feet mean sea level. At 7 DME the instructor made the radio call to Plattsmouth advisory. The student pilot performed his pre-landing checklist at 5 DME. The gear came down, and the student pilot told the instructor pilot that he turned on the boost pump and switched tanks. The instructor pilot said he did not actually see him do this, but looked over and saw the fuel pump on and the fuel selector switched over to the left tank. The engine instruments all looked normal. At 1.8 DME, the instructor pilot said the manifold pressure and RPMs dropped, and the airplane nosed down. The instructor pilot pushed the control levers full forward and told the student pilot to run the emergency checklist. "...our speed was still only about 80 and it was obvious we were not going to make the runway. We picked up a little speed, but even best glide wouldn't get us to the runway - we were too low for that. The instructor pilot said he looked for the best possible landing site straight ahead between us and the runway. The instructor pilot moved the throttle up and down twice. He said that it seemed very loose. There was no response from the engine. The engine sounded like it was still running. The instructor pilot said they kept the flaps up so they could stretch the glide to clear a tree line. On the other side of the tree line they saw a fence with large fence posts in their path. "We both got on the controls and pulled us over the fence. On the other side the terrain angled up. We flared, the stall warning sounded, the mains hit the ground and then it seemed like the nose wheel hit hard." An examination of the airplane at the accident site revealed no anomalies. The engine was examined 8 days later and showed no anomalies.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the loss of engine power for undetermined reasons during the approach and the inadvertent stall that occurred during the forced landing. Factors relating to this accident were the low airspeed, the uphill terrain, and the fence.

### Findings

Occurrence #1: LOSS OF ENGINE POWER

Phase of Operation: APPROACH - FAF/OUTER MARKER TO THRESHOLD (IFR)

Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED

-----

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY DESCENT/LANDING

-----

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: EMERGENCY DESCENT/LANDING

Findings

2. (C) STALL/MUSH - INADVERTENT - PILOT IN COMMAND(CFI)

3. (F) OBJECT - FENCE

4. (F) AIRSPEED - LOW - PILOT IN COMMAND(CFI)

5. (F) TERRAIN CONDITION - UPHILL

## Factual Information

On June 21, 2001, at 1805 central daylight time, a Piper PA-32R-300, N5659V, operated by a commercial pilot, sustained substantial damage when during a practice instrument approach to runway 34 (4,100 feet by 100 feet, dry concrete) at the Plattsmouth Municipal Airport, Plattsmouth, Nebraska, the airplane impacted the terrain. Prior to the accident, the airplane's engine lost power. Visual meteorological conditions prevailed at the time of the accident. The instructional flight was being conducted under the provisions of 14 CFR Part 91. A military visual flight rules plan was on file. The instructor pilot and dual student on board both reported minor injuries. The cross-country flight originated at Offutt Air Force Base, Nebraska, at 1700, and was filed to terminate there.

In his written statement, the instructor pilot said that the student pilot was flying a practice non-directional beacon (NDB) approach to runway 34. "During the procedure turn we started descending ..." The instructor pilot said that the student pilot turned left to the inbound heading of 354 degrees. "I called Omaha approach and they approved a switch to Plattsmouth advisory." The instructor pilot said that while he changed radio frequencies, the student pilot descended to the minimum descent altitude (MDA) for the approach of 1,820 feet mean sea level. "At 7 DME (distance measuring equipment) I made the radio call to Plattsmouth advisory." The student pilot performed his pre-landing checklist at 5 DME. The gear came down, and the student pilot told the instructor pilot that he turned on the boost pump and switched tanks. The instructor pilot said, "I did not actually see him do this, but looked over and saw the fuel pump on and the fuel selector switched over to the left tank. The engine instruments all looked normal." The instructor pilot said there was another airplane waiting to takeoff on runway 34 that told them he would wait for them to land. "I responded that we were three miles out and making a full stop landing. We were a little slow at about 80 knots and just below MDA ..." The instructor pilot said that 1 mile out, he would tell the student pilot to remove his goggles and have him execute a go around. "At 1.8 DME, the manifold pressure and RPMs dropped, and the airplane nosed down." The instructor pilot said that he pushed the control levers full forward and told the student pilot to run the emergency checklist. "...our speed was still only about 80 and it was obvious we were not going to make the runway. We picked up a little speed, but even best glide wouldn't get us to the runway - we were too low for that. I looked for the best possible landing site straight ahead between us and the runway." The instructor pilot said that he moved the throttle up and down twice. He said that it seemed very loose. There was no response from the engine. The engine sounded like it was still running. The instructor pilot said they kept the flaps up so they could stretch the glide to clear a tree line. On the other side of the tree line they saw a fence with large fence posts in their path. "We both got on the controls and pulled us over the fence. On the other side the terrain angled up. We flared, the stall warning sounded, the mains hit the ground and then it seemed like the nose wheel hit hard."

A Federal Aviation Administration inspector examined the airplane at the accident site. The airplane was resting upright in a field approximately 1/2 mile south of the approach end to runway 34. The airplane's left wing was bent upward and aft at the fuselage attach bolts. The outer portion of the left wing's leading edge was bent inward. The right wing's leading edge near the wing tip was bent inward and down. The left side of the fuselage at the wing root was crushed upward and buckled outward. The bottom cowling and forward fuselage were crushed upward, bent left, and aft. The engine mounts and engine were bent left. Both of the propeller blades were bent slightly aft. The nose gear and left main landing gear were collapsed and broken aft. Flight control continuity was confirmed. The airplane's engine was retained for further examination.

The airplane's engine was examined at Omaha, Nebraska, on June 29, 2001. The engine was successfully run on a test stand and showed no anomalies.

### Pilot Information

<b>Certificate:</b>	Commercial; Flight instructor	<b>Age:</b>	67, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	Airplane multi-engine; Airplane single-engine; Instrument airplane	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 1 Valid Medical-w/ waivers/lim	<b>Last FAA Medical Exam:</b>	December 1, 2000
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	June 20, 2001
<b>Flight Time:</b>	1840 hours (Total, all aircraft), 31 hours (Total, this make and model), 1700 hours (Pilot In Command, all aircraft), 90 hours (Last 90 days, all aircraft), 30 hours (Last 30 days, all aircraft)		

### Student pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	31, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 None	<b>Last FAA Medical Exam:</b>	August 31, 2000
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	November 30, 2000
<b>Flight Time:</b>	156 hours (Total, all aircraft), 4 hours (Total, this make and model), 94 hours (Pilot In Command, all aircraft), 5 hours (Last 90 days, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Piper	<b>Registration:</b>	N5659V
<b>Model/Series:</b>	PA-32R-300	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	32R-7780354
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	6
<b>Date/Type of Last Inspection:</b>	February 28, 2001 Annual	<b>Certified Max Gross Wt.:</b>	3600 lbs
<b>Time Since Last Inspection:</b>	40 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	5050 Hrs at time of accident	<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	Installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	IO-540-K1G5D
<b>Registered Owner:</b>	OFFUTT AIR FORCE BASE AERO CLUB	<b>Rated Power:</b>	300 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	OFF,1048 ft msl	<b>Distance from Accident Site:</b>	12 Nautical Miles
<b>Observation Time:</b>	17:55 Local	<b>Direction from Accident Site:</b>	355°
<b>Lowest Cloud Condition:</b>	Scattered / 7000 ft AGL	<b>Visibility</b>	7 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	7 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	330°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.1 inches Hg	<b>Temperature/Dew Point:</b>	24°C / 10°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	OFFUTT AFB, NE (OFF )	<b>Type of Flight Plan Filed:</b>	Military VFR
<b>Destination:</b>	PLATTSMOUTH, NE (PMV )	<b>Type of Clearance:</b>	VFR
<b>Departure Time:</b>	17:00 Local	<b>Type of Airspace:</b>	Class D

## Airport Information

<b>Airport:</b>	PLATTSMOUTH MUNICIPAL AIRPORT PMV	<b>Runway Surface Type:</b>	Concrete
<b>Airport Elevation:</b>	1201 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	34	<b>IFR Approach:</b>	ADF/NDB;Practice
<b>Runway Length/Width:</b>	4100 ft / 100 ft	<b>VFR Approach/Landing:</b>	None

## Wreckage and Impact Information

<b>Crew Injuries:</b>	2 Minor	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 Minor	<b>Latitude, Longitude:</b>	41.000198,-95.890403(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Bowling, David
<b>Additional Participating Persons:</b>	EILEEN VAN LENT; FEDERAL AVIATION ADMINISTRATION; LINCOLN, NE
<b>Original Publish Date:</b>	October 23, 2001
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB traveled to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=52572">https://data.ntsb.gov/Docket?ProjectID=52572</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).