

Aviation Investigation Final Report

Location: Plymouth, Massachusetts Accident Number: NYC01LA165

Date & Time: July 3, 2001, 17:30 Local Registration: N3042M

Aircraft: Piper PA-12 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot attempted to start the airplane; however, the starter would not engage. He then exited the airplane and rotated the propeller. During the third rotation, the engine started, and the airplane began to roll forward. The airplane struck a parked, unoccupied aircraft before the pilot was able to shut down the engine. Examination of the airplane's magnetos, P-leads, and ignition switch did not revealed any abnormalities. The starter switch operated correctly; however, the starter motor gear would not thrust forward to engage the engine ring gear. The pilot stated he did not intend to start the airplane when he rotated the propeller, and in retrospect, he felt rushed and "probably forgot" to turn the magnetos to the "off" position, prior to exiting the airplane.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to ensure the magnetos were off prior to rotating the propeller, which resulted in an unintentional engine start and subsequent unmanned taxi.

Findings

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: STANDING - STARTING ENGINE(S)

- Findings
 1. (C) IGNITION SYSTEM, MAGNETO NOT DISENGAGED
 2. (C) PREFLIGHT PLANNING/PREPARATION INADEQUATE PILOT IN COMMAND

Page 2 of 6 NYC01LA165

Factual Information

On July 3, 2001, about 1730 eastern daylight time, a Piper PA-12, N3042M, was substantially damaged during an unmanned taxi after engine start at the Plymouth Municipal Airport, (PYM), Plymouth, Massachusetts. The certificated commercial pilot was not injured. Visual meteorological conditions prevailed and no flight plan had been filed for the flight destined for the Lawrence Municipal Airport (LWM), Lawrence, Massachusetts. The personal flight was conducted under 14 CFR Part 91.

According to the pilot, he attempted to start the airplane; however, the starter would not engage. He then exited the airplane and rotated the propeller. During the third rotation, the engine started and the un-chocked airplane began to roll forward.

The airplane struck a parked, unoccupied aircraft before the pilot was able to shut down the engine.

Examination of the airplane's magnetos, P-leads, and ignition switch by a Federal Aviation Administration inspector did not revealed any abnormalities. It was noted that the starter switch operated correctly; however, the starter motor gear would not thrust forward to engage the engine ring gear.

During a subsequent telephone interview, the pilot stated that he did not intend to start the airplane when he rotated the propeller, and in retrospect, he felt rushed and "probably forgot" to turn the magnetos to the "off" position, prior to exiting the airplane.

Pilot Information

Certificate:	Commercial	Age:	26,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	June 1, 2000
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	May 23, 2000
Flight Time:	1200 hours (Total, all aircraft), 600 hours (Total, this make and model), 150 hours (Last 90 days, all aircraft), 50 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Page 3 of 6 NYC01LA165

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N3042M
Model/Series:	PA-12	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	12-1734
Landing Gear Type:	Tailwheel	Seats:	3
Date/Type of Last Inspection:	May 17, 2001 Annual	Certified Max Gross Wt.:	1750 lbs
Time Since Last Inspection:	15 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2231 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	0-360
Registered Owner:	Aviad Corp.	Rated Power:	180 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PYM,149 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	17:52 Local	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	200°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.15 inches Hg	Temperature/Dew Point:	21°C / 10°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Plymouth, MA (PYM)	Type of Flight Plan Filed:	None
Destination:	LAWRENCE, MA (LWM)	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Page 4 of 6 NYC01LA165

Airport Information

Airport:	PLYMOUTH MUNI PYM	Runway Surface Type:	
Airport Elevation:	149 ft msl	Runway Surface Condition:	Unknown
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	41.908889,-70.728614

Page 5 of 6 NYC01LA165

Administrative Information

Investigator In Charge (IIC):	Schiada, Luke	
Additional Participating Persons:	Jack Keenan; Bedford, MA	
Original Publish Date:	November 4, 2002	
Last Revision Date:		
Investigation Class:	Class	
Note:	The NTSB traveled to the scene of this accident.	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=52622	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 NYC01LA165