



Aviation Investigation Final Report

Location: Lewistown, Montana Accident Number: SEA01LA124

Date & Time: July 1, 2001, 12:30 Local Registration: N3251Z

Aircraft: Piper PA-22 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that shortly after departure the airplane settled back on to the runway. The pilot attempted to maneuver the airplane back into the air; however, the airplane again began to settle back toward the runway and the pilot aborted the takeoff. He reported that when the aircraft touched down, it veered to the right. The pilot stated that when he applied brakes, the airplane "spun around" and the left main gear collapsed. The airplane came to rest in a wheat field adjacent the departure runway.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: Pilot's failure to maintain directional control of the aircraft while landing.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. AIRSPEED - NOT ATTAINED - PILOT IN COMMAND

2. STALL/MUSH

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING

Findings

3. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #3: GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings
4. LANDING GEAR - OVERLOAD

Page 2 of 6 SEA01LA124

Factual Information

On July 1, 2001, about 1230 Mountain daylight time, a tail wheel-equipped Piper PA-22, N3251Z, sustained substantial damage during an aborted takeoff from Lewistown Municipal Airport, Lewistown, Montana. The airplane is registered to the pilot and was being operated as a personal/pleasure flight under the provisions of Title 14, CFR Part 91, when the accident occurred. The private pilot, and the one passenger aboard the airplane were not injured. Visual meteorological conditions prevailed and no flight plan was filed for the cross-country flight.

The pilot submitted a written statement to the National Transportation Safety Board dated July 9, and reported that shortly after departure the airplane settled back on to the runway. The pilot attempted to maneuver the airplane back into the air; however, the airplane again began to settle back toward the runway and the pilot aborted the takeoff. He reported that when the aircraft touched down, it veered to the right of runway centerline. The pilot stated that when he applied brakes, the airplane "spun around" and the left main gear collapsed. The airplane came to rest in a wheat field adjacent to the departure runway.

Pilot Information

Certificate:	Private	Age:	49,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	August 14, 2000
Occupational Pilot:	No	Last Flight Review or Equivalent:	June 26, 2001
Flight Time:	325 hours (Total, all aircraft), 17 hours (Total, this make and model), 237 hours (Pilot In Command, all aircraft), 31 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft), 17 hours (Last 24 hours, all aircraft)		

Page 3 of 6 SEA01LA124

Aircraft and Owner/Operator Information

Piper	Registration:	N3251Z
PA-22	Aircraft Category:	Airplane
	Amateur Built:	
Normal	Serial Number:	22-7199
Tailwheel	Seats:	4
April 10, 2001 Annual	Certified Max Gross Wt.:	2000 lbs
	Engines:	1 Reciprocating
1981 Hrs	Engine Manufacturer:	Lycoming
Installed, not activated	Engine Model/Series:	0-320
Robert W. Garniss	Rated Power:	150 Horsepower
	Operating Certificate(s) Held:	None
	PA-22 Normal Tailwheel April 10, 2001 Annual 1981 Hrs Installed, not activated	PA-22 Aircraft Category: Amateur Built: Normal Serial Number: Tailwheel Seats: April 10, 2001 Annual Certified Max Gross Wt.: Engines: 1981 Hrs Engine Manufacturer: Installed, not activated Robert W. Garniss Rated Power: Operating Certificate(s)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	lwt,4167 ft msl	Distance from Accident Site:	
Observation Time:	11:54 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	0 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.07 inches Hg	Temperature/Dew Point:	23°C / 16°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	LEWISTOWN, MT (LWT)	Type of Flight Plan Filed:	None
Destination:	Lewistown, MT (LWT)	Type of Clearance:	VFR
Departure Time:	12:30 Local	Type of Airspace:	Class G

Page 4 of 6 SEA01LA124

Airport Information

Airport:	LEWISTOWN MUNI LWT	Runway Surface Type:	Asphalt
Airport Elevation:	4167 ft msl	Runway Surface Condition:	Dry
Runway Used:	25	IFR Approach:	None
Runway Length/Width:	6100 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	47.009952,-109.339187(est)

Page 5 of 6 SEA01LA124

Administrative Information

Investigator In Charge (IIC):	HOGENSON, DENNIS
Additional Participating Persons:	Leo V Wadekamper; FAA - FSDO; Helena, MT
Original Publish Date:	August 26, 2003
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	The NTSB traveled to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=52687

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 SEA01LA124