



# Aviation Investigation Final Report

---

<b>Location:</b>	Wall, South Dakota	<b>Accident Number:</b>	CHI01LA254
<b>Date &amp; Time:</b>	July 27, 2001, 17:30 Local	<b>Registration:</b>	N39971
<b>Aircraft:</b>	Taylorcraft BC12-D	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation		

---

## Analysis

The airplane sustained substantial damage during landing roll when it nosed over in a wheat field after attempting to land on a runway (3,500 feet by 60 feet), but impacted the terrain about 150 yards past the runway. The airplane nosed over in the soft, wet ground. The student solo pilot reported he planned on doing a "wheel landing" to the first 1/4 of the runway. He used an approach speed of 65 mph. He reported the airplane floated down the runway and when he saw the end of the runway coming up, he elected to do a "go around." He applied full power and the engine sounded normal. He reported the airplane "just would not climb," and that the airplane did not climb more than "16 feet off the ground." He reported, "The controls were not very effective when the right wing was up and then I crashed." The student pilot's total flight time was 38.6 hours, and all of it had been flown in the accident airplane. He reported he had used automobile gas in the airplane, although no Supplementary Type Certificate (STC) had been issued to the airplane for the use of auto gas. The pilot reported the engine was running smooth; it did not "cough" when full power was applied; and it did not have carburetor ice. The pilot reported the winds were calm and the temperature was 85 degrees F. The elevation at 6V4 is 2,810 feet. The density altitude was about 5,031 feet.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The student pilot failed to maintain a proper glidepath, failed to obtain proper climb rate, and executed the go-around improperly. Additional factors included the pilot's lack of experience, the crop, and the soft, wet ground.

### Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: LANDING

Findings

1. (C) PROPER GLIDEPATH - NOT OBTAINED/MAINTAINED - PILOT IN COMMAND
2. (C) GO-AROUND - IMPROPER - PILOT IN COMMAND
3. (C) CLIMB - NOT OBTAINED/MAINTAINED - PILOT IN COMMAND
4. (F) LACK OF TOTAL EXPERIENCE - PILOT IN COMMAND

-----

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING

-----

Occurrence #3: NOSE OVER

Phase of Operation: LANDING - ROLL

Findings

5. (F) TERRAIN CONDITION - SOFT
6. (F) TERRAIN CONDITION - WET
7. (F) TERRAIN CONDITION - CROP

## Factual Information

On July 27, 2001, at 1730 central daylight time, a Taylorcraft BC12-D, N39971, sustained substantial damage during landing roll when it nosed over in a wheat field. The 14 CFR Part 91 student solo flight had departed from a private airstrip located at the pilot's ranch at 1715 en route to the Wall Municipal Airport (6V4), Wall, South Dakota. The student pilot attempted to land on runway 12 (3,500 feet by 60 feet), but impacted the terrain about 150 yards past the runway. The airplane nosed over in the soft, wet ground. The student pilot was not injured. Visual meteorological conditions prevailed and no flight plan was filed.

The student pilot reported to a Federal Aviation Administration Operations Inspector that he planned on doing a "wheel landing" to the first 1/4 of the runway. He used an approach speed of 65 mph. He reported the airplane floated down the runway and when he saw the end of the runway coming up, he elected to do a "go around." He applied full power. He reported the engine sounded normal, although he did not look at the tachometer. He reported the airplane "just would not climb," and that the airplane did not climb more than "16 feet off the ground." He reported, "The controls were not very effective when the right wing was up and then I crashed."

The student pilot had purchased the airplane and started flying on June 1, 2001. The student pilot's total flight time was 38.6 hours, and all of it had been flown in the accident airplane. He reported he had used automobile gas in the airplane, although no Supplementary Type Certificate (STC) had been issued to the airplane for the use of auto gas.

The pilot reported the engine was running smooth; it did not "cough" when full power was applied; and it did not have carburetor ice.

The pilot reported the winds were calm and the temperature was 85 degrees F. The elevation at 6V4 is 2,810 feet. The density altitude was about 5,031 feet.

## Pilot Information

<b>Certificate:</b>	Student	<b>Age:</b>	48, Male
<b>Airplane Rating(s):</b>	None	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 Valid Medical-w/ waivers/lim	<b>Last FAA Medical Exam:</b>	July 9, 2001
<b>Occupational Pilot:</b>	UNK	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	39 hours (Total, all aircraft), 39 hours (Total, this make and model), 39 hours (Last 90 days, all aircraft), 39 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Taylorcraft	<b>Registration:</b>	N39971
<b>Model/Series:</b>	BC12-D	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	6630
<b>Landing Gear Type:</b>	Tailwheel	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	June 1, 2001 Annual	<b>Certified Max Gross Wt.:</b>	1200 lbs
<b>Time Since Last Inspection:</b>	39 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	1084 Hrs at time of accident	<b>Engine Manufacturer:</b>	Continental
<b>ELT:</b>	Installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	A65-8
<b>Registered Owner:</b>	James Nachtigall	<b>Rated Power:</b>	65 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	RAP,3202 ft msl	<b>Distance from Accident Site:</b>	28 Nautical Miles
<b>Observation Time:</b>	18:55 Local	<b>Direction from Accident Site:</b>	280°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	7 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	110°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.06 inches Hg	<b>Temperature/Dew Point:</b>	27°C / 11°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Owanka, SD	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Wall, SD (6V4 )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	17:15 UTC	<b>Type of Airspace:</b>	Class E

## Airport Information

<b>Airport:</b>	Wall Airport 6V4	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	3268 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	12	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	3500 ft / 60 ft	<b>VFR Approach/Landing:</b>	Full stop

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	43.990779,-102.23027(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Silliman, Jim
<b>Additional Participating Persons:</b>	Gary Soldwisch; FAA; Rapid City, SD
<b>Original Publish Date:</b>	October 24, 2002
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB traveled to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=52907">https://data.ntsb.gov/Docket?ProjectID=52907</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).