



# Aviation Investigation Final Report

<b>Location:</b>	Kemmerer, Wyoming	<b>Accident Number:</b>	DEN01LA156
<b>Date &amp; Time:</b>	September 5, 2001, 18:30 Local	<b>Registration:</b>	N57843
<b>Aircraft:</b>	Aerospatiale AS350BA	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Positioning		

## Analysis

The pilot was aerial taxiing the helicopter to a parking area at 10 knots and into a slight quartering headwind. There was some thunderstorm activity west of the airport, and the nearest recorded winds were from 260 degrees at 20 knots, with gusts to 36 knots. As he turned towards the tie down area, there was a strong gust of wind from the left. The helicopter yawed to the left and full right pedal had no effect on arresting the spin. The helicopter struck the ground and rolled over. The pilot had 4,000 total flight hours in helicopters, but had recently transitioned to this make and model helicopter and had 8 hours in type.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the loss of tail rotor effectiveness while air taxiing. Contributing factors were the high winds and gusts, and the pilot's limited experience in aircraft make/model.

## Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT  
Phase of Operation: TAXI - AERIAL

### Findings

1. (C) LOSS OF TAIL ROTOR EFFECTIVENESS - ENCOUNTERED - PILOT IN COMMAND
2. (F) LACK OF TOTAL EXPERIENCE IN TYPE OF AIRCRAFT - PILOT IN COMMAND
3. (F) WEATHER CONDITION - HIGH WIND
4. (F) WEATHER CONDITION - GUSTS

-----

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER  
Phase of Operation: DESCENT - UNCONTROLLED

## Factual Information

On September 5, 2001, at 1830 mountain daylight time, an Aerospatiale AS350BA, N57843, operated by Crew Concepts, Inc., of Boise, Idaho, was substantially damaged when it collided with terrain during aerial taxi at the Kemmerer Municipal Airport, Kemmerer, Wyoming. The commercial pilot, the sole occupant aboard, was not injured. Visual meteorological conditions prevailed, and no flight plan had been filed for the positioning flight being conducted under Title 14 CFR Part 91. The flight originated from Pocatello, Idaho, at an undetermined time.

In a telephone interview with the pilot, he said he was bringing the helicopter to Kemmerer for seismic survey support. He was aerial taxiing over the taxiway parallel to runway 16 when the helicopter started spinning. Opposite anti-torque pedal input had no effect in arresting the spin. The helicopter struck the ground, and rolled over on its side. The tail boom was severed and the main rotor system was torn from its mounts. Recorded winds at Evanston, Wyoming, located 52 miles southwest of Kemmerer, were from 260 degrees at 25 knots, gusting to 36 knots. The peak wind, recorded at 1929, was from 240 degrees at 47 knots.

Upon learning of the accident, the operator dispatched its investigator to the accident scene to conduct a company investigation. According to his report, the pilot said he was aerial taxiing at 10 knots into a slight quartering headwind. There was some thunderstorm activity west of the airport. As the pilot turned towards the tie down area, "a very strong gust of wind seemed to hit the aircraft on the left side." The helicopter yawed to the left and full right pedal had no effect on arresting the counterclockwise spin. The report stated that the pilot lost control "due to severe/weather conditions...The application of full right pedal to correct yaw with no effect precipitated the situation whereby the pilot lost tail rotor effectiveness once the counterclockwise spin began." The report noted that Eurocopter, the helicopter manufacturer, issued Service Letter 1518-67-01 in April 2001, that described three similar mishaps. The report concluded, "Pilots must ensure that the application of LEFT pedal inputs are very slight with immediate correction using right pedal. Additionally, pilots are not to apply LEFT pedal inputs while passing through 'translational lift.' This restriction is to preclude the possibility of 'tail rotor vortex ring state' which may result in a spin to the left from which recovery is not possible."

According to the operator, the pilot had 4,000 total flight hours in helicopters. He had recently transitioned to, and had 8 hours in, the AS350.

## Pilot Information

<b>Certificate:</b>	Commercial; Flight instructor	<b>Age:</b>	41, Male
<b>Airplane Rating(s):</b>	None	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Helicopter	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	Helicopter	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Valid Medical—no waivers/lim.	<b>Last FAA Medical Exam:</b>	March 26, 2001
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	August 1, 2001
<b>Flight Time:</b>	3900 hours (Total, all aircraft), 8 hours (Total, this make and model), 3600 hours (Pilot In Command, all aircraft), 45 hours (Last 90 days, all aircraft), 8 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Aerospatiale	<b>Registration:</b>	N57843
<b>Model/Series:</b>	AS350BA	<b>Aircraft Category:</b>	Helicopter
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	1430
<b>Landing Gear Type:</b>	Skid	<b>Seats:</b>	6
<b>Date/Type of Last Inspection:</b>		<b>Certified Max Gross Wt.:</b>	4630 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Turbo shaft
<b>Airframe Total Time:</b>		<b>Engine Manufacturer:</b>	Turbomeca
<b>ELT:</b>	Installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	Arriel 1B
<b>Registered Owner:</b>	Roberts Aircraft Co.	<b>Rated Power:</b>	529 Horsepower
<b>Operator:</b>	Crew Concepts, Inc.	<b>Operating Certificate(s) Held:</b>	On-demand air taxi (135)
<b>Operator Does Business As:</b>		<b>Operator Designator Code:</b>	FZOA

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	EVW,7163 ft msl	<b>Distance from Accident Site:</b>	52 Nautical Miles
<b>Observation Time:</b>	19:53 Local	<b>Direction from Accident Site:</b>	200°
<b>Lowest Cloud Condition:</b>		<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	Broken / 11000 ft AGL	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	25 knots / 36 knots	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	260°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30 inches Hg	<b>Temperature/Dew Point:</b>	18°C / 2°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Pocatello, ID (PIH )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Kemmerer, WY (EMM )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>		<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>	Kemmerer Municipal EMM	<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>	7282 ft msl	<b>Runway Surface Condition:</b>	Unknown
<b>Runway Used:</b>		<b>IFR Approach:</b>	Unknown
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Unknown

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	41.780555,-110.55027(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Scott, Arnold
<b>Additional Participating Persons:</b>	Michael J Maglione; FAA Flight Standards Field Office; Casper, WY
<b>Original Publish Date:</b>	February 20, 2002
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB traveled to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=53183">https://data.ntsb.gov/Docket?ProjectID=53183</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).