



# **Aviation Investigation Final Report**

Location:	Harrisonburg, Louisiana	Accident Number:	FTW01LA204
Date & Time:	September 6, 2001, 07:10 Local	Registration:	N2162J
Aircraft:	Cessna A188B	Aircraft Damage:	Destroyed
Defining Event:		Injuries:	1 Serious
Flight Conducted Under:	Part 91: General aviation - Positioning		

## Analysis

The agricultural airplane was making an approach to land at a private airstrip when according to the pilot, the control stick locking device (gust lock) fell into the lock position, jaming the control stick. The airplane was "very" low, its left wing struck the ground, and the airplane cart wheeled separating both wings. No structural or mechanical anomalies were observed during an examination of the airplane. According to the aircraft manufacturer, to engage the gust lock, the assembly is rotated by hand from under the instrument panel to a point above the aircraft control stick. The barrel portion of the lock is then lowered onto the control stick. During the examination of the airplane, the barrel portion of contact with the control lock could not be located and no evidence of contact with the control lock barrel was noted on the control stick.

# **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: loss of control during approach for an undetermined reason.

**Findings** 

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: APPROACH

#### Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: DESCENT - UNCONTROLLED

#### Findings

2. TERRAIN CONDITION - GROUND

### **Factual Information**

On September 6, 2001, approximately 0710 central daylight time, a Cessna A188B agricultural airplane, N2162J, was destroyed by terrain impact and fire near Harrisonburg, Louisiana. The airplane was registered to and operated by Mowata Flying Service, Inc., of Eunice, Louisiana. The commercial pilot, sole occupant of the airplane, was seriously injured. Visual meteorological conditions prevailed, and a flight plan was not filed for the 14 Code of Federal Regulations Part 91 positioning flight. The flight originated from Jonesville Airport, Jonesville, Louisiana, at 0700, and was en route to the Robbins Flying Service private airstrip located approximately 5 miles northeast of the Jonesville Airport.

According to the operator, the pilot reported that "while making an approach to land" at the Robbins Flying Service airstrip, "the control stick locking device [gust lock] fell in the lock position, causing the control stick to jam, he was very low, causing the aircraft to hit the ground" short of the airstrip.

The FAA inspector, who responded to the accident site, reported that the airplane impacted the ground on an easterly direction. The airplane's left wing struck the ground and the airplane cart wheeled separating both wings. The airplane's cockpit area was consumed by fire.

The airplane wreckage was transported to Windance Salvage, Ben Wheeler, Texas.

According to the aircraft manufacturer, the gust lock on this aircraft consists of a barrel that fits over the control column. The gust lock is attached to a horizontal support bar under the instrument panel. Two springs on the lock are designed to keep the lock under the instrument panel when the lock is not in use. To engage the gust lock, the assembly is rotated by hand from under the instrument panel to a point above the aircraft control stick. The barrel portion of the lock is then lowered onto the control stick.

An examination of the airframe and engine was conducted by representatives of Cessna Aircraft and Teledyne Continental Motors under the supervision of the FAA at Windance Salvage on September 20, 2001. The barrel portion of the control lock could not be located and no evidence of contact with the control lock barrel was noted on the control stick. The portion of the control lock that attaches to the horizontal support under the instrument panel was located. The springs designed to swing the lock out of the way were still present. The control stick had separated from the aircraft frame at its mounting point. No structural or mechanical anomalies were observed during the examination.

### **Pilot Information**

Certificate:	Commercial	Age:	47,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	August 28, 2000
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	August 1, 2001
Flight Time:	4614 hours (Total, all aircraft), 300 hours (Total, this make and model), 210 hours (Last 90 days, all aircraft), 45 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N2162J
Model/Series:	A188B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	18803399T
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	March 19, 2001 Annual	Certified Max Gross Wt.:	4200 lbs
Time Since Last Inspection:	90 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3769 Hrs	Engine Manufacturer:	Continental
ELT:	Not installed	Engine Model/Series:	IO-520-D
Registered Owner:	Mowata Flying Service, Inc.	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	KGOG
Airframe Total Time: ELT: Registered Owner: Operator:	3769 Hrs Not installed	Engine Manufacturer: Engine Model/Series: Rated Power: Operating Certificate(s) Held:	Continental IO-520-D 300 Horsepower

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	7 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	24°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Jonesboro, LA (F88 )	Type of Flight Plan Filed:	None
Destination:	Harrisonburg, LA (NONE)	Type of Clearance:	None
Departure Time:	07:00 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	Robbins Flying Service NONE	Runway Surface Type:	
Airport Elevation:		<b>Runway Surface Condition:</b>	Unknown
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop

# Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Destroyed
Passenger Injuries:		Aircraft Fire:	On-ground
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	31.759159,-91.80941(est)

### **Administrative Information**

Investigator In Charge (IIC):	Wigington, Douglas
Additional Participating Persons:	Walter S Goodland; FAA FSDO; Baton Rouge, LA
Original Publish Date:	May 21, 2002
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	The NTSB traveled to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=53407

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.