



Aviation Investigation Final Report

Location: Albuquerque, New Mexico Accident Number: FTW02LA011

Date & Time: October 6, 2001, 09:30 Local Registration: N9524U

Aircraft: Cameron 105 Aircraft Damage: Minor

Defining Event: 2 Serious, 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The balloon pilot was provided a detailed weather briefing prior to the flight which called for light and variable winds. Soon after departure, the winds increased from 4-6 knots to 6-8 knots, gusting to 15 knots. The pilot flew around waiting for winds to subside to no avail. The pilot was forced to land with the prevailing high winds when he started getting low on fuel.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: Ther pilot's delay to compensate for changing weather conditions in-flight. Contributing factors were the high winds and an inaccurate weather forcast.

Findings

Occurrence #1: HARD LANDING Phase of Operation: LANDING

Findings

- 1. (C) WEATHER EVALUATION NOT PERFORMED PILOT IN COMMAND
- 2. (F) WEATHER FORECAST INACCURATE OTHER PERSON
- 3. (F) WEATHER CONDITION HIGH WIND

Factual Information

On October 6, 2001, approximately 0930 mountain daylight time, a Cameron 105 hot-air balloon, N9524U, registered to and operated by the pilot, sustained minor damage during a hard landing while the pilot was attempting a high wind landing near Albuquerque, New Mexico. The private pilot was not injured while 2 of his passengers sustained serious injuries and one was uninjured. Visual meteorological conditions prevailed and a flight plan was not filed for the 14 Code of Federal Regulations Part 91 personal flight. The local flight originated from Albuquerque at 0800.

The pilot was provided a detailed weather briefing at 0615. The forecast for the remaining of the morning called for light and variable winds. Soon after departure, the winds increased from 4-6 knots to 6-8 knots, gusting to 15 knots. The pilot flew around waiting for winds to subside to no avail. The pilot was forced to land with the prevailing high winds when he started getting low on fuel.

During the high wind landing, two of the 3 passengers sustained serious injuries.

Pilot Information

Certificate:	Private	Age:	52,Male
Airplane Rating(s):	None	Seat Occupied:	Unknown
Other Aircraft Rating(s):	Balloon	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	None None	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	February 28, 2000
Flight Time:	214 hours (Total, all aircraft), 214 ho aircraft)	ours (Total, this make and model), 1 ho	ours (Last 24 hours, all

Page 2 of 5 FTW02LA011

Aircraft and Owner/Operator Information

Aircraft Make:	Cameron	Registration:	N9524U
Model/Series:	105	Aircraft Category:	Balloon
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	5611
Landing Gear Type:		Seats:	
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	0
Airframe Total Time:		Engine Manufacturer:	
ELT:	Not installed	Engine Model/Series:	
Registered Owner:	Donald L. Rose	Rated Power:	
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Conditions at Accident one.	visual (vivio)	Condition of Light.	Day
Observation Facility, Elevation:	ABQ,5355 ft msl	Distance from Accident Site:	
Observation Time:	10:23 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots / 15 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	310°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.28 inches Hg	Temperature/Dew Point:	13°C / 2°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Albuquerque, NM (ABQ)	Type of Flight Plan Filed:	None
Destination:	Albuquerque, NM (ABQ)	Type of Clearance:	Unknown
Departure Time:	08:00 Local	Type of Airspace:	Class G

Page 3 of 5 FTW02LA011

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Minor
Passenger Injuries:	2 Serious	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Serious, 1 None	Latitude, Longitude:	35.04,-106.609169

Page 4 of 5 FTW02LA011

Administrative Information

Investigator In Charge (IIC):	Lemishko, Alexander
Additional Participating Persons:	Pamara Bell; FAA; Albuqerque, NM
Original Publish Date:	April 29, 2003
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=53636

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 FTW02LA011