

Aviation Investigation Final Report

Location:	Strausburg, Virginia	Accident Number:	IAD02LA036
Date & Time:	March 10, 2002, 10:10 Local	Registration:	N3878A
Aircraft:	Schweizer SGS 1-26A	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 Minor
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The glider was towed to altitude by a tow plane, and once released, the pilot flew towards the northeast portion of a mountain ridge to take advantage of "booming ridge lift." As the glider approached the ridge, it encountered insufficient thermal lift to maintain altitude, and the pilot performed a forced landing to a field. The pilot flew a traffic pattern approach, and during the downwind leg, the glider continued to lose altitude. As the pilot made a right turn onto the base leg of the traffic pattern, the glider's right wing struck a tree and the glider impacted the ground in a 70-degree nose down attitude. The pilot received an "outlook" weather briefing about 24 hours before his flight, which forecasted the winds to be from 290 degrees at 20 knots, with higher gusts. He did not receive an additional weather briefing; however, his visual observation of two wind socks at the airport indicated the winds were in agreement with the forecast. Examination of the glider revealed no mechanical deficiencies.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate evaluation of weather resulted in a loss of thermal lift, which resulted in an impact with trees.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: EMERGENCY DESCENT/LANDING

- Findings 1. (C) WEATHER CONDITION NO THERMAL LIFT 2. (C) WEATHER EVALUATION INADEQUATE PILOT IN COMMAND 3. OBJECT TREE(S)

Factual Information

On March 10, 2002, at 1010 eastern standard time, a Schweizer SGS 1-26A glider, N3878A, was substantially damaged during a forced landing near Strausburg, Virginia. The certificated private pilot received minor injuries. Visual meteorological conditions prevailed for the flight which originated at the Front Royal Airport (FRR), Front Royal, Virginia, at 1000. No flight plan was filed for the local personal flight conducted under 14 CFR Part 91.

According to the pilot, the glider was towed to altitude, about 3,800 feet, and when it was released, he flew towards the northeast portion of the Massanutten Ridge to use the "booming ridge lift." As the glider approached the ridge, it began to lose altitude, and the pilot found there was "no useable lift." The pilot performed a forced landing to a field, which was oriented on a 300-degree heading. He flew a traffic pattern approach to the field and during the downwind leg, the glider continued to lose altitude. As the pilot made a right turn onto the base leg of the traffic pattern, the glider's right wing struck a tree and it impacted the ground in a 70-degree nose down attitude.

The pilot stated that he received an "outlook briefing" about 24 hours before his flight, which forecasted the winds to be from 290 degrees at 20 knots, with higher gusts. He did not receive an additional weather briefing; however, his visual observation of two wind socks at the airport indicated the winds were in agreement with the forecast.

The pilot reported about 90 hours of total flight experience, all of which were accumulated in gliders. He also stated there were no mechanical deficiencies with the glider.

The glider was examined by a Federal Aviation Administration (FAA) inspector. According to the inspector, substantial damage was noted to the nose of the glider.

The winds reported at Front Royal, about 7 miles to the southwest, at 1000, were from 280 degrees at 21 knots gusting to 27 knots.

Pilot Information

Certificate:	Private	Age:	41,Male
Airplane Rating(s):	None	Seat Occupied:	Front
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	December 10, 1999
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	November 29, 2001
Flight Time:	90 hours (Total, all aircraft), 40 hours (Total, this make and model), 66 hours (Pilot In Command, all aircraft), 4 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Schweizer	Registration:	N3878A
Model/Series:	SGS 1-26A	Aircraft Category:	Glider
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	38
Landing Gear Type:	Tailwheel; Skid	Seats:	1
Date/Type of Last Inspection:		Certified Max Gross Wt.:	800 lbs
Time Since Last Inspection:		Engines:	
Airframe Total Time:		Engine Manufacturer:	
ELT:	Not installed	Engine Model/Series:	
Registered Owner:	John Lewis	Rated Power:	
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	OKV,727 ft msl	Distance from Accident Site:	15 Nautical Miles
Observation Time:	10:00 Local	Direction from Accident Site:	30°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	21 knots / 27 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	280°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.15 inches Hg	Temperature/Dew Point:	4°C / -12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Front Royal, VA (FRR)	Type of Flight Plan Filed:	None
Destination:	(FRR)	Type of Clearance:	None
Departure Time:	10:00 Local	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	38.950832,-78.319999

Administrative Information

Investigator In Charge (IIC):	Andrews, Jill	
Additional Participating Persons:	Chris Monteleon; FAA/FSDO; Dulles, VA	
Original Publish Date:	May 13, 2003	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=54320	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.