



Aviation Investigation Final Report

Location:	Bessemer, Alabama	Accident Number:	MIA02LA070
Date & Time:	March 24, 2002, 17:25 Local	Registration:	N7490F
Aircraft:	Hughes 269C	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Instructional		

Analysis

At the successful completion of one practice straight-in autorotation to the grass area between the runway and taxiway, terminating with a power-on three foot hover, the CFI asked the student to repeat the same maneuver. On the second attempt, the student over controlled aft cyclic and caused a tail rotor strike before the CFI could recognize and counter the student's abrupt control input. The rotorcraft entered an uncontrolled right yaw until the landing skid caught the terrain, and rolled over on its right side. The student and CFI evacuated the rotorcraft out the left door, unhurt.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The failure of the flight instructor to adequately monitor the student's rotorcraft control, resulting in an abrupt cyclic input causing a tail rotor strike of the terrain while entering a hover, and the resulting rollover during an uncontrolled descent.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: HOVER - IN GROUND EFFECT

Findings

1. AIRCRAFT CONTROL - ABRUPT - DUAL STUDENT
2. (C) MONITORING - INADEQUATE - PILOT IN COMMAND(CFI)

3. (C) ROTOR SYSTEM, TAIL ROTOR BLADE - BLADE STRIKE

Occurrence #2: ROLL OVER

Phase of Operation: DESCENT - UNCONTROLLED

Factual Information

On March 24, 2002, about 1725 central standard time, a Hughes HU-269C, N7490F, registered to a private individual, operating as a Title 14 CFR Part 91 instructional flight, crashed on the Bessemer Airport, Bessemer, Alabama. Visual meteorological conditions prevailed and no flight plan was filed. The rotorcraft sustained substantial damage, and the flight instructor and student were not injured. The flight originated about 25 minutes before the accident.

According to the instructor, the student was practicing power off autorotations to a power on recovery, terminating in a 3-foot hover over a grassy area between runway 23 and the taxiway. On this particular autorotation, the student did not apply power to accomplish the recovery, and the CFI brought in the power to salvage the maneuver. The student applied abrupt back cyclic, and the tail rotor struck the ground, even though the CFI was riding the cyclic controls with the student. Following the tail rotor strike, the rotorcraft started spinning to the right, the right landing skid dug into the terrain, and the rotorcraft rolled over on its right side. There were no malfunctions of the rotorcraft or its components involved.

According to an FAA inspector, the student induced the tail rotor strike by over controlling the cyclic control in the aft direction. The responsibility for the maintenance of control rests with the CFI, who allowed the maneuver to progress to a point that possibly exceeded his ability to identify and safely recover.

Flight instructor Information

Certificate:	Commercial; Flight instructor	Age:	53, Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane; Helicopter	Second Pilot Present:	
Instructor Rating(s):	Airplane single-engine; Helicopter; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical--w/ waivers/lim	Last FAA Medical Exam:	May 29, 2001
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	January 5, 2002
Flight Time:	1858 hours (Total, all aircraft), 535 hours (Total, this make and model), 1778 hours (Pilot In Command, all aircraft), 26 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Student pilot Information

Certificate:	Student	Age:	24, Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	November 15, 2001
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	42 hours (Total, all aircraft), 41 hours (Total, this make and model), 12 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Hughes	Registration:	N7490F
Model/Series:	269C	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	570596
Landing Gear Type:	Skid	Seats:	3
Date/Type of Last Inspection:	February 23, 2002 Annual	Certified Max Gross Wt.:	2050 lbs
Time Since Last Inspection:	5.2 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	7602.4 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	HIO-360 D1A
Registered Owner:	John R. McDonald	Rated Power:	190 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:	RotorTech Aviation, Inc.	Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	EET,584 ft msl	Distance from Accident Site:	10 Nautical Miles
Observation Time:	17:53 Local	Direction from Accident Site:	145°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	170°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.01 inches Hg	Temperature/Dew Point:	20°C / 1°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Bessemer, AL (EKY)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:		Type of Airspace:	Class E

Airport Information

Airport:	Bessemer EKY	Runway Surface Type:	Asphalt
Airport Elevation:	700 ft msl	Runway Surface Condition:	Dry;Vegetation
Runway Used:	23	IFR Approach:	None
Runway Length/Width:	5700 ft / 100 ft	VFR Approach/Landing:	Simulated forced landing

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	33.312778,-86.926109

Administrative Information

Investigator In Charge (IIC):	Stone, Alan
Additional Participating Persons:	Edward Jezska; FSDO FAA; Birmingham, AL
Original Publish Date:	August 28, 2002
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=54388

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).