



Aviation Investigation Final Report

Location: Deer Park, Washington **Accident Number**: SEA02LA056

Date & Time: March 17, 2002, 15:45 Local Registration: N77301

Aircraft: Cessna 120 Aircraft Damage: Substantial

Defining Event: 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The private pilot reported that the airplane "bounced" (during a simulated crosswind landing) and directional control was lost. After the bounced landing, the airplane veered to the left (west), exited the runway and collided with a drainage ditch.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: Loss of directional control while landing. A drainage ditch was a factor.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING

Findings

1. (F) TERRAIN CONDITION - DITCH

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING

Occurrence #3: NOSE DOWN Phase of Operation: LANDING

Page 2 of 6 SEA02LA056

Factual Information

On March 17, 2002, approximately 1545 Pacific standard time, a Cessna 120 airplane, N77301, registered to Dewpoint Aviation LLC of Deer Park, Washington, and being operated by a private pilot on a 14 CFR 91 personal flight, was substantially damaged when the pilot lost directional control, went off the side of the runway and struck a ditch during landing practice on runway 34 at Deer Park, Washington. The pilot, who was the airplane's sole occupant, received minor injuries in the accident. Visual meteorological conditions with calm winds were reported at Deer Park at 1553, and no flight plan was filed for the flight.

The pilot reported that the airplane "bounced" (during a simulated crosswind landing) and directional control was lost. After the bounced landing, the airplane veered to the left (west), exited the runway and collided with a drainage ditch.

Pilot Information

Certificate:	Private	Age:	54,Female
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	December 5, 2001
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	June 11, 2001
Flight Time:	843 hours (Total, all aircraft), 13 hours (Total, this make and model), 618 hours (Pilot In Command, all aircraft), 6 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft)		

Page 3 of 6 SEA02LA056

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N77301
Model/Series:	120	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	11743
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	November 20, 2001 Annual	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	48 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1259 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	C85-12
Registered Owner:	Dewpoint Aviation	Rated Power:	85 Horsepower
Operator:	Penelope L. Lewis	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

9.00.00			
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	DEW,2210 ft msl	Distance from Accident Site:	
Observation Time:	15:53 Local	Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Overcast / 4400 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	0 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.96 inches Hg	Temperature/Dew Point:	1°C / -7°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Deer Park, WA (DEW)	Type of Flight Plan Filed:	None
Destination:	(DEW)	Type of Clearance:	None
Departure Time:	15:40 Local	Type of Airspace:	Class G

Page 4 of 6 SEA02LA056

Airport Information

Airport:	Deer Park DEW	Runway Surface Type:	Asphalt
Airport Elevation:	2207 ft msl	Runway Surface Condition:	Dry
Runway Used:	34	IFR Approach:	None
Runway Length/Width:	6100 ft / 75 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	47.966667,-117.426666

Page 5 of 6 SEA02LA056

Administrative Information

Investigator In Charge (IIC):	Nesemeier, Gregg	
Additional Participating Persons:	Julie D Lee; FAA - FSDO; Spokane , WA	
Original Publish Date:	May 1, 2003	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=54449	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 SEA02LA056