

Aviation Investigation Final Report

Location:	Chugiak, Alaska	Accident Number:	ANC02LA056
Date & Time:	June 21, 2002, 20:30 Local	Registration:	N9378H
Aircraft:	Cessna 185	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 Minor
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot of the accident airplane made a straight-in approach to the 1,000 feet long airstrip. The pilot said he thought his ground speed felt a little fast, and that he thought he might have landed with a tailwind. He said the airplane touched down about halfway down the runway. He said when the main wheels touched he applied the brakes, the wheels locked-up, and the airplane nosed over. The airplane came to rest upside down near the center of the airstrip. A postaccident inspection by the pilot's mechanic disclosed no anomalies with the brakes.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's excessive braking, which resulted in a noseover during landing. Factors associated with the accident were the pilot's improper touchdown point, and landing with a tailwind.

Findings

Occurrence #1: NOSE OVER Phase of Operation: LANDING - ROLL

Findings

1. (F) WEATHER CONDITION - TAILWIND

2. (C) BRAKES(NORMAL) - EXCESSIVE - PILOT IN COMMAND

3. (F) PROPER TOUCHDOWN POINT - NOT ATTAINED - PILOT IN COMMAND

Factual Information

On June 21, 2002, about 2030 Alaska daylight time, a Cessna 185 airplane, N9378H, sustained substantial damage when it nosed over during landing at Bold airstrip, about 18 miles east of Chugiak, Alaska. The airplane was being operated as a visual flight rules (VFR) personal flight under Title 14, CFR Part 91, when the accident occurred. The solo private pilot was not injured. Visual meteorological conditions prevailed, and no flight plan was filed. The flight originated at the Iliamnia airport, Iliamnia, Alaska, about 1900.

During a telephone conversation with the National Transportation Safety Board (NTSB) investigator-in-charge (IIC) on June 24, the pilot said he was making a landing toward the east on the 1,000 feet long runway at Bold airstrip when the accident occurred. He said on final approach he felt his airspeed, 80 to 90 knots, was a little too fast, and that he might have had a tailwind. He said the airplane touched down about halfway down the runway, and he immediately applied the brakes. He said the brakes locked-up, and the airplane nosed over. The airplane came to rest upside down near the center of the airstrip.

The airplane sustained damage to the wings, fuselage, and tail.

After the airplane was recovered from the accident site, the pilot related to the NTSB IIC during a telephone conversation that his mechanic did not find any evidence of a preaccident malfunction of the airplane's brake system.

Certificate:	Private	Age:	26,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	October 3, 2001
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	122 hours (Total, all aircraft), 37 hours (Total, this make and model), 39 hours (Pilot In Command, all aircraft), 55 hours (Last 90 days, all aircraft), 37 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Pilot Information

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N9378H
		-	
Model/Series:	185	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18503434
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	May 1, 2002 Annual	Certified Max Gross Wt.:	3350 lbs
Time Since Last Inspection:	50 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	5580 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	IO-520-D24B
Registered Owner:	William Scoular	Rated Power:	300 Horsepower
Operator:	William Scoular	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night
Observation Facility, Elevation:	PABV,96 ft msl	Distance from Accident Site:	15 Nautical Miles
Observation Time:	20:35 Local	Direction from Accident Site:	90°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Overcast / 5000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	250°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.93 inches Hg	Temperature/Dew Point:	14°C / 5°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	lliamna, AK (PAIL)	Type of Flight Plan Filed:	None
Destination:	Bold Airstrip, AK (A13)	Type of Clearance:	None
Departure Time:	19:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	Bold Airstrip A13	Runway Surface Type:	Gravel
Airport Elevation:	900 ft msl	Runway Surface Condition:	Dry;Rough
Runway Used:	14	IFR Approach:	None
Runway Length/Width:	1000 ft / 30 ft	VFR Approach/Landing:	Full stop;Straight-in

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	61.341388,-148.998886

Administrative Information

Investigator In Charge (IIC):	Lewis, Lawrence
Additional Participating Persons:	Chuck McGee; Federal Aviation Administration FSDO-03; Anchorage, AK
Original Publish Date:	January 16, 2003
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=55037

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.